

Mukuto Seed School - facility report

1. Identification

Facility	Mukuto Seed School
Named on the programme list	Mukuto Seed School
Type	School
Local government	Namisindwa District
Region / sub-region	Eastern / Bugisu
Date of visit	2026-09-01
Team members present	Kayongo Tonny, Lydia Nakiganda
Informant interviewed	None recorded
Supervisor	Kassim Luminsa
Supervisor's contact	+256 702 806116
Date of submission	

2. Entry

On 1 September the team reached Mukuto Seed School in Namisindwa. A hand-filled register naming MUKOTO SEED SECONDARY SCHOOL is on file together with 44 photographs. A signboard at the site reads BWAYO SEED SECONDARY SCHOOL PHASE 1. Nobody is named as having received the team.

3. Condition and status

The four things the exercise exists to establish. Only what was established on site appears here; the rest is marked as not reported, not guessed.

Dimension	What was established on site
Ownership	Not reported. The guide says ownership sits between the contractor and the district while the school is still under construction.
Functionality	Established on the hand-filled register for furniture, ICT and buildings. The guide says the school is still under the contractor's hands.
Usage / performance	Partly established. The guide says the project brought services nearer but notes steep terrain, land encroachment and the need for fencing.
Location	Recorded on the register and shown in photographs of classroom blocks, the ICT room, laboratory stools, staff quarters and latrines.

4. Supplied against found

The hand-filled register is the found side and nothing was counted on the day.

5. Engraving and identification

The register records some chairs engraved but not numbered; most furniture and ICT lines read not engraved.

6. Obsolete, unserviceable or for disposal

Ten school chairs and one table are recorded non-functional; nothing was named for disposal.

7. Operation and maintenance

The discussion guide was answered. The school is under construction, keeps no functionality records yet, and asks for fencing and non-uniform budgeting because of the terrain.

8. Queries

- Settle Mukuto against Mukoto on the register and Bwayo on the signboard.
- Nothing here was counted on the day.
- Confirm commissioning once the contractor hands the site over.
- Ownership was not established.