

SCHOOL INTERVIEW/DISCUSSION GUIDE

Name of school: MUKOTO SEED SECONDARY SCHOOL

1a	Does the Facility have a record of all assets provided under UgIFT. (Obtain a record and verify if it has the costs and numbers supplied)	No
1b	If Not ask how many were supplied and when.	
2	How does this facility Maintain (repair/service/replace) the assets provided under Ugift	

Is still under construction and is between the contractor and the distrib.

The school is still under the contractor hands.

3	Does the facility take regular record about functionality/ or breakdown of the assets provided? Nonfunctional/ working, and reasons for non-functionality.	No
---	---	----

- The school is still under construction.

4	How has the UgIFT support helped in service delivery in the area, any issues, challenges and any recommendations for better program implementation.	
---	---	--

*- Very good and it has brought services nearer to people.
Challenges*

- Geographical, terrain of the area is very challenging and it makes it very expensive.

- Land encroachment, neighbour have started encroaching on the school land.

PROCEED TO VERIFICATION AFTER THIS DISCUSSION

Recommendations

Budgeting should not be uniform because different areas have different geographical challenges.

- Fencing to protect the school land.

SCHOOL FURNITURE

(School Desks, Office chairs, Laboratory stools, Book shelves)

Name of LG: NAMKINDWA L.G.

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
231 School chairs	Edn	-	wooden with metallic stand		some are engraved but not numbered	
28 Book shelves	Edn	-	wooden with metallic approx book shelves		Not engraved.	
101 Books	Edn		metallic stand wooden		Not engraved	
51 School tables			wooden with metallic stands		Not engraved	
Lab. 173 stools			wooden with metallic stand		Not engraved	

NAME OF SCHOOL MUKOTO SEED SECONDARY SCHOOL

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
							231 chair but
						good	10 Non functional
						condition	but other are
							in good shape.
						good	28 functional
						condition	and in good
							shape.
						good	101 functional
						condition	and in good
							shape.
						good	51 table
						condition	1 Non functional
							also 50 functional
							counted physically
						good	
						condition	173 stools in-
							good shape and
							functional counted
							physically.

ICT ITEMS TO VERIFY

(Desktop Computer, Server Processor, Network Switch 24 Port, Multipurpose Printer, UPS, Projector, Air Conditioners, Server, CCTV Camera)

Name of LG.. NAMISINDIWA AINTRICI

Equipment/ Item	Department	Asset Number	Item Description	Life Months	In	Tag Number (engrave no.)	Date of Purchase
20 Desktop computers	Edn	-	HP Black inter. core i5	-		Not engraved	
1 projector	Edn	-					
projector	Edn	X885301142	white Epson with white remote	-		Not engraved	
19 UPS	Edn	model 850VA	Black colour power MAXIMA	-		Not engraved	
		capacity 850VA	150w				
1 Server	Edn	CIN & ISME26	power. Maxima	-		Not	
Processor		33277	3KYA Black			engraved	
CCTV 1 Camera	Edn	AKVISION K5969573	white with black Screen	-		Not engraved	
Server	Edn	CIN 4CEH3 8CD3B	Black hp			Not engraved	
Air conditional		-	white with gold inverter CHIA with the A/C processor			Not engraved	

The contractor that installed the camera took the UPS that was not functional so 19 functional seen physically.

Name of School.....MUKOTO SEEDS SECONDARY SCHOOL.....

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Value	Book Value	Ytd Depn	Equipment status	Remarks
							Good 19 10	monitor functional in the
							condition	Jet 1 is the
								Administration,
								cpu are 19 in the
								computer lab.
							good 19	functional
							condition	in the computer
								lab.
							19 good condition	19 functional in
								the computer lab
								1 not working.
							3	
							good	Not working because
							condition	they have not
								installed 16 jet.
							good	functional
							condition	in the computer
								lab.
							good	functional
							condition	in the lab.
							good	functional
							condition	in the Lab

BUILDINGS TO VERIFY

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG NAMWINDWA DISTRICT

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Non-Residential Building	Edn	-	- 3 classroom blocks of 2 classroom Each		Not engraved but some labelled	
Administration block			- H/M - Deputy - Staff room - Reception - Store luxury			
Library & ICT block	Edn		- Library - ICT lab		Not engraved but labelled	
Science lab block	Edn		- Physics Biology & Chemistry Lab gas cylinder shelther behind		Not engraved but labelled	
Multipurpose Hall	Edn	-	- made 3 compartment		Not engraved but labelled	
Pit latrine	Edn	-	- 1 pit latrine			
1 pit latrine staff	Edn		- 2 latrine for male & female		Not engraved but labelled	

Name of School.....MUKOTO JESU J SECONDARY SCH.....

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Depn	Equipment status	Remarks
						good	functional &
						condition	good condition
						good	functional & in
						condition	good w/o
						good	functional and
						condition	they are good
							shape.
						good	functional and
						condition	they are good
							shape.
						good	functional and
						condition	they are good
							shape.
						good	functional &
						condition	good shape

BUILDINGS TO VERIFY

(Non- Residential and Residential, Kitchen, Toilets
Pit latrine Water tanks, Fences etc.)

Name of LG... NAMUNINDWA DISTRICT

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
1 pit latrine block Boys			1st storey * 1 bathroom 1 disabled		Labelled	
1 pit latrine block girls	Edn	-	1st storey * 1 bathroom 1 disabled		Labelled	
Water tanks	Edn		1 for 10000 LTR 1 for 3000 LTR but not complete 1 for 5000 LTR		Labelled	
stone pitch			on the cell guard rail with concrete walk ways in the school compound.		-	
Residential building						
Staff quarters			2 block 2 units Each 2 bedroom 2 sitting room 2 store		Not engraved	
Kitchen			3 blocks 2 units Each		Not engraved	
pit latrine			3 blocks 2 storey 2 bathroom Each		Not engraved	
Water tanks			1 for 5000 LTR Not complete, and Non functional.			

Name of SCHOOL MUKOTO SEED SECONDARY SCHOOL

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						good	functional
						condition	and good use
						good	functional
						condition	and good use
						good	functional
						condition	but one is incomplete.
						good	functional and
						condition	good in shape and look unique.
						good	functional +
						condition	good shape
						good	functional +
						condition	good shape
						good	functional and
						condition	good shape