

VERIFICATION DETAILS

NAME OF THE REGION:	Eastern		
SUB-REGION:	Bukedi		
Name of Local Government	Tororo District		
VERIFIER PARTICULARS			
Full name	Tony Kayongo		
Contact/ email and Telephone	tkayongo1@gmail.com		
Supervisor/ Sub team leader	Kassim Sekaggwa / Wasswa Wilson		
Name			
Contact	0702806116 / 0783230321		
Date of submission	31/08/2026		

Recommendation:

- Fencing to enhance on security of the facility,
- Staff accommodation construction
- Table replacement because the one supplied were of poor quality.
- Deploy more staff to support in service delivery

4

- Ugipt
facility
- Service
- Quality
PROCEED TO VER
- Good
Challen

- Staff all
- Fencing o
- Issues
- Under st

HEALTH CENTRES
INFORMANT INTERVIEW/DISCUSSION GUIDE (INCHARGE OR RESPONSIBLE PERSON)

Name of Health Centre: Kamuli Health Center III

1a	Does the Facility have a record of all assets provided under UgIFT. (Obtain a record and verify if it has the costs and numbers supplied) <u>Yes</u>
1b	If Not ask how many were supplied and when.

2	How does this facility Maintain (repair/service/replace) the assets provided under Ugift
---	--

Ugift Asset are still in good shape except the tables
 However the facility has a vote under PITC for
 operation and maintenance.

3	Does the facility take regular record about functionality/ or breakdown of the assets provided?
---	---

Yes, they have an inventory Register for
 functionality of Assets.

4	How has the UgIFT support helped in service delivery in the area, any issues, challenges and any recommendations for better program implementation.
---	---

- Ugift is very good, the contractor repainted the facility after completion of the Maternity block.
- Service delivery improvement for the facility
- Quality Equipment

PROCEED TO VERIFICATION AFTER THIS DISCUSSION

- Good Working Conditions for Health Workers
- Challenges:

- Staff accommodation is a challenge
- Fencing of the facility because of security issues
- Under Staffing currently the facility has 11 out of 11 of full staff structure.

HEALTH CENTRE CHECKLIST

NAME OF LG

Gororo District

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
B.P. Machine, Digital	Health		IRANSER		Not	
03			SNI 2005 374251006234		Engraved	
B.P. Machine (Aneroid wall mounted)						
Not Received						
Autoclave 20 Liters., Duo Operated	Health	-	Stainless steel		Not Engraved	
02						
Bowl, Kick						
Not Received						
Bowl Stand						
Not Received						
Counting chamber Neubauer- Improved						
Not Received						
Cupboard Steel, Lockable						
Not Received						
Drip Stand			Health		Not Engraved	
9	Health					

NAME OF HEALTH FACILITY Kamuli HCIII

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						Good	All in use
						Condition	
							This wasn't delivered
						Good	one in use in Others
						Condition	maternity. 2 are in store
							Nothing was seen at the facility.
							It wasn't seen at the facility.
							Not seen during Verification Exercise
						Good	All in use
						Condition	

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date Of Purchase
ESR Stand						
Not Received						
Examination Couch	Health	-	Metallic with a mattress	-	Not Engraved	
03						
Examination light, LED						
Not Received						
Glucometer						
01	Health		White ONE touch		Not Engraved	
Haemoglobin Meter, Digital						
01	Health		Plus Med White with Red colours		Not Engraved	
Height Meter						
Not Delivered						
Instrument Trolley	Health					
02			Stainless with plastic bases		Not Engraved	
Microscope Binocular	Health					
01			White & Black		Not Engraved	
Otoscope	Health					
09						
Patient Screen	Health					
10						
Patient Trolley						
Not Received						

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
							Not seen at m
						1 in good condition	Tirey deliver poor quality
						2 broke down	
						Good condition	In use
						Good condition	In use.
						Good condition	One in use another in sh
						Good condition	In use.
						Good condition	All kept in
						Good condition	3 in use 7 in store
							Nothing was so facilities for veris

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date Of Purchase
Refrigerator, Basic	Health		Pionway		not	
02			medical lab		engraved	
Stethoscope						
06 pcs	Health		Black		Not	
			with plastic		engraved	
			tube & stainless			
Stop Watch			&			
Not Received						
Stretcher						
Not Received						
Stove, Gas	Health					
Not Received						
Weighing Scale with Height Meter, Adult	Health		White & black base			
03						
Weighing Scale, Infant	Health		Metallic		Not	
03			with a scale		engraved	
Weighing Scale, Toddler						
Not Received						
Wheel Chair	Health				Not engraved	
01					Not	
Audio Visual Equipment	Health				engraved	
01 TV, Starline	Health		32 inch		Not	
Medical Waste Bin			TV Screen		engraved	
17	Health		Plastic		Not	
			black		engraved	
			big size			
Wall Clock	Health		Aganta		Not	
08			Brand		engraved	

2 Maternity
2 OPB

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						One in use	01 in use
						USE	another in store
						Good	All in store
						Condition	01 per children
						Nothing was seen	during verification
						One at the facility	is not UGIFG.
						Good condition	2 in use
						Good	07 in store
						Condition	In use
						Good	In
						Condition	use.
						Good	In use.
						Condition	
						Good	10 in use, 07 in
						Condition	store,
						Good	All in use.
						Condition	

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date Of Purchase
Diagnostic Equipment Set for MCH	Health	-	Stainless			
02 sets			steel			
Diagnostic Equipment Set for OPD						
Glassware Set, Laboratory, Basic	Health					
Hollow Ware Set, Treatment						
Instrument Set, Dressing	Health	-	Stainless		Not-Engraved	
02 sets					Not	
Instrument Set, Basic ENT	Health		Black casing	-		
01 set-					Engraved	
Instrument Set, Suture	Health		Stainless			
04			steel			
Pulse Oximeter, Hand held						
02	Health	-				
Bed, Adult Patient with Mattress						
24	Health	-	Plastic with blue & white color with a mattress			
Bed, Pediatric Patient, With Mattress	Health	-	Stainless steel with a blue covered mattress		Not Engraved	

Mixed up

Not seen

[illegible]

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
11	Health		Stainless steel rods and blue Mattress		Not Engraved	
Bedside Locker	Health	-	Plastic		Not	
12			with wheels Blue and cream		Engraved	
Cupboard, Instrument						
Delivery Bed, Hydraulic Manual 191	Health	-	Off white metallic		Not Engraved	
Not Received						
Oxygen Therapy Apparatus, Minimum 45L cylinder	Health	-	Blue colour	-	Not Engraved	
Resuscitator Manual, Infant, with all Mask sizes						
Not seen						
Resuscitator Manual, Adult, with all mask sizes	Health	-	Plastic. Contains		Not	
04 sets			transparent		Engraved	
Suction Apparatus, (Electric)						
Not seen						
Nebulizer, Ultrasonic						
Not Received						
Oxygen Concentrator, Duo Flow						
Not Received						
Bench	Health					
0504						

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Depn	Equipment status	Remarks
						Good	All in
						Condition	use.
						Good	All in
						Condition	use.
						Good	In use
						Condition	
						Good	In use but they
						Condition	have never used.
						Good	All in
						Condition	Store.
						Not seen during	
						Verification	
						Not seen during	
						Verification	
						Good	2 Broken,
						Condition	2 in use
							Those in use have
							been sitting since

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Disinfection Buckets						
Not Received						
Baby Cot						
Not Received						
Diagnostic Equipment Set for Ward						
Hollow Ware Set, Ward						
Instrument Set, Delivery						
Instrument Set, Stitch Removing						
MVA Kit						
3 sets	Health	Transparent container			Not Engraved	
Stool, Laboratory						
Not delivered						

Mixed up and identifiable.

Five sets which are in store are mixed up in container

[illegible]

Equipment/ Item	Department	Asset Number	Item Description	Life In Months	Tag Number (engrave no.)	Date of Purchase
<i>Not Delivered</i>						
Penguin Sucker	<i>Health</i>	<i>-</i>	<i>Penguin</i>	<i>-</i>	<i>Not</i>	
<i>04</i>			<i>Shape</i>		<i>Engraved</i>	
Fetoscope, Dopplar						
<i>Not Received</i>						
Bubble CPAP						
<i>Not Received</i>						
Centrifuge (Electric)	<i>Health</i>		<i>Bowl</i>		<i>Not</i>	
<i>01</i>			<i>Shaped</i>		<i>Engraved</i>	
Kangaroo Mother Care Chair			<i>White & Blue</i>			
<i>Not Received</i>						
Radiant Infant Warmer						
<i>Not Received</i>						
Haemoglobin Meter, Sahli						
<i>Not Received</i>						
Delivery Bed	<i>Health</i>					
<i>03</i>						
Examination light						
<i>Not Received</i>						

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						3 in good condition	It was disposed off.
							Not seen during Verification
						Good & In use	Condition in Lab
							Not seen during Verification
							Not seen during Verification
							Not seen during Verification
						3 in use	Redistributed to Malabar Hill, not distributed
							Not seen during Verification

Equipment/ Item	Department	Asset Number	Item Description	Life In Months	Tag Number (engrave no.)	Date of Purchase
Instrument set, ENT Basic for HCIII	Health		Black	-	Not	
102 sets			Casing with		Engraved	
			Stainless		Not	
			Steel Instruments		Engraved	
Bag Valve mask (Ambu Bag), Neonatal						
01	Health	-	Blue Coloured		Not	
					Engraved	
Incubator						
Not Received						
Office Chair	Health	-	Black		Not	
15			with		Engraved	
			Plastic			
			hand			
			handles			
Desk / Tables	Health	-	Wood		Not	
05			brown		Engraved	
			soft wood			
			marble			

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Filing Cabinet			Grey with		Not	
02	Health		Lockers		Engraved	
Non Residential Buildings						
Maternity Block	Health		Cream &		Not	
Placenta Pit			Margen paint		Engraved	
Residential Buildings			Orange paint			
Not Received						

The Maternity Block has a 10,000 litre capacity water tank on ground and a 3000 litre capacity water tank on a kabit platform with a water pump.

Another tank of 5000 litre capacity is connected on water of with pipes from the roof.

Pit Latrine, has two stances for both males and females with two bathrooms.

Painted Orange and Cream/Yellowish paint.

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						Good	All in use
						Condition	
						Good	All in
						Condition	use.
						Not Staff accommodation at the facility.	