

VERIFICATION DETAILS

NAME OF THE REGION:	Eastern
SUB-REGION:	Bukedi
Name of Local Government	Tororo District
VERIFIER PARTICULARS	
Full name	Kayongo Tony
Contact/ email and Telephone	kayongo1@gmail.com 0783405610
Supervisor/ Sub team leader	
Name	Kassim Sekajja/Wasswa Wilson
Contact	0702806116 0783230321
Date of submission	29/08/2026

HEALTH INFORMANT INTERVIEW/DISCUSSION

Name of Health Centre: Namwa

1a	Does the Facility have a record of (Obtain a record and verify if it has)
1b	If Not ask how many were supplied

2	How does this facility Maintain () YES
---	--

All the items are still in
Report back to dis
to be repaired by
uses P.H.C.

3	Does the facility take regular provided?
---	---

Yes: However
they haven't

4	How has the UglFT support challenges and any recommen
---	--

There is value p
Quality and de
Improved servi
numbers visitin
Staff welfare ha
PROCEED TO VERIFICATION AFTER
Challenge
Insecurity since
Staffing level
Recor
Fencing of the

HEALTH CENTRES
INFORMANT INTERVIEW/DISCUSSION GUIDE (INCHARGE OR RESPONSIBLE PERSON)

Name of Health Centre: Namwaya Health Centre III

1a	Does the Facility have a record of all assets provided under UgIFT. (Obtain a record and verify if it has the costs and numbers supplied) <u>Yes</u>
1b	If Not ask how many were supplied and when.
2	How does this facility Maintain (repair/service/replace) the assets provided under Ugift <u>Yes</u>

All the items are still in good shape/condition.

Report back to district since they are very expensive to be repaired by the facility. Simple repairs, the facility uses PTC.

3	Does the facility take regular record about functionality/ or breakdown of the assets provided?
---	---

Yes: However, the Assets are still new and they haven't recorded any break down.

4	How has the UgIFT support helped in service delivery in the area, any issues, challenges and any recommendations for better program implementation.
---	---

There is value for money all equipments are of high Quality and durable.

Improved service delivery at the facility, the numbers visiting of the facility

Staff welfare has been improved, staff accommodation

PROCEED TO VERIFICATION AFTER THIS DISCUSSION

Challenges

Insecurity since the facility is not fenced.

Staffing levels are still Low.

Recommendations:

Fencing of the facility to enhance security

HEALTH CENTRE CHECKLIST

NAME OF LG Tororo District

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
B.P. Machine, Digital			Kept in			
01	Health		agrey container		Not- engraved	
B.P. Machine (Aneroid wall mounted)			Kept in			
03	Health		agrey container		Not- engraved	
Autoclave 20 Liters., Duo Operated			Stainless			
02	Health		Steel with Black lining		Not engraved	
Bowl, Kick			Stainless			
02	Health		Steel with		Not engraved	
Bowl Stand			Wheels			
03	Health					
Counting chamber Neubauer- Improved						
02						
Cupboard Steel, Lockable			Steel, Green			
04	Health		with door Lockable		Not- engraved	
Drip Stand			Stainless			
01	Health		Stand with Drip holder blue coloured			

NAME OF HEALTH FACILITY Namwaya HC III

Date Placed In Service	Cost	Recovery Cost-	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						Good condition	In use
						Good condition	One in use - 2 in store
						Good condition	One in use - Another in store
						Good condition	One in use
						Good condition	One in store
						Good condition	One in use another in store
						Good condition	2 in use
						Good condition	One in store
						Good condition	11
						Good condition	
						Good condition	All in use.
						Good condition	All in use

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date Of Purchase
ESR Stand	Health	-	White		Not	
01			Base with stainless stands		engraved	
Examination Couch						
04	Health	-	Metallic		Not	
			with black mattress		engraved	
Examination light, LED						
04						
Glucometer	Health	-	On call		Not	
03 + 1			plus		engraved	
4						
Haemoglobin Meter, Digital	Health	-	White		Not	
02 + 1			coloured		engraved	
Height Meter	Health	-	White in		Not	
02			colour		engraved	
Instrument Trolley	Health	-	Stainless		Not	
02			steel with wheels		engraved	
Microscope Binocular			to			
01	Health		Black		Not	
			with white base		engraved	
Otoscope	Health		Stainless			
01			Steel coloured			
Patient Screen			Blue			
1 in maternity	Health		Screen		Not	
04			sheet & white stands		engraved	
Patient Trolley	Health		Blue		Not	
02			mattress		engraved	

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						Good Condition	In use
						Good Condition	All in use
						Good Condition	One in use three in store
						Good Condition	Use One in use three are in store
						Good Condition	Two One in use One in store
							One in use another in store
						Good Condition	All in use, one in delivery room, another in AVE
						Good Condition	In use
						Good Condition	In use
						Good Condition	All in use
						Good Condition	All in use one in delivery

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date Of Purchase
Refrigerator, Basic	Health		Grey		Not	
01			Chigo Brand		Engraved	
Stethoscope						
04	Health		Black		Not	
			Card		Engraved	
Stop Watch	Health		White		Not	
02			with blue buttons		Engraved	
Stretcher						
01						
Not Received						
Stove, Gas	Health		Still in the			
02 01		-	box			
Weighing Scale with Height Meter, Adult	Health	-	White with		Not	
02			Screen		Engraved	
Weighing Scale, Infant	Health	-	Green &		Not	
04			White box		Engraved	
Weighing Scale, Toddler	Health	-	KIN LCC		Not	
02			FB 51-20		Engraved	
Wheel Chair	Health					
03						
Audio Visual Equipment	Health					
Not Received						
Medical Waste Bin	Health	-	Stainless		Not	
03			Steel		Engraved	
Wall Clock	Health	-	Quartz		Not	
05			White		Engraved	
			Coloured			

one
Given
to Jore
Hospital

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Depn	Equipment status	Remarks
						Good	1 in use
						Condition	
						Good	Two in use
						Condition	Two in store
						Good	All in store
						Condition	
						Good	1 in
						Condition	use
						Good	Received a Gas
						Condition	plate
						Good	Two in use
						Condition	one store
						Good	One in use, two
						Condition	in store, due to
						Good	One in use ^{to over temp}
						Condition	another in store
						Good	All in use
						Condition	
							Not Received
						Good	All in use
						Condition	
						Good	4 in use
						Condition	1 in store

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date Of Purchase
Diagnostic Equipment Set for MCH 02	Health		stainless steel case		Not Engraved	
Diagnostic Equipment Set for OPD	Health					
Glassware Set, Laboratory, Basic	Health					
Hollow Ware Set, Treatment	Health					
Instrument Set, Dressing 02	Health		Stainless Steel		Not Engraved	
Instrument Set, Basic ENT 02	Health		Kept in their cases		Not Engraved	
Instrument Set, Suture Not received						
Pulse Oximeter, Hand held 03	Health		Kept in a black case		Not Engraved	
Bed, Adult Patient with Mattress 10	Health		Metallic with a mattress black cover		Not Engraved	
Bed, Pediatric Patient, With Mattress 05	Health		Metallic covered with a mattress with a black cover		Not Engraved	

up: mixed
identifiable

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Depn	Equipment status	Remarks
						Good	One in use
						condition	One in store
						Not seen	} They are in use mixed up
						Not seen	
							They don't know it is stored
						Not seen	} They don't know where it is stored
						Good condition	In use
						Good	Not in use
						condition	
						Good	All in use
						condition	
						Good	All in
						condition	use
						Good	All in use
						condition	

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Not Received Bedside Locker	Health					
02						
Cupboard, Instrument	Health					
Not Received						
Delivery Bed, Hydraulic Manual	Health		1. Blue & another pink coloured		Not Engraved	
02						
Oxygen Therapy Apparatus, Minimum 45L cylinder						
Resuscitator Manual, Infant, with all Mask sizes	Health		Kept in		Not	
03			White plastic		Engraved	
Resuscitator Manual, Adult, with all mask sizes	Health		Containers		Not Engraved	
03						
Suction Apparatus, (Electric)	Health		Grey		Not	
01 01			& White coloured		Engraved	
Nebulizer, Ultrasonic	Health					
01						
Oxygen Concentrator, Duo Flow	Health		Grey & White coloured		Not Engraved	
02						
Bench	Health		Metallic		Not	
04			stands with wooden sitting bases		Engraved	

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
							Not Received
						Good	All in use, one
						Condition	piece and another blue
							Not Received
						Good	All in
						Condition	use
							Not Received
						Good	Two in use
						Condition	Some 4 in store
						Good	One in use
						Condition	two in store
						Good	
						Condition	One in use
							two in store
						Good	In use
						Good Condition	Not in use
						Good	In use in the
						Condition	delivery room
							one in store
						Good	All in use
						Condition	

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Disinfection Buckets	Health		Green Plastic		Not Engraved	
06						
Baby Cot	Health		Not Stainless Steel		Not Engraved	
02						
Diagnostic Equipment Set for Ward	Health		Stainless Steel		Not Engraved	
01						
Hollow Ware Set, Ward	Health		Stainless Steel		Not Engraved	
01						
Instrument Set, Delivery	Health		Stainless Steel		Not Engraved	
03						
Instrument Set, Stitch Removing	Health		Stainless Steel		Not Engraved	
01						
MVA Kit	Health		A set with a 519 syringe-like instrument		Not Engraved	
03						
Stool, Laboratory	Health		Blue & black Base		Not Engraved	

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						Good one ^{two} broken, of	
						Condition ⁴ in use	
						Good All in use	
						Condition in delivery room	
						Good In use	
						Condition at OPD	
						Good All in	
						Condition use	
						Good All in use	
						Condition	
						Good In use	
						Condition	
						Good All in use	
						Condition	
						In use	
						Good	
						Condition	

Date Placed In Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						Good	One grown ² Condition is <u>growing</u>
						Good	All in use
						Condition	
						Good	All in store
						Condition	purchased
						Good	Not in use
						Good	Fixed in wall
						Condition	
						Good	In use at
						Condition	delivery
						Good	
						Condition	
						Good	All in use
						Condition	
						The facility	Received
						Two delivery	beds
						Same make	
						The facility	Received only
						Red light	
						Leght	

Good ~~One given out to~~ ^{2 in store}
Candidate ~~to~~ anger a hospital

Good	All in use
Condition	

Good All in store
Condition perfect

Good	Not in use
------	------------

Good	Fixed in ward
Condition	

Good In use at
condition delivery

Good
condition

Good All in use
Condition

condition

The facility received
two delivery beds of the
same make

the facility
Receives only
led light
lights

Equipment/ Item	Department	Asset Number	Item Description	Life In Months	Tag Number (engrave no.)	Date of Purchase
Instrument set, ENT Basic for HCIII	Health		Packed in a		Not	
02			Black case		Engraved	
			Stainless			
			Instruments			
Bag Valve mask (Ambu Bag), Neonatal	Health		Not kept		Not	
03			in plastic		Engraved	
			containers			
Incubator						
Not Received						
Office Chair	Health		Black		Not	
6+1			Leather		Engraved	
07						
Desk	Health		Brown		Engraved	
04+2			varnish,			
05 07			natural			
			timber			

Equipment/ Item	Department	Asset Number	Item Description	Life in Months	Tag Number (engrave no.)	Date of Purchase
Filing Cabinet	Health		Cream		Not	
02			Colours		engraved	
			with lockers			
Non Residential Buildings						
Placenta Pit						
Pit latrine						
Residential Buildings						
One block of	Health		Painted		Not	
2 units of 2			Oranges		engraved	
bedrooms each			Cream			

Non Residential Buildings

Placenta Pit

Waste decomposition pit

Latrines 2 stances, 2 bathrooms for both Male and female

OPD, Maternity Block, With Wards, Waiting Area, mini store, ANC room and cleaning room. Fixed with Water Tanks of 10,000 litres on ground and others raised on tank stands with a pump.

Date Placed in Service	Cost	Recovery Cost	Acc Dep Cost	Net Book Value	Ytd Deprn	Equipment status	Remarks
						Good	All in use
						Condition	
						Good	OPS, Maternity,
						Condition	washing, ^{and} and and
						Good	All in use.
						Condition	