VisionAI Industrial Inspection Report

Id: 97db31a3465b4e9b8ff0124233392266

Status: FAIL

Summary: Hazelnut shell has a diagonal crack.

Alignment: Not requested

Elapsed: 22.864

Annotated inspection image



Detected regions (SAM mask area is not necessarily true defect area)

#	Type	Area (px)	Area (mm2)
1	Crack	5319	Not calibrated