



+2 Score

- No evidence of survey line



+1 Score

- Only wheel tracks are evident



0 Score

- Line has been rolled or walked
- No blade work
- Creek banks cut only where necessary
- Creeks are not blocked



-1 Score

- Windrows exist but are <0.5m high
- Extensive wheel ruts exist
- Creek banks 1-2m high cut and not restored
- Creeks are blocked by material <1m deep
- Offline wheel tracking evident



-2 Score

- Gibber mantle removed
- Creek banks >2m high cut and not restored
- Creeks blocked by material >1m deep
- Windrows are >0.5m high