



+2 Score

- No disturbance to vegetation



+1 Score

- No removal of vegetation



0 Score

- Creek crossings are doglegged
- Maximum of two trees 1-3m high have been unavoidably removed at creek crossings
- Less than 10% tree branches removed



-1 Score

- Vegetation has been removed unnecessarily
- Three or more trees 1-3m high have been removed at creek crossings



-2 Score

- Trees have been removed unnecessarily
- Two or more trees >3m high have been removed at creek crossings