

<div>TACOMA</div> <div>SUBARU</div> <div>Tacoma Subaru</div>	Customer Name:	JENNIFER HUYNH	Year:	2008
	ORDERS-LIS.date:	13/09/2025 04:32:39	Make:	LAND ROVER
	Repair Order #:	64292801	Model:	LR2
	Service Advisor:	Matthew Fulweller	VIN:	SALFT24N08H068596
	Technician:	Ryker Thompson	Mileage:	75645

Checked and Ok at this time

May Require Future Attention

Requires Immediate Attention

N/A

Requires Immediate Attention

Front Lights	<div></div> <div></div> <div></div>	Engine Oil Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>
<u>Notes:</u> d/s front marker out		<u>Notes:</u> oil leak above skid plate. recommend diag	
Brake Fluid Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>		
<u>Notes:</u> very dirty at minimum			

May Require Future Attention

Rear Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>
<u>Notes:</u> 4mm	

Full Inspection Results

Interior and Underhood Inspection

Instruments and Gauges/Warning Lights	<div></div> <div></div> <div></div> <div></div>	Seat Belt Inspection	<div></div> <div></div> <div></div> <div></div>
Heating & AC / Performance / Hoses / Lines	<div></div> <div></div> <div></div> <div></div>	Brake Pedal Operation	<div></div> <div></div> <div></div> <div></div>
Parking Brake Operation	<div></div> <div></div> <div></div> <div></div>	Electrical Inspection (Horns, Signals, Lights)	<div></div> <div></div> <div></div> <div></div>
Front Lights	<div></div> <div></div> <div></div>	Rear Lights	<div></div> <div></div> <div></div>
<u>Notes:</u> d/s front marker out			
Glass/Power Window Operation	<div></div> <div></div> <div></div> <div></div>	Mirror Operation-Side/Auto-Dimming	<div></div> <div></div> <div></div> <div></div>
Door Latches/Power Lock Operation	<div></div> <div></div> <div></div> <div></div>	Master Cylinder/Brake Lines	<div></div> <div></div> <div></div> <div></div>
Engine Air Filter	<div></div> <div></div> <div></div> <div></div>		

Radiator/Coolant System/Hoses

Windshield Wiper/Washer Operation	<div></div> <div></div> <div></div> <div></div>	Engine Oil Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>
		<u>Notes:</u> oil leak above skid plate. recommend diag	
Transmission Fluid Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>	Brake Fluid Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>
		<u>Notes:</u> very dirty at minimum	
Cabin Air Filter	<div></div> <div></div> <div></div> <div></div>	Accessory Drive Belts	<div></div> <div></div> <div></div> <div></div>

Brake Pad Wear/Rotor Condition

Front Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>	Rear Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>
-------------------------	---	------------------------	---

Notes: 8mm

Notes: 4mm

Exterior, Suspension and Drive Components

Socks/Struts and Suspension Components	<div></div>	<div></div>	<div></div>	<div></div>
Exhaust System (Leaks, Damage, Loose Parts)	<div></div>	<div></div>	<div></div>	<div></div>
Engine / Transmission Mounts	<div></div>	<div></div>	<div></div>	<div></div>
Front & Rear Differential Fluid Level & Condition	<div></div>	<div></div>	<div></div>	<div></div>

Steering System / Rack / Pump / Lines	<div></div>	<div></div>	<div></div>	<div></div>
Transmission / Linkages / Clutch (if equipped)	<div></div>	<div></div>	<div></div>	<div></div>
Axles & Boots	<div></div>	<div></div>	<div></div>	<div></div>

Battery Condition

Battery	<div></div>	<div></div>	<div></div>	<div></div>
---------	-------------	-------------	-------------	-------------

Terminals/Cables	<div></div>	<div></div>	<div></div>	<div></div>
------------------	-------------	-------------	-------------	-------------

Tire Wear Inspection

Front/Rear Tires	<div></div>	<div></div>	<div></div>	<div></div>
------------------	-------------	-------------	-------------	-------------

Notes: 7/32 x4

Spare Tire	<div></div>	<div></div>	<div></div>	<div></div>
------------	-------------	-------------	-------------	-------------