

<div>TACOMA</div> <div>SUBARU</div> <div>Tacoma Subaru</div>	Customer Name:	JENNIFER HUYNH	Year:	2017
	ORDERS-LIS.date:	06/09/2025 06:02:53	Make:	VOLKSWAGEN
	Repair Order #:	64292321	Model:	JETTA
	Service Advisor:	Matthew Fulweller	VIN:	3VWDB7AJ5HM312641
	Technician:	Carlos Aponte	Mileage:	88675

Checked and Ok at this time

May Require Future Attention

Requires Immediate Attention

N/A

Requires Immediate Attention

Engine Oil Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>	Rear Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>
Notes: oil leak present on bottom of engine, oil level low prior to service.		Notes: 2mm	

May Require Future Attention

Full Inspection Results

Interior and Underhood Inspection

Instruments and Gauges/Warning Lights	<div></div> <div></div> <div></div> <div></div>	Seat Belt Inspection	<div></div> <div></div> <div></div> <div></div>
Heating & AC / Performance / Hoses / Lines	<div></div> <div></div> <div></div> <div></div>	Brake Pedal Operation	<div></div> <div></div> <div></div> <div></div>
Parking Brake Operation	<div></div> <div></div> <div></div> <div></div>	Electrical Inspection (Horns, Signals, Lights)	<div></div> <div></div> <div></div> <div></div>
Front Lights	<div></div> <div></div> <div></div>	Rear Lights	<div></div> <div></div> <div></div>
Glass/Power Window Operation	<div></div> <div></div> <div></div> <div></div>	Mirror Operation-Side/Auto-Dimming	<div></div> <div></div> <div></div> <div></div>
Door Latches/Power Lock Operation	<div></div> <div></div> <div></div> <div></div>	Master Cylinder/Brake Lines	<div></div> <div></div> <div></div> <div></div>
Engine Air Filter	<div></div> <div></div> <div></div> <div></div>		

Radiator/Coolant System/Hoses

Windshield Wiper/Washer Operation	<div></div> <div></div> <div></div> <div></div>	Engine Oil Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>
		Notes: oil leak present on bottom of engine, oil level low prior to service.	
Transmission Fluid Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>	Brake Fluid Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>
Cabin Air Filter	<div></div> <div></div> <div></div> <div></div>	Accessory Drive Belts	<div></div> <div></div> <div></div> <div></div>

Brake Pad Wear/Rotor Condition

Front Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>	Rear Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>
Notes: 8mm		Notes: 2mm	

Exterior, Suspension and Drive Components



Socks/Struts and Suspension Components	<div><div></div><div></div><div></div><div></div></div>
Exhaust System (Leaks, Damage, Loose Parts)	<div><div></div><div></div><div></div><div></div></div>
Engine / Transmission Mounts	<div><div></div><div></div><div></div><div></div></div>
Front & Rear Differential Fluid Level & Condition	<div><div></div><div></div><div></div><div></div></div>

Steering System / Rack / Pump / Lines	<div><div></div><div></div><div></div><div></div></div>
Transmission / Linkages / Clutch (if equipped)	<div><div></div><div></div><div></div><div></div></div>
Axles & Boots	<div><div></div><div></div><div></div><div></div></div>

Battery Condition



Battery	<div><div></div><div></div><div></div><div></div></div>
---------	---

Terminals/Cables	<div><div></div><div></div><div></div><div></div></div>
------------------	---

Tire Wear Inspection



Front/Rear Tires	<div><div></div><div></div><div></div><div></div></div>
Notes: 8/32nds all around.	

Spare Tire	<div><div></div><div></div><div></div><div></div></div>
------------	---