

<div>TACOMA</div> <div>SUBARU</div> <div>Tacoma Subaru</div>	Customer Name:	JENNIFER HUYNH	Year:	2017
	ORDERS-LIS.date:	09/09/2025 04:32:06	Make:	FIAT
	Repair Order #:	64292476	Model:	500E
	Service Advisor:	Matthew Fulweller	VIN:	3C3CFFGE6HT586240
	Technician:	Zach Mchugh	Mileage:	66534

Checked and Ok at this time

May Require Future Attention

Requires Immediate Attention

N/A

Requires Immediate Attention

Front Lights	<div></div> <div></div> <div></div>	Rear Lights	<div></div> <div></div> <div></div>
<b>Notes:</b> both high and low beams out,driver side fog light out,and both lower fog lights out		<b>Notes:</b> driver side reverse lights	

May Require Future Attention

Windshield Wiper/Washer Operation	<div></div> <div></div> <div></div> <div></div>	Front Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>
<b>Notes:</b> windshield washer fluid leaks		<b>Notes:</b> 5mm	
Rear Brake Pads/Rotors	<div></div> <div></div> <div></div> <div></div>		
<b>Notes:</b> 6mm			

Full Inspection Results

Interior and Underhood Inspection

Instruments and Gauges/Warning Lights	<div></div> <div></div> <div></div> <div></div>	Seat Belt Inspection	<div></div> <div></div> <div></div> <div></div>
Heating & AC / Performance / Hoses / Lines	<div></div> <div></div> <div></div> <div></div>	Brake Pedal Operation	<div></div> <div></div> <div></div> <div></div>
Parking Brake Operation	<div></div> <div></div> <div></div> <div></div>	Electrical Inspection (Horns, Signals, Lights)	<div></div> <div></div> <div></div> <div></div>
Front Lights	<div></div> <div></div> <div></div>	Rear Lights	<div></div> <div></div> <div></div>
<b>Notes:</b> both high and low beams out,driver side fog light out,and both lower fog lights out		<b>Notes:</b> driver side reverse lights	
Glass/Power Window Operation	<div></div> <div></div> <div></div> <div></div>	Mirror Operation-Side/Auto-Dimming	<div></div> <div></div> <div></div> <div></div>
Door Latches/Power Lock Operation	<div></div> <div></div> <div></div> <div></div>	Master Cylinder/Brake Lines	<div></div> <div></div> <div></div> <div></div>
Engine Air Filter	<div></div> <div></div> <div></div> <div></div>		

Radiator/Coolant System/Hoses

Windshield Wiper/Washer Operation	<div></div> <div></div> <div></div> <div></div>	Engine Oil Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>
<b>Notes:</b> windshield washer fluid leaks		Brake Fluid Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>
Transmission Fluid Level & Condition/Leaks	<div></div> <div></div> <div></div> <div></div>	Accessory Drive Belts	<div></div> <div></div> <div></div> <div></div>
Cabin Air Filter	<div></div> <div></div> <div></div> <div></div>		

Brake Pad Wear/Rotor Condition

Front Brake Pads/Rotors

**Notes:** 5mm

Rear Brake Pads/Rotors

**Notes:** 6mm

Exterior, Suspension and Drive Components



Socks/Struts and Suspension Components

Exhaust System (Leaks, Damage, Loose Parts)

Engine / Transmission Mounts

Front & Rear Differential Fluid Level & Condition

Steering System / Rack / Pump / Lines

Transmission / Linkages / Clutch (if equipped)

Axles & Boots

Battery Condition



Battery

Terminals/Cables

Tire Wear Inspection



Front/Rear Tires

**Notes:** 7 all around

Spare Tire