

THIRD PARTY INSPECTION REPORT
FOR
CONSTRUCTION OF THIRD FLOOR
AT
SWARN JAYANTI HOSTEL BHAWAN

C.S.J.M. UNIVERSITY CAMPUS
KANPUR

Submitted to:

Executive Engineer U.P. R.N.S.S.
5/750 SECTOR-5 GOMTI NAGAR
LUCKNOW

Submitted By :

Dr. S. K. SINGH GAUR
B.E. (Civil I.I.T. Roorkee) M.E. PhD
DR. AMBEDKAR INSTITUTE OF TECHNOLOGY
FOR DIVYANGJAN AWADHPURI KANPUR



INTRODUCTION:

In reference with letter no.677/Anu. Prakh./ 2025-26 dated 22/11/2025 received from executive engineer U.P.R.N.S.S. (Maintenance Div.) Lucknow, a site visit was made on 24/11/2025 for third party quality inspection of **“Construction of third floor at Swarn Jayanti hostel bhawan”** at C.S.J.M. University campus Kanpur.

The site visit was carried out in presence of following officers/representatives :

- 1) Mr. Ajay Patel J.E. UPRNSS
- 2) Mr. Atul Bajpai A.E. UPRNSS
- 3) Mr. Mayank Mishra, Representative of M/S Ganesh Construction & Order Suppliers

This inspection report includes the visual inspection of **“Construction of third floor at Swarn Jayanti hostel (International Hostel) bhawan”** at C.S.J.M. University campus Kanpur.


SCOPE OF THIRD PARTY INSPECTION:


The third party inspection of aforesaid site included the progress quality assurance of work, observation of technical sanction and relevant drawings made available by UPRNSS.

OBSERVATIONS & FINDINGS:


During my site visit main focus was done on following points:




- Process and quality of rebar for columns.
- Construction of work as per approved plan and drawings.
- Proper use of structural steel as per approved drawings.


Dr. S. K. Singh Gaur
Deptt. of Civil / Architecture
A.I.T.D., Kanpur






Dr. S. K. Singh Gaur
Dept. of Civil / Architecture
A.I.T.D., Kanpur





vivo T4R

Dr. S. K. Singh Gaur
Deptt. of Civil / Architecture
A.I.T.D., Kanpur



[Handwritten signature]
K. Singh Gaur
Civil / Architect
I.D., Kanpur



- Test reports of different materials (Brick, Coarse sand, Cement, Steel & finished concrete.

Work under consideration includes:

- Construction and installation of lift from Ground floor to proposed third floor.
- Outer plaster work of existing Ground, First & Second floor.
- Part construction of second floor.
- Construction of third floor, mummy, terrace water tank & machine room work.
- Fire fighting arrangement.
- Furniture for hostel rooms, net working and split A.C. installation.
- Construction of Cement Concrete road


It was observed that the building under consideration is in construction stage. Lift foundation work is completed and RCC wall up to plinth level have been casted as per approved layout & structural drawings.

Part RCC construction of second floor has been completed with complete brick work and plaster work.

Total proposed covered area on all floors is approximately 2700 sqm.

Rebarring and casting of almost all columns of third floor up to floor beam bottoms have been completed.

Approximately 800 sqm. slab on third floor has been casted with almost same slab area ready for casting.


Dr. S. K. Singh Gaur
Deptt. of Civil / Architecture
A.I.T.D., Kanpur

Reinforcement used for columns was found to be as per approved structural drawings. Proper overlaps were found in longitudinal reinforcement of columns. Bar bending site was inspected for rebarring of structural members and it was found satisfactory. Construction agency was asked to produce the design mix report for proposed mix of concrete. It was informed by the contractor and UPRNSS that they are using ready mix concrete even then they were instructed to get an approved design mix report of concrete and testing report of major concrete castings along with other relevant material testing reports.

The building is constructed according to the proposed plans covering an area of 2700 sqm. for proposed extension work (approximately) with a total cost sanction of Rs. 981.42 lacs (Rs. Nine Crore Eighty One lacs & Forty Two Thousand only).

In the site visit visual observations were made and quality of work was found satisfactory.

CONCLUSION :

In reference with request letter issued by executive engineer UPRNSS Lucknow, a site visit was made on 22/11/2025 for third party inspection for **“Construction of third floor at Swarn Jayanti hostel (International Hostel) bhawan”** at C.S.J.M. University campus Kanpur. **The quality of civil work was found satisfactory as per my inspection.**


Dr. S. K. Singh Gaur
Deptt. of Civil / Architecture
A.I.T.D., Kanpur