

THIRD PARTY INSPECTION REPORT
FOR
CONSTRUCTION OF NEW BUILDING FOR
SCIENCE DEPARTMENT

AT
C.S.J.M. UNIVERSITY CAMPUS
KANPUR

Submitted to:
Executive Engineer U.P. R.N.S.S.
5/750 SECTOR-5 GOMTI NAGAR
LUCKNOW

Submitted By :
Dr. S. K. SINGH GAUR
B.E. (Civil I.I.T. Roorkee) M.E. PhD
DR. AMBEDKAR INSTITUTE OF TECHNOLOGY
FOR DIVYANGJAN AWADHPURI KANPUR

INTRODUCTION:

In reference with letter no.489-91/Maintenance Div./ 2025-26 dated 16/09/2025 received from executive engineer U.P.R.N.S. (Maintenance Div.) Lucknow, a site visit was made on 17/09/2021 for third party quality inspection of “**Construction new building for Science department** ” at C.S.J.M. University campus Kanpur.

The site visit was carried out in presence of following officers/representatives :

- 1) Mr. Ajay Patel J.E. UPRNSS
- 2) Mr. Atul Bajpai A.E. UPRNSS
- 3) Mr. Shikhar Bajpai , Representative of M/S Imagine

This inspection report includes the visual inspection of “**Construction new building for Science department**” at C.S.J.M. University campus Kanpur.


SCOPE OF THIRD PARTY INSPECTION:

The third party inspection of aforesaid site included the quality assurance of work, observation of technical sanction and relevant drawings made available by UPRNSS.


OSERVATIONS & FINDINGS:

During site visit, It was observed that the building under consideration is in construction stage. All footings have been casted as per approved layout drawings. All plinth beams have been casted with partial construction of dwarf walls where ever needed. Almost 50% columns have been casted up to lintel level with remaining columns ready for casting. Reinforcement used for columns was found to be as per approved structural drawings. Structural drawings and analysis presented by UPRNSS



Dr. S. K. Singh Gaur
Deptt. of Civil / Architecture
A.I.T.D., Kanpur




Dr. S. K. Singh Gaur
Deptt. of Civil / Architecture
A.I.T.D., Kanpur




Uttar Pradesh, Kanpur, Khyora
- 26.50094, 80.26622
17 Sept 2025 14:31:08



Uttar Pradesh, Kanpur, Khyora
26.50094, 80.26622
17 Sept 2025 14:30:14



Uttar Pradesh, Kanpur, Khyora
26.50094, 80.26622
17 Sept 2025 14:33:25



Uttar Pradesh, Kanpur, Khyora
26.50094, 80.26622
17 Sept 2025 14:31:18

Dr. S. Singh Gaur
Dept. of Civil / Architecture
A.I.T.D., Kanpur

indicated that these drawings have been prepared for G+3 floors, though only ground floor is under construction presently. Total covered area on ground floor is around 1675 Sqm. Proper overlaps were found in longitudinal reinforcement of columns though stirrups were not provided/ tied in uncasted columns. Bar bending site was inspected for rebaring of structural members and it was found satisfactory. Construction agency was asked to produce the design mix report for proposed mix of concrete. It was informed by the contractor and UPRNSS that they are using ready mix concrete even then they were instructed to get an approved design mix report of concrete and testing report of major concrete castings along with other relevant material testing reports.

The building is constructed according to the proposed plans covering an area of 1675 sq.m.(approximately) at ground floor with a total cost sanction of Rs. 591.98 lacs (Rs. Five Crore Ninety One lacs & Ninety Eight Thousand only). In the site visit visual observations were made and quality of work was found satisfactory.

CONCLUSION :

In reference with request letter issued by executive engineer UPRNSS Lucknow, a site visit was made on 16/09/2025 for third party inspection for “**Construction new building for Science department** ” at C.S.J.M. University campus Kanpur. The quality of civil work was found satisfactory as per my inspection.


Dr. S. K. Singh Gaur
Deptt. of Civil / Architecture
A.I.T.D., Kanpur