



भारतीय  
प्रौद्योगिकी  
संस्थान  
काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY  
BANARAS HINDU UNIVERSITY

## Department of Civil Engineering

Ref. No.: IIT(BHU)/CE/KrKP/25-26/UPRNSS/ Sports Stadium/Mirzapur Hostel/2nd Visit/02

Date: 17/11/2025

### Third Party Inspection Report on Construction of 60 Bedded Hostel in the Campus of Sports Stadium, Bhiskhuri, Mirzapur (UP)

#### A. General

|    |                                                      |                                                        |
|----|------------------------------------------------------|--------------------------------------------------------|
| 1  | Reference letter no.                                 | 592/Work-161/168, Dated: 14/08/2025                    |
| 2  | Date of Inspection                                   | 14 <sup>th</sup> September, 2025                       |
| 3  | Name of Construction Agency                          | UPRNSS Ltd., Mirzapur                                  |
| 4  | Name of Architect                                    | M/s Accurate & Associate, Haridwar                     |
| 5  | Name of Structural Consultant                        | M/s Vijay & Associate, Lucknow                         |
| 6  | Name of the officials present during site inspection | Er. Ranjeet Singh Rathore, AE, UPRNSS, Mirzapur        |
| 7  | % progress of work at the time of inspection         | 90 %                                                   |
| 8  | Type of work                                         | G+2, Framed structure                                  |
| 9  | Name of Contractor                                   | M/s Maa Vindhyaavashini Construction Company, Mirzapur |
| 10 | Foundation                                           | Raft                                                   |

#### B. List of the site elements

1. Hostel Building, Framed structure (G+2)
2. Overhead tank 50 kL
3. Rain water harvesting
4. CC road
5. Boundary wall
6. Boring and pump
7. Septic tank & Soakpit
8. Open surface drain
9. External sewerage work
10. Fire fighting work

*Krishna Kant*

Prof. K.K. PATHAK  
Department of Civil Engineering  
Indian Institute of Technology  
Banaras Hindu University  
Varanasi-221005



भारतीय  
प्रौद्योगिकी  
संस्थान  
काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY  
BANARAS HINDU UNIVERSITY

## Department of Civil Engineering

### C. Progress of the work

Following is the progress of work-

| Sr. No. | Elements                                | Progress                                                                                                                                                                                                                              | Remark                                                                                                                                             |
|---------|-----------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|
| 1       | Hostel Building, Framed structure (G+2) | Foundation completed, Structure work completed. Brick work completed, Plaster completed. One coat of painting completed. Door window frame fixing is completed. Door shutter fixing is in progress. Glass fixing work is in progress. | Overall quality of construction is found satisfactory.                                                                                             |
| 2       | Overhead tank 50 kL                     | Foundation work is completed. column casting work upto 5 <sup>th</sup> lift is in completed. Shuttering work for tank body is in progress.                                                                                            | Overall quality of construction is found satisfactory.                                                                                             |
| 3       | Rain water harvesting                   | 2 nos of Rain Water harvesting recharge pits have been constructed.                                                                                                                                                                   | Overall quality of construction is found satisfactory.                                                                                             |
| 4       | CC road                                 | 90 % work is completed as per the specification.                                                                                                                                                                                      | Overall quality of construction is found satisfactory.                                                                                             |
| 5       | Boundary wall                           | 100 % work is completed as per the specification.                                                                                                                                                                                     | Overall quality of construction is found satisfactory.                                                                                             |
| 6       | Boring and pump                         | Completed as per the specifications.                                                                                                                                                                                                  | Overall quality of work is found satisfactory.                                                                                                     |
| 7.      | Fire Fighting work                      | Work in progress                                                                                                                                                                                                                      | <i>Krishna Caw</i><br>Prof. K.K. PATHAK<br>Department of Civil Engineering<br>Indian Institute of Technology<br>Banaras Hindu University<br>221005 |
| 8.      | Open surface drain                      | Completed as per the specifications.                                                                                                                                                                                                  | Found satisfactory                                                                                                                                 |
| 9       | External sewerage work                  | Completed as per the specifications.                                                                                                                                                                                                  | Found satisfactory                                                                                                                                 |
| 10      | Septic tank &                           | Construction completed as per the                                                                                                                                                                                                     | Overall quality of work is                                                                                                                         |



भारतीय  
प्रौद्योगिकी  
संस्थान  
काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY  
BANARAS HINDU UNIVERSITY

## Department of Civil Engineering

|                  |                 |                     |
|------------------|-----------------|---------------------|
| Soak pit         | specifications. | found satisfactory. |
| Overall Progress | 90 %            |                     |

### D. Material used

|   |               |                               |
|---|---------------|-------------------------------|
| 1 | Concrete      | M20 (1:1.5:3) (Nominal Mix)   |
| 2 | Brick         | 150 class                     |
| 3 | Cement        | PPC- Prism & Ultratech cement |
| 4 | Reinforcement | Kamdhenu TMT Fe 500           |
| 5 | Sand          | Zone 2                        |

### E. Routine quality control

|   |                                   |                                                   |
|---|-----------------------------------|---------------------------------------------------|
| 1 | Material testing report           | MTC reports are available at site.                |
| 2 | Quality inspection                | Regular inspection by approved committee.         |
| 3 | Vetted design and drawing details | Approved drawings are available at site.          |
| 4 | Soil investigation report         | Soil investigation reports are available at site. |

### F. Quality statement

The overall quality of the 60 Bedded Hostel in the Campus of Sports Stadium, Bhiskhuri, Mirzapur, (U.P.) is found satisfactory.

### G. Recommendations

- ❖ Rough surfaces on wall and ceilings should be rectified.
- ❖ Unfilled tile joints should be completely grouted.
- ❖ Finishing quality should be regularly monitored.
- ❖ Weld joints in door and window frames should be completely filled.
- ❖ Edge protection of the outer drain at the front of hostel building may be considered.

*Krishna Pathak*

Prof. K.K. PATHAK  
Department of Civil Engineering  
Indian Institute of Technology  
Banaras Hindu University  
Varanasi-221005

Prof. K.K. Pathak  
Department of Civil Engineering  
Indian Institute of Technology (BHU)



भारतीय  
प्रौद्योगिकी  
संस्थान  
काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY  
BANARAS HINDU UNIVERSITY

## Department of Civil Engineering Site Photographs



*Krishna Caut*

Prof. K.K. PATHAK  
Department of Civil Engineering  
Indian Institute of Technology  
Banaras Hindu University  
Varanasi-221005



भारतीय  
प्रौद्योगिकी  
संस्थान  
काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY  
BANARAS HINDU UNIVERSITY

## Department of Civil Engineering



Latitude: 25.111516  
Longitude: 82.59092  
Elevation: 107.11±20.9 m  
Accuracy: 3.145 m  
Time: 09-14-2025 12:49  
Note: Sports hostel MIRZAPUR

Powered by NoteCam



Latitude: 25.111687  
Longitude: 82.591165  
Elevation: 103.31±9.39 m  
Accuracy: 14.6 m  
Time: 09-14-2025 12:46  
Note: Sports hostel MIRZAPUR

Powered by NoteCam

*KrishnaCwt*

Prof. K.K. PATHAK  
Department of Civil Engineering  
Indian Institute of Technology  
Banaras Hindu University  
Varanasi-221005



भारतीय  
प्रौद्योगिकी  
संस्थान  
काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY  
BANARAS HINDU UNIVERSITY

## Department of Civil Engineering



Latitude: 25.112343  
Longitude: 82.594138  
Elevation: 103.31±3.74 m  
Accuracy: 1900.0 m  
Time: 09-14-2025 12:46  
Note: Sports hostel MIRZAPUR

Powered by NoteCam




Time: 09-14-2025 12:46  
Note: Sports hostel MIRZAPUR

Powered by NoteCam

*KrishnaCOW*

Prof. K.K. PATHAK  
Department of Civil Engineering  
Indian Institute of Technology  
Banaras Hindu University  
Varanasi-221005



भारतीय  
प्रौद्योगिकी  
संस्थान

काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY

BANARAS HINDU UNIVERSITY

## Department of Civil Engineering



Latitude: 25.11155  
Longitude: 82.59097  
Elevation: 103.31±10.9 m  
Accuracy: 3.234 m  
Time: 09-14-2025 12:49  
Note: Sports hostel MIRZAPUR

Powered by NoteCam



Latitude: 25.111252  
Longitude: 82.590943  
Elevation: 117.31±15.0 m  
Accuracy: 3.0 m  
Time: 09-14-2025 12:54  
Note: Sports hostel MIRZAPUR

Powered by NoteCam

*KrishnaCwt*

Prof. K.K. PATHAK  
Department of Civil Engineering  
Indian Institute of Technology  
Banaras Hindu University  
Varanasi-221005




भारतीय  
प्रौद्योगिकी  
संस्थान  
काशी हिन्दू विश्वविद्यालय



INDIAN  
INSTITUTE OF  
TECHNOLOGY  
BANARAS HINDU UNIVERSITY

## Department of Civil Engineering



Latitude: 25.111155  
Longitude: 82.590972  
Elevation: 124.2±14.1 m  
Accuracy: 1.933 m  
Time: 09-14-2025 12:55  
Note: Sports hostel MIRZAPUR

Powered by NoteCam

*Krishna Caw*

Prof. K.K. PATHAK  
Department of Civil Engineering  
Indian Institute of Technology  
Banaras Hindu University  
Varanasi-221005