

Third Party Quality Inspection Report on Construction

of Auditorium Building in the Campus of Lal Bahadur Shastri
Homeopathic Medical College & Hospital Phaphamau, Prayagraj (UP)

A. General

1. Reference letter no.: 857/EE/NPP/F, Dated 15-02-2024
2. Date of Inspection: 22nd February, 2024
3. Name of Construction agency: UPRNSS, Prayagraj
4. Architect: Awadesh & Associates, Lucknow
5. Structure: BuildTech, Lucknow.
6. Name of the officials present during site inspection:
 - Shri Shailendra Kumar Verma, AE, UPRNSS Prayagraj
7. Type of Construction: Auditorium building
8. Type of Foundation: Isolated footing.
9. % progress of work at the time of inspection: 100. %

B. Routine quality control

1. **Material report:** Construction materials have been used as per the specification and found satisfactory.
2. **Design and drawing details:** Available at the site
3. **Other inspection:** Time to time inspection of the work has been carried out by different authorized teams and found it satisfactory

C. Material used

1. Cement: PPC, ACC & Ambuja
2. Steel: FE 500, Gallant
3. Brick: 1st Class, "ISI" and "SAI" marks
4. Mortar in Brickwork: 9" wall- 1:6
4" wall- 1:4
5. Mortar in plaster: 1:4

D. Observation on compliance of Quality control system

The project is complete. Following are the progress of construction in 3 units:

Kishna Chaw
Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banarasi Hindu University
Varanasi-221005

1. Auditorium Building

- a. Flooring – Complete
- b. Brickwork- Complete
- c. Door window fixing- Complete
- d. Putty- Complete
- e. Plastering- Complete
- f. Painting- Complete
- g. Brick coba- Complete
- h. Plumbing- Complete
- i. False ceiling: Complete
- j. Wall paneling: Complete
- k. Sound system work: Complete
- l. Curtain work: Complete

Construction is as per the design and specifications and found **Satisfactory**.

2. Staircase

Construction of staircase alongwith tile flooring is complete as per the specifications. The quality of construction is found to be **satisfactory**.

3. Toilet Area

Construction of toilets alongwith tile flooring is complete as per the specifications. Sanitary installation is complete. The quality of construction is found to be **satisfactory**.

4. Septic Tank and Soakpit

Construction is completed as per the design. The quality of construction is found to be **satisfactory**.

5. Electrical wiring

Electrical wiring work is completed as per the drawing and found **Satisfactory**.

6. Fire Fighting

Fire fighting work is completed as per the drawing and found **Satisfactory**.

7. Rain water harvesting

Rain water harvesting work is completed as per the drawing and found **Satisfactory**.

8. Airconditioning

Air conditioning work is completed as per the drawing and found **Satisfactory**

Proof Checked
Kishan Lal
Prof. K. K. PATHAK
Prof. K. K. Pathak, Head of Department
Bharat Institute of Technology
Bharat Institute of Technology
Bharat Institute of Technology
Bharat Institute of Technology

9. Boring

Boring is completed as per the norms.

E. Quality Statement:

- ❖ The overall quality of the construction of Auditorium Building in the Campus of Lal Bahadur Shastri Homeopathic Medical College & Hospital Phaphamau, Prayagraj (UP) is found satisfactory

F. Recommendations:

- ❖ Unfilled flooring and titling joints should be grouted.
- ❖ Weak paint areas should be properly painted.
- ❖ Campus should be properly cleaned before handover.
- ❖ Developmental works should be as per the specifications.
- ❖ Drain works should be ensured as per the specifications to drain storm water efficiently.

K.K. Pathak

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005

(Prof. K.K. Pathak)