

Vehicle Inspection Notes

CASE	Bowen v. Hyundai	DATE	Sep 25, 2026
VEHICLE		VIN	KMHD84LF5HU123456
LOCATION	Copart Houston	ENGINEERS	R. Chadwick
CLIENT		FILE NO.	

Case & Inspection

Case / Matter	Bowen v. Hyundai		
VI Date	Sep 25, 2026	VI Location	Copart Houston
VI Engineers	R. Chadwick		

Vehicle Information

VIN	KMHD84LF5HU123456		
Transmission	Automatic	Mileage (odometer)	48211
Optional Equipment	ABS, ESC		

Wheels & Tires

Left Front



Photo 1 — LF tire, tread wear

Brand	Hankook	Unseated	No
Tread Depth (/32")	Outside 7/32 · Middle 6/32 · Inside 6/32		



Photo 2

Front Suspension

Front Suspension — Left / Right

Lower Control Arm	Left bent, contact w/ tire	Right
Brake Type	Left Disc	Right

SRS / Airbags

SRS Warning Lamp (key on) On

Driver Frontal Airbag

Deployed Yes

Passenger Knee Airbag NOT APPLICABLE / NOT EVALUATED

Crash / Satellite Sensors

Sensors	Type	Location	Condition / Notes
	Front impact		
	Side pressure		

ADAS

Systems Equipped (per build / window sticker / observation) FCW, AEB

Front Radar

Mounting / Bracket Displaced — bracket bent rearward ~10mm

Photo Log

No.	Section / Item	Caption	Time
1	Wheels & Tires › Left Front	LF tire, tread wear	9/25/2026, 10:59:15 AM
2	Wheels & Tires › Tread Depth (/32")		9/25/2026, 10:59:16 AM

Engineer

Date