CITY OF CLEVELAND HEIGHTS

HOUSING INSPECTION DEPARTMENT

NOTICE OF CODE VIOLATION
[redacted]

PROPERTY INSPECTED:
[redacted]

TYPE OF STRUCTURE:
1-FAMILY PLATTED LOT

TYPE OF INSPECTION:
Rental Inspection

INSPECTION DA[redacted]

COMPLIANCE D[redacted]

[redacted]

Balance Due: $0.00

Garage - Exterior

14. **Properly remove. REMOVE DETERIORATING WINDOW UNIT AND SIDE OVER**
    Section: 1351.23, 1369.02
15. **Clean out gutter(s).**
    Section: 1351.25, 1369.04

Exterior - Yard

16. **Make drain fully operable. DRIVEWAY DRAIN**
    Section: 1351.13, 1369.08
17. **Cut tall grass/weeds & properly maintain landscaped areas..**
    Section: 1351.29, 1775.10

Basement - Main Room

1. **Replace missing pilot cover on hot water tank..**
   Section: 1351.13, 1369.08
2. **Properly install hot water tank flue pipe, maintaining a 1/4 inch per foot rise. CORRECT NEGATIVE PITCH**
   Section: 1351.18, 1369.10
3. **Make light fixture fully operable.**
   Section: 1351.20, 1369.09
4. **Properly install a smoke detector. This violation requires immediate compliance.**
   Section: 1351.211
5. **Properly install a CO detector outside of the sleeping area in the immediate vicinity of the bedrooms or within the bedroom where a fuel-burning appliance is located. Including one on every level where a fuel-burning appliance is located.**
   Section: 1103.09

Stairway to 1st Floor

6. **Make light fixture fully operable.**
   Section: 1351.20, 1369.09
7. **Properly replace. REPLACE CLOSER FOR SECURITY DOOR**
   Section: 1351.23, 1369.02

1st Floor - Kitchen

8. **Secure loose receptacle. RIGHT OF SINK**
   Section: 1351.20, 1369.09

1st Floor - Bedroom Hall

9. **Properly install a smoke detector. This violation requires immediate compliance.**
   Section: 1351.211

1st Floor - Bedroom