

Move Out Evaluation

Property: 628 Constant Drive	Tenant(s):	Date: 2022-09-15	Evaluator: Anna Cogdill
--	-------------------	----------------------------	-----------------------------------

Move-Out Conditions


S=Satisfactory

 Entry	 CONDITION	 ACTION	 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



2022-09-12 13:32:30

 [Image](#)



2022-09-12 13:33:45

 [Image](#)



📅 2022-09-12 13:33:47

 [Image](#)




📅 2022-09-12 13:33:48

 [Image](#)



📅 2022-09-12 13:33:55

 [Image](#)



📅 2022-09-12 13:34:00

 [Image](#)



📅 2022-09-12 13:34:01

 [Image](#)



📅 2022-09-12 13:34:03

 [Image](#)



📅 2022-09-12 13:34:04

 [Image](#)



📅 2022-09-12 13:34:07

 [Image](#)




📅 2022-09-12 13:34:09

 [Image](#)




📅 2022-09-12 13:34:16

 [Image](#)




📅 2022-09-12 13:34:23

 [Image](#)




📅 2022-09-12 13:34:26

 [Image](#)



📅 2022-09-12 13:34:27

 [Image](#)



📅 2022-09-12 13:34:31

 [Image](#)



📅 2022-09-12 13:34:33

 [Image](#)



📅 2022-09-12 13:34:36

 [Image](#)



📅 2022-09-12 13:34:42

 [Image](#)



📅 2022-09-12 13:34:46

 [Image](#)



2022-09-12 13:34:48

[Image](#)



2022-09-12 13:34:50

[Image](#)

Front Yard/Exterior	CONDITION	ACTION	COMMENTS
Building Exterior	- S - -	None	
Fence/Gate	- S - -	None	
Landscaping	- S - -	None	
Walk/Driveway	- S - -	None	



2022-09-12 13:24:53

[Image](#)



2022-09-12 13:24:55

[Image](#)



2022-09-12 13:25:04

[Image](#)



2022-09-12 13:25:06

[Image](#)



📅 2022-09-12 13:25:08

 [Image](#)



📅 2022-09-12 13:25:10

 [Image](#)



📅 2022-09-12 13:25:22

 [Image](#)



📅 2022-09-12 13:25:24

 [Image](#)



📅 2022-09-12 13:25:39

 [Image](#)



📅 2022-09-12 13:25:42

 [Image](#)



📅 2022-09-12 13:25:47

 [Image](#)



📅 2022-09-12 13:25:49

 [Image](#)



📅 2022-09-12 13:25:51

 [Image](#)



📅 2022-09-12 13:25:53

 [Image](#)



📅 2022-09-12 13:26:00

 [Image](#)



📅 2022-09-12 13:26:05

 [Image](#)



📅 2022-09-12 13:26:08

 [Image](#)



📅 2022-09-12 13:26:12

 [Image](#)



📅 2022-09-12 13:26:18

 [Image](#)



📅 2022-09-12 13:26:29

 [Image](#)



📅 2022-09-12 13:26:31

 [Image](#)



📅 2022-09-12 13:26:33

 [Image](#)



📅 2022-09-12 13:26:35

 [Image](#)



📅 2022-09-12 13:26:44

 [Image](#)



📅 2022-09-12 13:26:46

 [Image](#)



📅 2022-09-12 13:26:48

 [Image](#)



📅 2022-09-12 13:26:51

 [Image](#)



📅 2022-09-12 13:27:00

 [Image](#)



📅 2022-09-12 13:27:05

 [Image](#)



📅 2022-09-12 13:27:06

 [Image](#)



📅 2022-09-12 13:27:08

 [Image](#)



📅 2022-09-12 13:27:10

 [Image](#)



📅 2022-09-12 13:27:12

 [Image](#)



📅 2022-09-12 13:27:14

 [Image](#)



2022-09-12 13:27:18

[Image](#)



2022-09-12 13:27:20

[Image](#)



2022-09-12 13:29:19

[Image](#)



2022-09-12 13:29:21

[Image](#)



2022-09-12 13:29:22

[Image](#)



2022-09-12 13:29:32

[Image](#)



2022-09-12 13:29:34

[Image](#)



2022-09-12 13:29:35

[Image](#)



2022-09-12 13:29:41

[Image](#)



2022-09-12 13:29:42

[Image](#)



2022-09-12 13:29:43

[Image](#)




2022-09-12 13:29:45

[Image](#)



2022-09-12 13:29:47

[Image](#)



2022-09-12 13:29:52

[Image](#)



2022-09-12 13:29:53

[Image](#)



2022-09-12 13:29:55

[Image](#)



2022-09-12 13:30:02

[Image](#)




2022-09-12 13:30:05

[Image](#)



2022-09-12 13:30:49

[Image](#)



2022-09-12 13:30:51

[Image](#)



2022-09-12 13:30:53

[Image](#)



2022-09-12 13:32:02

[Image](#)



2022-09-12 13:32:04

[Image](#)



2022-09-12 13:32:07

[Image](#)



2022-09-12 13:32:14

[Image](#)

Bathroom: End hall	CONDITION	ACTION	COMMENTS
Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	




2022-09-12 14:07:38

[Image](#)



2022-09-12 14:07:40

[Image](#)



2022-09-12 14:07:41

[Image](#)



2022-09-12 14:07:45

[Image](#)



📅 2022-09-12 14:07:46

 [Image](#)



📅 2022-09-12 14:07:48

 [Image](#)



📅 2022-09-12 14:07:50

 [Image](#)




📅 2022-09-12 14:07:52

 [Image](#)



📅 2022-09-12 14:07:54

 [Image](#)



📅 2022-09-12 14:07:59

 [Image](#)



2022-09-12 14:08:02

[Image](#)



2022-09-12 14:08:05

[Image](#)



2022-09-12 14:08:08

[Image](#)



2022-09-12 14:08:09

[Image](#)



2022-09-12 14:08:13

[Image](#)



2022-09-12 14:08:16

[Image](#)



2022-09-12 14:08:18

[Image](#)



2022-09-12 14:08:20

[Image](#)



2022-09-12 14:08:22

[Image](#)



2022-09-12 14:08:23

[Image](#)



2022-09-12 14:08:27

[Image](#)




2022-09-12 14:08:29

[Image](#)



2022-09-12 14:08:31

[Image](#)



2022-09-12 14:08:34

[Image](#)



2022-09-12 14:08:35

[Image](#)



2022-09-12 14:08:37

[Image](#)



2022-09-12 14:08:39

[Image](#)



2022-09-12 14:08:41

[Image](#)

Bathroom 2: Secondary




CONDITION

ACTION

COMMENTS

Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	



📅 2022-09-12 13:51:22

 [Image](#)



📅 2022-09-12 13:51:24

 [Image](#)



📅 2022-09-12 13:51:26

 [Image](#)




📅 2022-09-12 13:51:31

 [Image](#)



📅 2022-09-12 13:51:32

 [Image](#)



📅 2022-09-12 13:51:34

 [Image](#)



2022-09-12 13:52:18

[Image](#)



2022-09-12 13:52:20

[Image](#)



2022-09-12 13:52:23

[Image](#)




2022-09-12 13:52:25

[Image](#)



2022-09-12 13:52:32

[Image](#)



2022-09-12 13:52:35

[Image](#)



2022-09-12 13:52:37

[Image](#)



2022-09-12 13:52:39

[Image](#)



2022-09-12 13:52:41

[Image](#)



2022-09-12 13:52:43

[Image](#)



2022-09-12 13:52:46

[Image](#)



2022-09-12 13:52:48

[Image](#)



📅 2022-09-12 13:54:47

 [Image](#)



📅 2022-09-12 13:54:50

 [Image](#)



📅 2022-09-12 13:54:56

 [Image](#)



📅 2022-09-12 13:54:58

 [Image](#)



📅 2022-09-12 13:54:59

 [Image](#)



📅 2022-09-12 13:55:01

 [Image](#)



📅 2022-09-12 13:55:04

 [Image](#)



📅 2022-09-12 13:55:06

 [Image](#)



📅 2022-09-12 13:55:08

 [Image](#)

 Bedroom: Hall right	 CONDITION	 ACTION	 COMMENTS
Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



📅 2022-09-12 14:04:47

 [Image](#)



📅 2022-09-12 14:04:48

 [Image](#)



📅 2022-09-12 14:04:49

 [Image](#)



📅 2022-09-12 14:04:55

 [Image](#)



📅 2022-09-12 14:04:57

 [Image](#)



📅 2022-09-12 14:04:58

 [Image](#)



📅 2022-09-12 14:05:02

 [Image](#)



📅 2022-09-12 14:05:03

 [Image](#)



📅 2022-09-12 14:05:04

 [Image](#)



📅 2022-09-12 14:05:08

 [Image](#)



📅 2022-09-12 14:05:09

 [Image](#)



📅 2022-09-12 14:05:10

 [Image](#)



📅 2022-09-12 14:05:15

 [Image](#)



📅 2022-09-12 14:05:17

 [Image](#)




2022-09-12 14:05:24

[Image](#)



2022-09-12 14:05:26

[Image](#)



2022-09-12 14:05:29

[Image](#)



2022-09-12 14:05:31

[Image](#)

📖 Bedroom 2: End hall	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



2022-09-12 14:05:52

[Image](#)



2022-09-12 14:05:54

[Image](#)



2022-09-12 14:05:55

[Image](#)



2022-09-12 14:06:02

[Image](#)



2022-09-12 14:06:03

[Image](#)



2022-09-12 14:06:05

[Image](#)



2022-09-12 14:06:12

[Image](#)



2022-09-12 14:06:16

[Image](#)



📅 2022-09-12 14:06:18

[Image](#)



📅 2022-09-12 14:06:20

[Image](#)



📅 2022-09-12 14:06:23


[Image](#)



📅 2022-09-12 14:06:25


[Image](#)

Bedroom 3: Hall left	CONDITION	ACTION	COMMENTS
Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



📅 2022-09-12 14:06:54

[Image](#)




📅 2022-09-12 14:06:56

[Image](#)



📅 2022-09-12 14:06:57

 [Image](#)



📅 2022-09-12 14:07:01

 [Image](#)




📅 2022-09-12 14:07:02

 [Image](#)



📅 2022-09-12 14:07:03

 [Image](#)



📅 2022-09-12 14:07:09

 [Image](#)




📅 2022-09-12 14:07:10

 [Image](#)



📅 2022-09-12 14:07:11

 [Image](#)



📅 2022-09-12 14:07:16

 [Image](#)



📅 2022-09-12 14:07:17

 [Image](#)



📅 2022-09-12 14:07:18

 [Image](#)



📅 2022-09-12 14:07:20

 [Image](#)



📅 2022-09-12 14:07:21

 [Image](#)



2022-09-12 14:07:24

[Image](#)



2022-09-12 14:07:25

[Image](#)



2022-09-12 14:07:26

[Image](#)



2022-09-12 14:07:28

[Image](#)

Dining Room: main	CONDITION	ACTION	COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



2022-09-12 14:02:30

[Image](#)



2022-09-12 14:02:31

[Image](#)



📅 2022-09-12 14:02:33

 [Image](#)



📅 2022-09-12 14:02:36

 [Image](#)



📅 2022-09-12 14:02:37

 [Image](#)



📅 2022-09-12 14:02:39

 [Image](#)



📅 2022-09-12 14:02:44

 [Image](#)



📅 2022-09-12 14:02:46

 [Image](#)



📅 2022-09-12 14:02:47

 [Image](#)



📅 2022-09-12 14:02:52

 [Image](#)



📅 2022-09-12 14:02:54

 [Image](#)



📅 2022-09-12 14:02:55

 [Image](#)



📅 2022-09-12 14:02:57

 [Image](#)



📅 2022-09-12 14:02:59

 [Image](#)



2022-09-12 14:03:02

[Image](#)




2022-09-12 14:03:05

[Image](#)



2022-09-12 14:03:08

[Image](#)



2022-09-12 14:03:16

[Image](#)



2022-09-12 14:03:18

[Image](#)



2022-09-12 14:03:20

[Image](#)



2022-09-12 14:03:22

[Image](#)



2022-09-12 14:03:23

[Image](#)



2022-09-12 14:03:28

[Image](#)



2022-09-12 14:03:29

[Image](#)



2022-09-12 14:03:32

[Image](#)



2022-09-12 14:03:35

[Image](#)



2022-09-12 14:04:16

[Image](#)



2022-09-12 14:04:19

[Image](#)



2022-09-12 14:04:23

[Image](#)



2022-09-12 14:04:24

[Image](#)

Family Room	CONDITION	ACTION	COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



2022-09-12 13:56:07

[Image](#)



2022-09-12 13:56:08

[Image](#)



2022-09-12 13:56:09

[Image](#)



2022-09-12 13:56:14

[Image](#)



2022-09-12 13:56:15

[Image](#)




2022-09-12 13:56:16

[Image](#)



2022-09-12 13:56:18

[Image](#)



2022-09-12 13:56:25

[Image](#)



📅 2022-09-12 13:56:26

 [Image](#)



📅 2022-09-12 13:56:28

 [Image](#)



📅 2022-09-12 13:56:31

 [Image](#)



📅 2022-09-12 13:56:32

 [Image](#)




📅 2022-09-12 13:56:33

 [Image](#)



📅 2022-09-12 13:56:37

 [Image](#)



📅 2022-09-12 13:56:39

[Image](#)



📅 2022-09-12 13:56:40

[Image](#)



📅 2022-09-12 13:56:49

[Image](#)



📅 2022-09-12 13:56:51

[Image](#)


📖 Hallway/Stairs: first floor to second

📌 CONDITION

🔧 ACTION


💬 COMMENTS

Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	




📅 2022-09-12 13:38:27

[Image](#)



📅 2022-09-12 13:38:28

[Image](#)



📅 2022-09-12 13:38:30

 [Image](#)



📅 2022-09-12 13:38:36

 [Image](#)



📅 2022-09-12 13:38:38

 [Image](#)



📅 2022-09-12 13:38:40

 [Image](#)



📅 2022-09-12 13:38:41

 [Image](#)



📅 2022-09-12 13:38:43

 [Image](#)



📅 2022-09-12 13:38:51

 [Image](#)




📅 2022-09-12 13:38:53

 [Image](#)



📅 2022-09-12 13:38:55

 [Image](#)



📅 2022-09-12 13:38:57

 [Image](#)



📅 2022-09-12 13:38:59

 [Image](#)



📅 2022-09-12 13:39:02

 [Image](#)



2022-09-12 13:39:04

[Image](#)



2022-09-12 13:39:06

[Image](#)



2022-09-12 13:39:14

[Image](#)



2022-09-12 13:39:24

[Image](#)



2022-09-12 13:39:26

[Image](#)




2022-09-12 13:39:33

[Image](#)



2022-09-12 13:39:34

[Image](#)



2022-09-12 13:39:36

[Image](#)



2022-09-12 13:39:41

[Image](#)



2022-09-12 13:39:42

[Image](#)



2022-09-12 13:39:44

[Image](#)



2022-09-12 13:39:47

[Image](#)



📅 2022-09-12 13:39:49

 [Image](#)




📅 2022-09-12 13:39:50

 [Image](#)



📅 2022-09-12 13:39:52

 [Image](#)




📅 2022-09-12 13:39:53

 [Image](#)



📅 2022-09-12 13:39:54

 [Image](#)



📅 2022-09-12 13:39:56

 [Image](#)



📅 2022-09-12 13:40:01

 [Image](#)

 Kitchen	 CONDITION	 ACTION	 COMMENTS
Appliances	- S - -	None	
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2022-09-12 13:58:59

 [Image](#)



📅 2022-09-12 13:59:00

 [Image](#)



📅 2022-09-12 13:59:01

 [Image](#)



📅 2022-09-12 13:59:03

 [Image](#)



📅 2022-09-12 13:59:04

 [Image](#)



📅 2022-09-12 13:59:06

 [Image](#)



📅 2022-09-12 13:59:12

 [Image](#)



📅 2022-09-12 13:59:13

 [Image](#)



📅 2022-09-12 13:59:14

 [Image](#)



📅 2022-09-12 13:59:16

 [Image](#)



2022-09-12 13:59:17

[Image](#)



2022-09-12 13:59:18

[Image](#)



2022-09-12 13:59:21

[Image](#)



2022-09-12 13:59:26

[Image](#)



2022-09-12 13:59:28

[Image](#)



2022-09-12 13:59:36

[Image](#)



📅 2022-09-12 13:59:38

 [Image](#)



📅 2022-09-12 13:59:49

 [Image](#)



📅 2022-09-12 13:59:56

 [Image](#)



📅 2022-09-12 13:59:58

 [Image](#)



📅 2022-09-12 14:00:00

 [Image](#)



📅 2022-09-12 14:00:07

 [Image](#)



2022-09-12 14:00:16

[Image](#)



2022-09-12 14:00:22

[Image](#)



2022-09-12 14:00:24

[Image](#)



2022-09-12 14:00:26

[Image](#)



2022-09-12 14:00:27

[Image](#)



2022-09-12 14:00:30

[Image](#)



2022-09-12 14:00:34

[Image](#)



2022-09-12 14:00:50

[Image](#)



2022-09-12 14:00:54

[Image](#)



2022-09-12 14:00:56

[Image](#)



2022-09-12 14:00:58

[Image](#)



2022-09-12 14:00:59

[Image](#)



2022-09-12 14:01:01

[Image](#)



2022-09-12 14:01:05

[Image](#)



2022-09-12 14:01:12

[Image](#)



2022-09-12 14:01:14

[Image](#)



2022-09-12 14:01:17

[Image](#)



2022-09-12 14:01:19

[Image](#)



📅 2022-09-12 14:01:29

 [Image](#)



📅 2022-09-12 14:01:35

 [Image](#)



📅 2022-09-12 14:01:39

 [Image](#)




📅 2022-09-12 14:01:44

 [Image](#)



📅 2022-09-12 14:01:54

 [Image](#)



📅 2022-09-12 14:02:02


 [Image](#)



📅 2022-09-12 14:02:06

[Image](#)

📖 Laundry Room	📍 CONDITION	✂ ACTION	💬 COMMENTS
Washer / Dryer / Hookups	- S - -	None	



📅 2022-09-12 13:57:32

[Image](#)




📅 2022-09-12 13:57:33

[Image](#)



📅 2022-09-12 13:57:34

[Image](#)



📅 2022-09-12 13:57:36

[Image](#)




📅 2022-09-12 13:57:39

 [Image](#)



📅 2022-09-12 13:57:40

 [Image](#)



📅 2022-09-12 13:57:43

 [Image](#)



📅 2022-09-12 13:57:44

 [Image](#)



📅 2022-09-12 13:57:46

 [Image](#)



📅 2022-09-12 13:57:50

 [Image](#)



2022-09-12 13:57:53

[Image](#)



2022-09-12 13:57:55

[Image](#)



2022-09-12 13:57:58

[Image](#)



2022-09-12 13:58:00

[Image](#)



2022-09-12 13:58:03

[Image](#)



2022-09-12 13:58:10

[Image](#)



📅 2022-09-12 13:58:11

 [Image](#)

📖 Living Room	📌 CONDITION	✂ ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2022-09-12 13:35:56

 [Image](#)



📅 2022-09-12 13:35:58

 [Image](#)



📅 2022-09-12 13:35:59

 [Image](#)



📅 2022-09-12 13:36:04

 [Image](#)



📅 2022-09-12 13:36:05

 [Image](#)



📅 2022-09-12 13:36:06

 [Image](#)



📅 2022-09-12 13:36:12

 [Image](#)



📅 2022-09-12 13:36:14

 [Image](#)



📅 2022-09-12 13:36:15

 [Image](#)



📅 2022-09-12 13:36:20

 [Image](#)



2022-09-12 13:36:21

[Image](#)



2022-09-12 13:36:23

[Image](#)



2022-09-12 13:36:26

[Image](#)



2022-09-12 13:36:28

[Image](#)



2022-09-12 13:36:32

[Image](#)



2022-09-12 13:36:35

[Image](#)



2022-09-12 13:36:38

[Image](#)



2022-09-12 13:36:42

[Image](#)



2022-09-12 13:36:44

[Image](#)



2022-09-12 13:36:47

[Image](#)



2022-09-12 13:36:49

[Image](#)



2022-09-12 13:36:51

[Image](#)

Additional Comments

Final Comments

Tenant Signature	Evaluator Signature 
-------------------------	---