

Move Out Evaluation

Property: 1457 Old Whitesville Rd	Tenant(s):	Date: 2023-01-25	Evaluator: Anna Cogdill
---	-------------------	----------------------------	-----------------------------------

Move-Out Conditions


S=Satisfactory

 Entry	 CONDITION	 ACTION	 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



 2023-01-25 09:43:18

 [Image](#)



 2023-01-25 09:43:19

 [Image](#)



2023-01-25 09:43:21

[Image](#)




2023-01-25 09:43:24

[Image](#)



2023-01-25 09:43:29

[Image](#)



2023-01-25 09:43:32

[Image](#)



2023-01-25 09:43:34

[Image](#)



2023-01-25 09:43:35

[Image](#)



📅 2023-01-25 09:43:37

[Image](#)



📅 2023-01-25 09:43:39

[Image](#)

📖 Front Yard/Exterior	📍 CONDITION	✂ ACTION	💬 COMMENTS
Building Exterior	- S - -	None	
Fence/Gate	- S - -	None	
Landscaping	- S - -	None	
Walk/Driveway	- S - -	None	



📅 2023-01-25 09:58:04

[Image](#)



📅 2023-01-25 09:58:06

[Image](#)



📅 2023-01-25 09:58:10

[Image](#)



📅 2023-01-25 09:58:11

[Image](#)



📅 2023-01-25 09:58:13

 [Image](#)



📅 2023-01-25 09:58:14

 [Image](#)



📅 2023-01-25 09:58:36

 [Image](#)



📅 2023-01-25 09:58:37

 [Image](#)



📅 2023-01-25 09:58:39

 [Image](#)



📅 2023-01-25 09:58:41

 [Image](#)



2023-01-25 09:58:42

[Image](#)



2023-01-25 09:58:44

[Image](#)

Bathroom: Master
appears to be good

CONDITION

ACTION

COMMENTS

Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	



2023-01-25 09:53:38

[Image](#)



2023-01-25 09:53:39

[Image](#)



2023-01-25 09:53:42

[Image](#)



2023-01-25 09:53:43

[Image](#)



📅 2023-01-25 09:53:45

 [Image](#)



📅 2023-01-25 09:53:49

 [Image](#)



📅 2023-01-25 09:53:50

 [Image](#)



📅 2023-01-25 09:53:51

 [Image](#)



📅 2023-01-25 09:53:55

 [Image](#)



📅 2023-01-25 09:53:56

 [Image](#)



2023-01-25 09:53:57

[Image](#)



2023-01-25 09:54:00

[Image](#)



2023-01-25 09:54:01

[Image](#)



2023-01-25 09:54:02

[Image](#)



2023-01-25 09:54:06

[Image](#)

Bathroom 2: Bathtub floor is damaged and is covered up, the stopper is broken inside the bathtub and drains slow



CONDITION




ACTION



COMMENTS

Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	



📅 2023-01-25 09:47:20

 [Image](#)



📅 2023-01-25 09:47:21

 [Image](#)



📅 2023-01-25 09:47:23

 [Image](#)



📅 2023-01-25 09:47:25

 [Image](#)



📅 2023-01-25 09:47:27

 [Image](#)



📅 2023-01-25 09:48:11

 [Image](#)



2023-01-25 09:48:14

[Image](#)



2023-01-25 09:48:16

[Image](#)



2023-01-25 09:48:17

[Image](#)



2023-01-25 09:48:21

[Image](#)



2023-01-25 09:48:24

[Image](#)



2023-01-25 09:48:28

[Image](#)



2023-01-25 09:48:35

[Image](#)



2023-01-25 09:48:42

[Image](#)

Bedroom: Master
appears to be good

CONDITION

ACTION

COMMENTS

Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



2023-01-25 09:54:56

[Image](#)



2023-01-25 09:54:58

[Image](#)



2023-01-25 09:54:59

[Image](#)



2023-01-25 09:55:00

[Image](#)



2023-01-25 09:55:05

[Image](#)



2023-01-25 09:55:06

[Image](#)



2023-01-25 09:55:09

[Image](#)



2023-01-25 09:55:14

[Image](#)



2023-01-25 09:55:16

[Image](#)



2023-01-25 09:55:19

[Image](#)



2023-01-25 09:55:20

[Image](#)



2023-01-25 09:55:28

[Image](#)



2023-01-25 09:55:33

[Image](#)



2023-01-25 09:55:36

[Image](#)

Bedroom 2: Straight across the hallway Appears to be good

CONDITION

ACTION

COMMENTS

Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



2023-01-25 09:52:06

[Image](#)



2023-01-25 09:52:07

[Image](#)



📅 2023-01-25 09:52:08

 [Image](#)



📅 2023-01-25 09:52:12

 [Image](#)



📅 2023-01-25 09:52:13

 [Image](#)



📅 2023-01-25 09:52:14

 [Image](#)



📅 2023-01-25 09:52:18

 [Image](#)



📅 2023-01-25 09:52:19

 [Image](#)



📅 2023-01-25 09:52:21

 [Image](#)



📅 2023-01-25 09:52:24

 [Image](#)



📅 2023-01-25 09:52:25

 [Image](#)




📅 2023-01-25 09:52:26

 [Image](#)



📅 2023-01-25 09:52:29

 [Image](#)



📅 2023-01-25 09:52:34

 [Image](#)



📅 2023-01-25 09:52:42

[Image](#)

📖 **Bedroom 3: First door to the right Door damaged and painted over**

📌 **CONDITION**

✂ **ACTION**

💬 **COMMENTS**

Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



📅 2023-01-25 09:49:59

[Image](#)



📅 2023-01-25 09:50:01

[Image](#)



📅 2023-01-25 09:50:06

[Image](#)



📅 2023-01-25 09:50:08

[Image](#)



📅 2023-01-25 09:50:10

 [Image](#)



📅 2023-01-25 09:50:13

 [Image](#)



📅 2023-01-25 09:50:14

 [Image](#)



📅 2023-01-25 09:50:16

 [Image](#)



📅 2023-01-25 09:50:19

 [Image](#)



📅 2023-01-25 09:50:20

 [Image](#)



📅 2023-01-25 09:50:21

 [Image](#)



📅 2023-01-25 09:50:25

 [Image](#)



📅 2023-01-25 09:50:26

 [Image](#)



📅 2023-01-25 09:50:28

 [Image](#)



📅 2023-01-25 09:50:31

 [Image](#)



📅 2023-01-25 09:50:32

 [Image](#)



📅 2023-01-25 09:50:33

[Image](#)



📅 2023-01-25 09:50:41

[Image](#)

Dining Room	CONDITION	ACTION	COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-01-25 09:36:38

[Image](#)



📅 2023-01-25 09:36:39

[Image](#)



📅 2023-01-25 09:36:41

[Image](#)



📅 2023-01-25 09:36:44

[Image](#)



2023-01-25 09:36:45

[Image](#)



2023-01-25 09:36:46

[Image](#)



2023-01-25 09:36:48

[Image](#)



2023-01-25 09:36:50

[Image](#)



2023-01-25 09:36:51

[Image](#)



2023-01-25 09:36:54

[Image](#)

Family Room	CONDITION	ACTION	COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-01-25 09:38:32

 [Image](#)



📅 2023-01-25 09:38:34

 [Image](#)



📅 2023-01-25 09:38:35

 [Image](#)



📅 2023-01-25 09:38:40

 [Image](#)



📅 2023-01-25 09:38:41

 [Image](#)



📅 2023-01-25 09:38:42

 [Image](#)



📅 2023-01-25 09:38:48

 [Image](#)



📅 2023-01-25 09:38:49

 [Image](#)



📅 2023-01-25 09:38:51

 [Image](#)



📅 2023-01-25 09:38:55

 [Image](#)



📅 2023-01-25 09:38:56

 [Image](#)



📅 2023-01-25 09:38:57

 [Image](#)



📅 2023-01-25 09:39:01

 [Image](#)



📅 2023-01-25 09:39:06

 [Image](#)



📅 2023-01-25 09:39:09

 [Image](#)



📅 2023-01-25 09:39:11

 [Image](#)



📅 2023-01-25 09:39:16

 [Image](#)



📅 2023-01-25 09:39:20

 [Image](#)




2023-01-25 09:39:27

[Image](#)



2023-01-25 09:39:32

[Image](#)



2023-01-25 09:39:33

[Image](#)



2023-01-25 09:39:34

[Image](#)



2023-01-25 09:41:22

[Image](#)



2023-01-25 09:41:56

[Image](#)

Hallway/Stairs	CONDITION	ACTION	COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



2023-01-25 09:45:52

[Image](#)




2023-01-25 09:45:53

[Image](#)



2023-01-25 09:45:54

[Image](#)



2023-01-25 09:45:58

[Image](#)



2023-01-25 09:46:01

[Image](#)



2023-01-25 09:46:08

[Image](#)



2023-01-25 09:46:14

[Image](#)



2023-01-25 09:46:15

[Image](#)



2023-01-25 09:46:19

[Image](#)



2023-01-25 09:46:21

[Image](#)



2023-01-25 09:46:27

[Image](#)



2023-01-25 09:46:28

[Image](#)



📅 2023-01-25 09:46:30

[Image](#)



📅 2023-01-25 09:46:31

[Image](#)



📅 2023-01-25 09:46:35


[Image](#)



📅 2023-01-25 09:46:39

[Image](#)

Kitchen	CONDITION	ACTION	COMMENTS
Appliances	- S - -	None	
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-01-25 09:31:43

[Image](#)



📅 2023-01-25 09:31:45

[Image](#)



📅 2023-01-25 09:31:47

[🖼️ Image](#)



📅 2023-01-25 09:31:48

[🖼️ Image](#)



📅 2023-01-25 09:31:53

[🖼️ Image](#)



📅 2023-01-25 09:31:57

[🖼️ Image](#)



📅 2023-01-25 09:32:04

[🖼️ Image](#)



📅 2023-01-25 09:32:13

[🖼️ Image](#)



2023-01-25 09:32:18

[Image](#)



2023-01-25 09:32:22

[Image](#)



2023-01-25 09:32:27

[Image](#)



2023-01-25 09:32:31

[Image](#)



2023-01-25 09:32:35

[Image](#)



2023-01-25 09:32:43

[Image](#)



📅 2023-01-25 09:32:45

 [Image](#)



📅 2023-01-25 09:33:43

 [Image](#)



📅 2023-01-25 09:33:52

 [Image](#)



📅 2023-01-25 09:33:58

 [Image](#)



📅 2023-01-25 09:34:03

 [Image](#)



📅 2023-01-25 09:34:04

 [Image](#)



📅 2023-01-25 09:34:06

[Image](#)



📅 2023-01-25 09:34:11

[Image](#)



📅 2023-01-25 09:34:20

[Image](#)



📅 2023-01-25 09:34:28

[Image](#)



📅 2023-01-25 09:34:29

[Image](#)



📅 2023-01-25 09:34:31

[Image](#)



📅 2023-01-25 09:34:55

[Image](#)



📅 2023-01-25 09:35:01

[Image](#)



📅 2023-01-25 09:35:10

[Image](#)



📅 2023-01-25 09:35:18

[Image](#)



📅 2023-01-25 09:35:39

[Image](#)



📅 2023-01-25 09:35:46

[Image](#)

Laundry Room	CONDITION	ACTION	COMMENTS
Washer / Dryer / Hookups	- S - -	None	



📅 2023-01-25 09:41:32

[Image](#)




📅 2023-01-25 09:41:33

[Image](#)



📅 2023-01-25 09:41:35

[Image](#)



📅 2023-01-25 09:41:40

[Image](#)



📅 2023-01-25 09:41:41

[Image](#)



📅 2023-01-25 09:41:42

[Image](#)



📅 2023-01-25 09:41:44

[Image](#)



📅 2023-01-25 09:41:46

[Image](#)

📖 Living Room	🔗 CONDITION	✂ ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-01-25 09:44:36

[Image](#)



📅 2023-01-25 09:44:37

[Image](#)



📅 2023-01-25 09:44:38

[Image](#)



📅 2023-01-25 09:44:42

[Image](#)



📅 2023-01-25 09:44:44

 [Image](#)



📅 2023-01-25 09:44:45

 [Image](#)



📅 2023-01-25 09:44:59

 [Image](#)



📅 2023-01-25 09:45:01

 [Image](#)



📅 2023-01-25 09:45:02

 [Image](#)




📅 2023-01-25 09:45:06

 [Image](#)



📅 2023-01-25 09:45:07

[Image](#)



📅 2023-01-25 09:45:08

[Image](#)



📅 2023-01-25 09:45:11

[Image](#)

Back Yard/Exterior	CONDITION	ACTION	COMMENTS
Landscaping	- S - -	None	
Other	- S - -	None	



📅 2023-01-25 09:56:20

[Image](#)



📅 2023-01-25 09:56:22

[Image](#)



📅 2023-01-25 09:56:23

 [Image](#)



📅 2023-01-25 09:56:25

 [Image](#)



📅 2023-01-25 09:56:34

 [Image](#)



📅 2023-01-25 09:56:36

 [Image](#)



📅 2023-01-25 09:56:37

 [Image](#)



📅 2023-01-25 09:56:39

 [Image](#)



📅 2023-01-25 09:56:40

[Image](#)

Garage/Parking	CONDITION	ACTION	COMMENTS
Overall area	- S - -	None	

Keys/Remotes/Devices	CONDITION	ACTION	COMMENTS
Keys/fobs/devices	- S - -	None	

Roof	CONDITION	ACTION	COMMENTS
Dry Rot	- S - -	None	
Eaves	- S - -	None	
Fireplace/Chimney	- S - -	None	
Gutters	- S - -	None	
Other	- S - -	None	
Shingles/Roof Covering	- S - -	None	
Vent Pipes	- S - -	None	

Safety/Security	CONDITION	ACTION	COMMENTS
Other	- S - -	None	
Please provide picture of smoke detector in each bedroom.	- S - -	None	
Security System	- S - -	None	
Security Window Bars	- S - -	None	
Smoke/CO Detector	- S - -	None	

Systems	CONDITION	ACTION	COMMENTS
Air Conditioning/Filter	- S - -	None	
Breaker Box	- S - -	None	
Furnace	- S - -	None	
Other	- S - -	None	

 Systems	 CONDITION	 ACTION	 COMMENTS
Sewer Cleanout	- S - -	None	
Sprinkler/Timer	- S - -	None	
Thermostat	- S - -	None	
Water Heater	- S - -	None	
Water Softener	- S - -	None	
Whole House Fan	- S - -	None	

Additional Comments

Final Comments

Tenant Signature	Evaluator Signature 
--------------------------------	--