

Move Out Evaluation

Property: 101 Gatehouse Drive	Tenant(s):	Date: 2023-01-23	Evaluator: Anna Cogdill
---	-------------------	----------------------------	-----------------------------------

Move-Out Conditions

S=Satisfactory

 Entry	 CONDITION	 ACTION	 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



 2023-01-23 12:14:29

 [Image](#)



 2023-01-23 12:14:31

 [Image](#)



📅 2023-01-23 12:14:32

 [Image](#)



📅 2023-01-23 12:14:34

 [Image](#)



📅 2023-01-23 12:14:36

 [Image](#)



📅 2023-01-23 12:14:38

 [Image](#)



📅 2023-01-23 12:14:43

 [Image](#)



📅 2023-01-23 12:14:47

 [Image](#)




📅 2023-01-23 12:14:51

[Image](#)



📅 2023-01-23 12:14:53

[Image](#)



📅 2023-01-23 12:14:55

[Image](#)



📅 2023-01-23 12:14:57

[Image](#)



📅 2023-01-23 12:15:00

[Image](#)



📅 2023-01-23 12:15:10

[Image](#)

Front Yard/Exterior	CONDITION	ACTION	COMMENTS
Building Exterior	- S - -	None	
Fence/Gate	- S - -	None	
Landscaping	- S - -	None	
Walk/Driveway	- S - -	None	



📅 2023-01-23 12:32:56

 [Image](#)



📅 2023-01-23 12:32:57

 [Image](#)



📅 2023-01-23 12:32:59

 [Image](#)



📅 2023-01-23 12:33:01

 [Image](#)



📅 2023-01-23 12:33:02

 [Image](#)



📅 2023-01-23 12:33:05

 [Image](#)



📅 2023-01-23 12:33:07

 [Image](#)



📅 2023-01-23 12:33:09

 [Image](#)



📅 2023-01-23 12:33:12

 [Image](#)



📅 2023-01-23 12:33:15

 [Image](#)




📅 2023-01-23 12:33:17

 [Image](#)



📅 2023-01-23 12:33:20

 [Image](#)



📅 2023-01-23 12:33:21

 [Image](#)



📅 2023-01-23 12:52:09

 [Image](#)



📅 2023-01-23 12:52:11

 [Image](#)



📅 2023-01-23 12:52:12

 [Image](#)



📅 2023-01-23 12:52:14

 [Image](#)



📅 2023-01-23 12:52:15

 [Image](#)



📅 2023-01-23 12:52:19

 [Image](#)



📅 2023-01-23 12:52:21

 [Image](#)



📅 2023-01-23 12:52:31

 [Image](#)



📅 2023-01-23 12:52:33

 [Image](#)



📅 2023-01-23 12:52:34

 [Image](#)



📅 2023-01-23 12:52:36

 [Image](#)



📅 2023-01-23 12:52:38

🖼️ [Image](#)



📅 2023-01-23 12:52:42

🖼️ [Image](#)



📅 2023-01-23 12:52:44


🖼️ [Image](#)



📅 2023-01-23 12:52:50

🖼️ [Image](#)

📖 Bathroom: Master	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	



📅 2023-01-23 12:47:38

🖼️ [Image](#)



📅 2023-01-23 12:47:39

🖼️ [Image](#)



2023-01-23 12:47:41

[Image](#)



2023-01-23 12:47:43

[Image](#)



2023-01-23 12:47:44

[Image](#)



2023-01-23 12:47:46

[Image](#)



2023-01-23 12:47:48

[Image](#)



2023-01-23 12:48:00

[Image](#)



2023-01-23 12:48:13

[Image](#)



2023-01-23 12:48:21

[Image](#)



2023-01-23 12:48:24


[Image](#)



2023-01-23 12:48:30


[Image](#)

🏠 Bathroom 2: Secondary		📍 CONDITION	🔧 ACTION	💬 COMMENTS
Plumbing	- S - -	None		
Walls/Ceiling/Paint	- S - -	None		



2023-01-23 12:40:52

[Image](#)



2023-01-23 12:40:56

[Image](#)



📅 2023-01-23 12:40:58

 [Image](#)



📅 2023-01-23 12:40:59

 [Image](#)



📅 2023-01-23 12:41:01

 [Image](#)



📅 2023-01-23 12:41:03

 [Image](#)



📅 2023-01-23 12:41:05

 [Image](#)



📅 2023-01-23 12:41:06

 [Image](#)



📅 2023-01-23 12:41:10

 [Image](#)



📅 2023-01-23 12:41:16

 [Image](#)



📅 2023-01-23 12:41:20

 [Image](#)



📅 2023-01-23 12:41:23

 [Image](#)




📅 2023-01-23 12:41:36

 [Image](#)



📅 2023-01-23 12:41:39

 [Image](#)




2023-01-23 12:41:42

[Image](#)



2023-01-23 12:41:44

[Image](#)




2023-01-23 12:41:48

[Image](#)




2023-01-23 12:41:50

[Image](#)



2023-01-23 12:41:52

[Image](#)



2023-01-23 12:41:54

[Image](#)



📅 2023-01-23 12:41:56

 [Image](#)



📅 2023-01-23 12:41:59

 [Image](#)



📅 2023-01-23 12:42:04

 [Image](#)



📅 2023-01-23 12:42:06

 [Image](#)



📅 2023-01-23 12:42:08

 [Image](#)




📅 2023-01-23 12:42:13

 [Image](#)



📅 2023-01-23 12:42:23

[Image](#)



📅 2023-01-23 12:42:25

[Image](#)



📅 2023-01-23 12:42:36

[Image](#)

📖 Bedroom: Master	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



📅 2023-01-23 12:45:18

[Image](#)



📅 2023-01-23 12:45:20

[Image](#)



📅 2023-01-23 12:45:30

 [Image](#)



📅 2023-01-23 12:45:37

 [Image](#)



📅 2023-01-23 12:45:38

 [Image](#)



📅 2023-01-23 12:45:39

 [Image](#)



📅 2023-01-23 12:45:45

 [Image](#)



📅 2023-01-23 12:45:46

 [Image](#)



📅 2023-01-23 12:45:48

 [Image](#)



📅 2023-01-23 12:45:56

 [Image](#)



📅 2023-01-23 12:45:58

 [Image](#)



📅 2023-01-23 12:45:59

 [Image](#)



📅 2023-01-23 12:46:05

 [Image](#)




📅 2023-01-23 12:46:06

 [Image](#)



📅 2023-01-23 12:46:08

 [Image](#)



📅 2023-01-23 12:46:16

 [Image](#)



📅 2023-01-23 12:46:17

 [Image](#)



📅 2023-01-23 12:46:25

 [Image](#)



📅 2023-01-23 12:46:29

 [Image](#)



📅 2023-01-23 12:46:33

 [Image](#)



2023-01-23 12:46:38

[Image](#)




2023-01-23 12:46:42

[Image](#)



2023-01-23 12:51:22

[Image](#)



2023-01-23 12:51:26

[Image](#)

Bedroom 2: spare room 2

	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



2023-01-23 12:43:22

[Image](#)



2023-01-23 12:43:24

[Image](#)



📅 2023-01-23 12:43:27

 [Image](#)



📅 2023-01-23 12:43:28

 [Image](#)



📅 2023-01-23 12:43:29

 [Image](#)



📅 2023-01-23 12:43:35

 [Image](#)



📅 2023-01-23 12:43:36

 [Image](#)



📅 2023-01-23 12:43:37

 [Image](#)



📅 2023-01-23 12:43:42

 [Image](#)



📅 2023-01-23 12:43:44

 [Image](#)



📅 2023-01-23 12:43:45

 [Image](#)



📅 2023-01-23 12:43:50

 [Image](#)



📅 2023-01-23 12:43:51

 [Image](#)




📅 2023-01-23 12:43:52

 [Image](#)



📅 2023-01-23 12:44:03

 [Image](#)




📅 2023-01-23 12:44:06

 [Image](#)



📅 2023-01-23 12:44:09

 [Image](#)



📅 2023-01-23 12:44:14

 [Image](#)



📅 2023-01-23 12:44:16

 [Image](#)



📅 2023-01-23 12:44:22

 [Image](#)



📅 2023-01-23 12:44:23

 [Image](#)


📖 Bedroom 3: spare room
3

🔗 CONDITION

✂ ACTION

💬 COMMENTS

Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



📅 2023-01-23 12:49:25

 [Image](#)



📅 2023-01-23 12:49:27

 [Image](#)



📅 2023-01-23 12:49:31

 [Image](#)



📅 2023-01-23 12:49:35

 [Image](#)



📅 2023-01-23 12:49:36

 [Image](#)



📅 2023-01-23 12:49:39

 [Image](#)



📅 2023-01-23 12:49:41

 [Image](#)



📅 2023-01-23 12:49:44

 [Image](#)



📅 2023-01-23 12:49:49

 [Image](#)



📅 2023-01-23 12:49:50

 [Image](#)



📅 2023-01-23 12:49:52

 [Image](#)



📅 2023-01-23 12:49:57

 [Image](#)



📅 2023-01-23 12:49:58

 [Image](#)



📅 2023-01-23 12:49:59

 [Image](#)



📅 2023-01-23 12:50:04

 [Image](#)



📅 2023-01-23 12:50:07

 [Image](#)



📅 2023-01-23 12:50:08

 [Image](#)



📅 2023-01-23 12:50:14

 [Image](#)



📅 2023-01-23 12:50:15

 [Image](#)



📅 2023-01-23 12:50:16

 [Image](#)



📅 2023-01-23 12:50:20

 [Image](#)



📅 2023-01-23 12:50:21

 [Image](#)



📅 2023-01-23 12:50:24

[Image](#)



📅 2023-01-23 12:50:26

[Image](#)

Garage/Parking	CONDITION	ACTION	COMMENTS
Overall area	- S - -	None	




📅 2023-01-23 12:28:59

[Image](#)



📅 2023-01-23 12:29:01

[Image](#)



📅 2023-01-23 12:29:13

[Image](#)



📅 2023-01-23 12:29:15

[Image](#)



📅 2023-01-23 12:29:16

 [Image](#)



📅 2023-01-23 12:29:24

 [Image](#)



📅 2023-01-23 12:29:26

 [Image](#)



📅 2023-01-23 12:29:27

 [Image](#)



📅 2023-01-23 12:29:33

 [Image](#)



📅 2023-01-23 12:29:35

 [Image](#)



📅 2023-01-23 12:29:36

 [Image](#)



📅 2023-01-23 12:29:46

 [Image](#)



📅 2023-01-23 12:29:48

 [Image](#)



📅 2023-01-23 12:29:49

 [Image](#)



📅 2023-01-23 12:29:53

 [Image](#)



📅 2023-01-23 12:29:56

 [Image](#)



📅 2023-01-23 12:31:33

 [Image](#)



📅 2023-01-23 12:36:33

 [Image](#)



📅 2023-01-23 12:36:35

 [Image](#)



📅 2023-01-23 12:36:38

 [Image](#)



📅 2023-01-23 12:36:42

 [Image](#)



📅 2023-01-23 12:36:44

 [Image](#)



📅 2023-01-23 12:36:47

 [Image](#)



📅 2023-01-23 12:36:51

 [Image](#)



📅 2023-01-23 12:36:55

 [Image](#)



📅 2023-01-23 12:36:56

 [Image](#)



📅 2023-01-23 12:37:01

 [Image](#)



📅 2023-01-23 12:37:04

 [Image](#)



📅 2023-01-23 12:37:05

 [Image](#)

📖 Garage/Parking 2	📍 CONDITION	✂ ACTION	💬 COMMENTS
Overall area	- S - -	None	



📅 2023-01-23 12:30:07

 [Image](#)



📅 2023-01-23 12:30:09

 [Image](#)



📅 2023-01-23 12:30:15

 [Image](#)



📅 2023-01-23 12:30:19

 [Image](#)



📅 2023-01-23 12:30:24

[Image](#)



📅 2023-01-23 12:30:35

[Image](#)



📅 2023-01-23 12:31:23

[Image](#)



📅 2023-01-23 12:31:24

[Image](#)

📖 Dining Room: main

📌 CONDITION

🔧 ACTION

💬 COMMENTS

Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-01-23 12:18:40

[Image](#)



📅 2023-01-23 12:18:42

[Image](#)



📅 2023-01-23 12:18:43

 [Image](#)



📅 2023-01-23 12:18:48

 [Image](#)



📅 2023-01-23 12:18:49

 [Image](#)



📅 2023-01-23 12:18:51

 [Image](#)



📅 2023-01-23 12:18:57

 [Image](#)



📅 2023-01-23 12:18:58

 [Image](#)



📅 2023-01-23 12:19:00

 [Image](#)



📅 2023-01-23 12:19:09

 [Image](#)



📅 2023-01-23 12:19:11

 [Image](#)



📅 2023-01-23 12:19:12

 [Image](#)



📅 2023-01-23 12:19:22

 [Image](#)



📅 2023-01-23 12:19:30

 [Image](#)



📅 2023-01-23 12:19:32

[Image](#)



📅 2023-01-23 12:19:33

[Image](#)



📅 2023-01-23 12:25:50

[Image](#)

📖 Hallway/Stairs: first floor to second

	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	




📅 2023-01-23 12:37:40

[Image](#)



📅 2023-01-23 12:37:42

[Image](#)



📅 2023-01-23 12:37:43

 [Image](#)




📅 2023-01-23 12:37:46

 [Image](#)



📅 2023-01-23 12:37:48

 [Image](#)



📅 2023-01-23 12:38:15

 [Image](#)



📅 2023-01-23 12:38:16

 [Image](#)



📅 2023-01-23 12:38:18

 [Image](#)



2023-01-23 12:38:20

[Image](#)



2023-01-23 12:38:21

[Image](#)



2023-01-23 12:38:25

[Image](#)



2023-01-23 12:38:42

[Image](#)




2023-01-23 12:38:50

[Image](#)



2023-01-23 12:38:52

[Image](#)



📅 2023-01-23 12:38:54

[Image](#)



📅 2023-01-23 12:38:55

[Image](#)

Kitchen	CONDITION	ACTION	COMMENTS
Appliances	- S - -	None	
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-01-23 12:20:31

[Image](#)



📅 2023-01-23 12:20:33

[Image](#)



📅 2023-01-23 12:20:34

[Image](#)



📅 2023-01-23 12:20:37

[Image](#)



2023-01-23 12:20:41

[Image](#)




2023-01-23 12:20:47

[Image](#)



2023-01-23 12:20:50

[Image](#)



2023-01-23 12:20:53

[Image](#)



2023-01-23 12:21:16

[Image](#)



2023-01-23 12:21:24

[Image](#)



📅 2023-01-23 12:21:35

 [Image](#)



📅 2023-01-23 12:21:45

 [Image](#)



📅 2023-01-23 12:21:56

 [Image](#)



📅 2023-01-23 12:22:05

 [Image](#)



📅 2023-01-23 12:22:14

 [Image](#)



📅 2023-01-23 12:22:15

 [Image](#)



📅 2023-01-23 12:22:17

 [Image](#)



📅 2023-01-23 12:22:19

 [Image](#)



📅 2023-01-23 12:22:24

 [Image](#)



📅 2023-01-23 12:22:28

 [Image](#)



📅 2023-01-23 12:22:32

 [Image](#)



📅 2023-01-23 12:22:35

 [Image](#)



📅 2023-01-23 12:22:36

 [Image](#)



📅 2023-01-23 12:22:45

 [Image](#)



📅 2023-01-23 12:22:52

 [Image](#)



📅 2023-01-23 12:22:54

 [Image](#)



📅 2023-01-23 12:23:07

 [Image](#)



📅 2023-01-23 12:23:17

 [Image](#)



📅 2023-01-23 12:23:19

 [Image](#)



📅 2023-01-23 12:23:35

 [Image](#)



📅 2023-01-23 12:23:38

 [Image](#)



📅 2023-01-23 12:23:43

 [Image](#)



📅 2023-01-23 12:23:54

 [Image](#)



📅 2023-01-23 12:23:59


 [Image](#)



📅 2023-01-23 12:26:00

[Image](#)

📖 Laundry Room	📍 CONDITION	🛠 ACTION	💬 COMMENTS
Washer / Dryer / Hookups	- S - -	None	



📅 2023-01-23 12:27:00

[Image](#)



📅 2023-01-23 12:27:01

[Image](#)



📅 2023-01-23 12:27:03

[Image](#)



📅 2023-01-23 12:27:05

[Image](#)



📅 2023-01-23 12:27:06

 [Image](#)



📅 2023-01-23 12:27:08

 [Image](#)



📅 2023-01-23 12:27:12

 [Image](#)



📅 2023-01-23 12:27:14

 [Image](#)



📅 2023-01-23 12:27:15

 [Image](#)



📅 2023-01-23 12:27:34

 [Image](#)



2023-01-23 12:27:41

[Image](#)



2023-01-23 12:27:42

[Image](#)

Living Room	CONDITION	ACTION	COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



2023-01-23 12:16:19

[Image](#)



2023-01-23 12:16:20

[Image](#)



2023-01-23 12:16:21

[Image](#)



2023-01-23 12:16:30

[Image](#)



📅 2023-01-23 12:16:32

 [Image](#)



📅 2023-01-23 12:16:33

 [Image](#)



📅 2023-01-23 12:16:40

 [Image](#)



📅 2023-01-23 12:16:42

 [Image](#)



📅 2023-01-23 12:16:43

 [Image](#)



📅 2023-01-23 12:16:50

 [Image](#)



📅 2023-01-23 12:16:52

 [Image](#)



📅 2023-01-23 12:16:53

 [Image](#)



📅 2023-01-23 12:17:00

 [Image](#)



📅 2023-01-23 12:17:05

 [Image](#)



📅 2023-01-23 12:17:12

 [Image](#)



📅 2023-01-23 12:17:15

 [Image](#)



📅 2023-01-23 12:17:17

 [Image](#)



📅 2023-01-23 12:17:26

 [Image](#)



📅 2023-01-23 12:17:33

 [Image](#)



📅 2023-01-23 12:17:35

 [Image](#)



📅 2023-01-23 12:17:40

 [Image](#)

Additional Comments

Final Comments

Tenant Signature	Evaluator Signature 
-------------------------	--