

 AREA
 DETAIL
 ACTION
 COMMENTS
 MEDIA

ManagerServices Page 1 of 45 Report generated by zInspector

AREA	DETAIL		ACTION	COMMENTS	MEDIA
Dining Room	Flooring/Baseboard		Maintenance	Missing wood paneling	 Image
Dining Room	Wall/Ceiling		Maintenance	Broken wall outlet, marks on wall, scratched doorframe, hooks for certain left in wall.	 Image  Image  Image  Image  Image  Image  Image  Image  Image  Image
Dining Room	Window Covering		Maintenance	Mismatching blinds	 Image
Kitchen	Appliances		Maintenance	Broken covering on microwave	 Image  Image  Image  Image  Image  Image  Image
Kitchen	Flooring/Baseboard		Maintenance	Scratches in tile	 Image  Image
Kitchen	Wall/Ceiling		Maintenance	Discoloration from oven on ceiling, scratched paint	 Image  Image
Laundry Room	Wall/Ceiling		Maintenance	Marks on wall	 Image  Image  Image  Image
Garage/Parking	Walls/Ceiling		Maintenance	Marks/scratches on wall	 Image  Image  Image  Image  Image
Bathroom: Primary	Door/Knob/Lock		Maintenance	Scratched door frame	 Image  Image
Bathroom: Primary	Flooring/Baseboard		Maintenance	Wood paneling separating	 Image  Image
Bathroom: Primary	Tub/Shower		Maintenance	Dirty bath tub	 Image
Bathroom: Primary	Wall/Ceiling		Maintenance	Scratches on wall, aging on mirror	 Image  Image  Image

AREA	DETAIL		ACTION	COMMENTS	MEDIA
Bedroom: Primary	Wall/Ceiling		Maintenance	Marks on wall, mismatching paint, Ethernet cable cover pulled out	 Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image
Bedroom 2: Right of stairs	Closet/Door/Track/Shelving		Maintenance	Marks on door and wall	 Image  Image
Bedroom 2: Right of stairs	Door/Knob/Lock		Maintenance	Scratches on door and door frame	 Image  Image  Image  Image
Bedroom 2: Right of stairs	Wall/Ceiling		Maintenance	Marks/holes in wall	 Image  Image  Image  Image  Image  Image  Image
Bedroom 3: Far right behind stairs	Door/Knob/Lock		Maintenance	Scratches/marks on door and door frame	 Image  Image  Image  Image  Image
Bedroom 3: Far right behind stairs	Wall/Ceiling		Maintenance	Marks on walls	 Image  Image  Image  Image  Image
Bedroom 4: In family room	Closet/Door/Track/Shelving		Maintenance	Scratches on door	 Image  Image
Bedroom 4: In family room	Door/Knob/Lock		Maintenance	Scratches/marks on door and door frame	 Image  Image  Image  Image

AREA	DETAIL		ACTION	COMMENTS	MEDIA
Bedroom 4: In family room	Wall/Ceiling		Maintenance	Marks and scratches on wall, tacks	 Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image  Image
Systems	Smoke Alarms		Maintenance	Smoke detector hanging from ceiling.	 Image

🔒 Move-Out Conditions

S=Satisfactory

! - Action

📖 Front Yard/Exterior	🔒 CONDITION	✂ ACTION	💬 COMMENTS
Building Exterior	- S - -	None	
Landscaping	- S - -	None	
Light Fixture	- S - -	None	
Walk/Driveway	- - - !	Maintenance	Items left behind



Building Exterior
📅 2024-04-30 10:57:04
[🖼 Image](#)



Building Exterior
📅 2024-04-30 10:57:24
[🖼 Image](#)



Building Exterior
📅 2024-04-30 10:57:41
[🖼 Image](#)



Walk/Driveway
📅 2024-04-30 10:56:39
[🖼 Image](#)

📖 Back Yard/Exterior	🔒 CONDITION	✂ ACTION	💬 COMMENTS
Building Exterior	- - - !	Maintenance	Damaged door frame
Fence/Gate	- S - -	None	
Landscaping	- S - -	None	
Light Fixture	- S - -	None	

📖 Back Yard/Exterior	📍 CONDITION	🛠 ACTION	💬 COMMENTS
Patio/Deck/Balcony	- - - !	Maintenance	Particle board left on patio



Building Exterior
📅 2024-04-30 10:59:00
[🖼 Image](#)



Building Exterior
📅 2024-04-30 10:59:09
[🖼 Image](#)



Building Exterior
📅 2024-04-30 10:59:28
[🖼 Image](#)



Building Exterior
📅 2024-04-30 11:01:09
[🖼 Image](#)



Building Exterior
📅 2024-04-30 11:01:16
[🖼 Image](#)



Fence/Gate
📅 2024-04-30 10:59:43
[🖼 Image](#)



Fence/Gate
📅 2024-04-30 10:59:47
[Image](#)



Fence/Gate
📅 2024-04-30 10:59:50
[Image](#)



Fence/Gate
📅 2024-04-30 10:59:56
[Image](#)



Fence/Gate
📅 2024-04-30 11:00:00
[Image](#)



Fence/Gate
📅 2024-04-30 11:00:06
[Image](#)



Fence/Gate
📅 2024-04-30 11:00:14
[Image](#)



Landscaping
 📅 2024-04-30 10:58:38
[Image](#)



Patio/Deck/Balcony
 📅 2024-04-30 11:00:34
[Image](#)



Patio/Deck/Balcony
 📅 2024-04-30 11:00:38
[Image](#)



Patio/Deck/Balcony
 📅 2024-04-30 11:00:41
[Image](#)



Patio/Deck/Balcony
 📅 2024-04-30 11:00:52
[Image](#)

📖 Entry	📍 CONDITION	🛠 ACTION	💬 COMMENTS
Door/Knob/Lock	- - - !	Maintenance	Door missing paint
Doorbell	- S - -	None	
Flooring/Baseboard	- S - -	None	
Front Porch	- S - -	None	

📖 Entry	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Damaged wood on pillar. Scratched paint on interior entry way



📅 2024-04-30 11:03:52
[🌐 360 Viewer](#)



Door/Knob/Lock
 📅 2024-04-30 10:19:39
[🖼️ Image](#)



Door/Knob/Lock
 📅 2024-04-30 10:30:49
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:19:29
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:19:52
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:56:00
[🖼️ Image](#)

📖 Living Room	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- - - !	Maintenance	Wood paneling splitting apart
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Scratches on wall, chipped paint, screws left in wall, missing outlet cover
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



📅 2024-04-30 11:03:25
🌐 [360 Viewer](#)



Flooring/Baseboard
📅 2024-04-30 10:31:16
🖼️ [Image](#)



Flooring/Baseboard
📅 2024-04-30 10:31:21
🖼️ [Image](#)



Wall/Ceiling
📅 2024-04-30 10:17:37
🖼️ [Image](#)



Wall/Ceiling
📅 2024-04-30 10:17:46
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:17:54
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:18:02
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:18:15
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:18:22
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:18:31
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:18:36
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:18:49
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:18:55
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:19:16
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:20:05
[Image](#)


📖 Dining Room	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- - - !	Maintenance	Missing wood paneling
Light Fixture/Fan	- S - -	None	

 Dining Room	 CONDITION	 ACTION	 COMMENTS
Wall/Ceiling	- - - !	Maintenance	Broken wall outlet, marks on wall, scratched doorframe, hooks for certain left in wall.
Window Covering	- - - !	Maintenance	Mismatching blinds
Window/Lock/Screen	- S - -	None	



 2024-04-30 11:08:52

 [360 Viewer](#)



Flooring/Baseboard

 2024-04-30 10:32:06

 [Image](#)



Wall/Ceiling

 2024-04-30 10:27:19

 [Image](#)



Wall/Ceiling

 2024-04-30 10:27:25

 [Image](#)



Wall/Ceiling
📅 2024-04-30 10:27:48
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:28:03
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:28:09
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:28:13
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:28:26
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:28:38
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:28:49
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:29:01
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:32:13
[Image](#)



Window Covering
 📅 2024-04-30 10:27:37
[Image](#)

📖 Kitchen	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Appliances	- - - !	Maintenance	Broken covering on microwave
Cabinets/Drawers	- S - -	None	
Flooring/Baseboard	- - - !	Maintenance	Scratches in tile
Light Fixture	- S - -	None	
Sink/Disposal	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Discoloration from oven on ceiling, scratched paint
Window/Lock/Screen	- S - -	None	



📅 2024-04-30 11:09:24

[360 Viewer](#)



Appliances

📅 2024-04-30 10:32:30

[Image](#)



Appliances

📅 2024-04-30 10:32:37

[Image](#)



Appliances

📅 2024-04-30 10:32:51

[Image](#)



Appliances

📅 2024-04-30 10:33:07

[Image](#)



Appliances

📅 2024-04-30 10:33:23

[Image](#)



Appliances
📅 2024-04-30 10:33:30
[Image](#)



Appliances
📅 2024-04-30 10:33:45
[Image](#)



Appliances
📅 2024-04-30 10:33:52
[Image](#)



Flooring/Baseboard
📅 2024-04-30 11:10:22
[Image](#)



Flooring/Baseboard
📅 2024-04-30 11:10:27
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:34:13
[Image](#)



Wall/Ceiling

📅 2024-04-30 11:04:45

[Image](#)

📖 Laundry Room	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Marks on wall



📅 2024-04-30 11:11:25

[360 Viewer](#)



Wall/Ceiling

📅 2024-04-30 10:34:37

[Image](#)



Wall/Ceiling

📅 2024-04-30 10:34:42

[Image](#)



Wall/Ceiling

📅 2024-04-30 10:34:47

[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:34:53
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:37:06
[Image](#)

📖 Garage/Parking	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Driveway/Floor	- S - -	None	
Garage Door	- S - -	None	
Light Fixture	- S - -	None	
Other	- S - -	None	
Walls/Ceiling	- - - !	Maintenance	Marks/scratches on wall



📅 2024-04-30 11:12:14
[360 Viewer](#)



Walls/Ceiling
 📅 2024-04-30 10:36:12
[Image](#)



Walls/Ceiling
 📅 2024-04-30 10:36:19
[🖼️ Image](#)



Walls/Ceiling
 📅 2024-04-30 10:36:22
[🖼️ Image](#)



Walls/Ceiling
 📅 2024-04-30 10:36:31
[🖼️ Image](#)



Walls/Ceiling
 📅 2024-04-30 10:36:39
[🖼️ Image](#)

📖 Bathroom: Primary	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Door/Knob/Lock	- - - !	Maintenance	Scratched door frame
Exhaust Fan	- S - -	None	
Flooring/Baseboard	- - - !	Maintenance	Wood paneling separating
Light Fixture	- S - -	None	
Sink/Faucet	- S - -	None	
Toilet	- S - -	None	
Tub/Shower	- - - !	Maintenance	Dirty bath tub
Wall/Ceiling	- - - !	Maintenance	Scratches on wall, aging on mirror



📅 2024-04-30 11:06:44

[360 Viewer](#)



Door/Knob/Lock

📅 2024-04-30 10:26:11

[Image](#)



Door/Knob/Lock

📅 2024-04-30 10:26:16

[Image](#)



Flooring/Baseboard

📅 2024-04-30 11:06:50

[Image](#)



Flooring/Baseboard

📅 2024-04-30 11:07:04

[Image](#)



Tub/Shower

📅 2024-04-30 10:26:01

[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:25:00
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:25:07
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:25:42
[🖼️ Image](#)

🏠 Bathroom 2: Full bath upstairs

	🔧 CONDITION	⚡ ACTION	💬 COMMENTS
Door/Knob/Lock	- S - -	None	
Exhaust Fan	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Sink/Faucet	- S - -	None	
Toilet	- S - -	None	
Tub/Shower	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Aging on mirror, bent towel holder, holes in wall



📅 2024-04-30 11:15:42

[360 Viewer](#)



Wall/Ceiling

📅 2024-04-30 10:40:41

[Image](#)



Wall/Ceiling

📅 2024-04-30 10:40:46

[Image](#)



Wall/Ceiling

📅 2024-04-30 10:40:51

[Image](#)



Wall/Ceiling

📅 2024-04-30 10:41:22

[Image](#)

🏠 Bathroom 3: Half Bath	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Door/Knob/Lock	- S - -	None	
Exhaust Fan	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	

 Bathroom 3: Half Bath	 CONDITION	 ACTION	 COMMENTS
Sink/Faucet	- S - -	None	
Toilet	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Scratches, marks on wall



 2024-04-30 11:05:15

 [360 Viewer](#)



Wall/Ceiling

 2024-04-30 10:22:00

 [Image](#)



Wall/Ceiling

 2024-04-30 10:22:04

 [Image](#)



Wall/Ceiling

 2024-04-30 10:22:09

 [Image](#)

 Hallway/Stairs	 CONDITION	 ACTION	 COMMENTS
Flooring/Baseboard	- - - !	Maintenance	Missing pieces of wood flooring
Light Fixture	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Scratches and marks on wall, broken outlet cover



📅 2024-04-30 11:04:25

[360 Viewer](#)



📅 2024-04-30 11:04:45

[360 Viewer](#)



📅 2024-04-30 11:13:25

[360 Viewer](#)



📅 2024-04-30 11:14:10

[360 Viewer](#)



Flooring/Baseboard
📅 2024-04-30 10:22:42

[Image](#)



Flooring/Baseboard
📅 2024-04-30 10:31:39

[Image](#)



Flooring/Baseboard
📅 2024-04-30 10:31:44

[Image](#)



Wall/Ceiling
📅 2024-04-30 10:20:50

[Image](#)



Wall/Ceiling
📅 2024-04-30 10:20:56
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:21:11
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:21:28
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:21:37
[🖼️ Image](#)




Wall/Ceiling
📅 2024-04-30 10:26:39
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:26:55
[🖼️ Image](#)



2024-04-30 10:37:31 CDT
Wall/Ceiling
📅 2024-04-30 10:37:31
[Image](#)



2024-04-30 10:37:39 CDT
Wall/Ceiling
📅 2024-04-30 10:37:39
[Image](#)



2024-04-30 10:37:46 CDT
Wall/Ceiling
📅 2024-04-30 10:37:46
[Image](#)



2024-04-30 10:46:16 CDT
Wall/Ceiling
📅 2024-04-30 10:46:16
[Image](#)



2024-04-30 10:46:19 CDT
Wall/Ceiling
📅 2024-04-30 10:46:19
[Image](#)



2024-04-30 10:46:26 CDT
Wall/Ceiling
📅 2024-04-30 10:46:26
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:46:31
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:46:39
[🖼️ Image](#)

📖 Family Room	📌 CONDITION	⚡ ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Light fixture/ Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Scratches on wall, marks, outlet cover drawn on
Window/Lock/Screen	- - - !	Maintenance	Blinds string damaged



📅 2024-04-30 11:14:35
[🌐 360 Viewer](#)



Wall/Ceiling
 📅 2024-04-30 10:38:13
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:38:19
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:38:29
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:38:59
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:39:07
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:39:27
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:39:32
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:39:40
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:39:45
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:39:52
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:40:00
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:40:06
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:40:11
[🖼️ Image](#)



2024-04-30 10:38:45 CDT

Window/Lock/Screen
 2024-04-30 10:38:45
[Image](#)

Bedroom: Primary	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- - - !	Maintenance	Marks on door and door frame
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Marks on wall, mismatching paint, Ethernet cable cover pulled out
Window/Lock/Screen	- S - -	None	



2024-04-30 11:06:10 CDT

2024-04-30 11:06:10
[360 Viewer](#)



2024-04-30 10:23:05 CDT

Door/Knob/Lock
 2024-04-30 10:23:05
[Image](#)



Door/Knob/Lock
📅 2024-04-30 10:23:08
[🖼️ Image](#)



Door/Knob/Lock
📅 2024-04-30 10:23:12
[🖼️ Image](#)




Door/Knob/Lock
📅 2024-04-30 10:24:30
[🖼️ Image](#)



Door/Knob/Lock
📅 2024-04-30 10:24:37
[🖼️ Image](#)



Door/Knob/Lock
📅 2024-04-30 10:24:44
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:23:27
[🖼️ Image](#)



2024-04-30 10:23:35 CDT
Wall/Ceiling
📅 2024-04-30 10:23:35
[🖼️ Image](#)



2024-04-30 10:23:48 CDT
Wall/Ceiling
📅 2024-04-30 10:23:48
[🖼️ Image](#)



2024-04-30 10:23:53 CDT
Wall/Ceiling
📅 2024-04-30 10:23:53
[🖼️ Image](#)



2024-04-30 10:23:58 CDT
Wall/Ceiling
📅 2024-04-30 10:23:58
[🖼️ Image](#)



2024-04-30 10:24:05 CDT
Wall/Ceiling
📅 2024-04-30 10:24:05
[🖼️ Image](#)



2024-04-30 10:24:10 CDT
Wall/Ceiling
📅 2024-04-30 10:24:10
[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:24:19
[Image](#)



Wall/Ceiling
 📅 2024-04-30 11:07:22
[Image](#)



Wall/Ceiling
 📅 2024-04-30 11:07:34
[Image](#)



Wall/Ceiling
 📅 2024-04-30 11:08:25
[Image](#)

📖 Bedroom 2: Right of stairs

	📌 CONDITION	⚡ ACTION	💬 COMMENTS
Closet/Door/Track/Shelving	- - - !	Maintenance	Marks on door and wall
Door/Knob/Lock	- - - !	Maintenance	Scratches on door and door frame
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Marks/holes in wall
Window/Lock/Screen	- S - -	None	



📅 2024-04-30 11:16:24
[360 Viewer](#)



Closet/Door/Track/Shelving
📅 2024-04-30 10:45:09
[Image](#)



Closet/Door/Track/Shelving
📅 2024-04-30 10:45:39
[Image](#)



Door/Knob/Lock
📅 2024-04-30 10:44:06
[Image](#)



Door/Knob/Lock
📅 2024-04-30 10:44:10
[Image](#)



Door/Knob/Lock
📅 2024-04-30 10:44:21
[Image](#)



Door/Knob/Lock
📅 2024-04-30 10:44:27
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:44:36
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:44:41
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:44:50
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:44:58
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:45:02
[Image](#)



2024-04-30 10:45:30 CDT
Wall/Ceiling
 📅 2024-04-30 10:45:30
[🖼️ Image](#)



2024-04-30 10:45:59 CDT
Wall/Ceiling
 📅 2024-04-30 10:45:59
[🖼️ Image](#)

🏠 Bedroom 3: Far right behind stairs

	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- - - !	Maintenance	Scratches/marks on door and door frame
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Marks on walls
Window/Lock/Screen	- S - -	None	



2024-04-30 11:17:00 CDT
 📅 2024-04-30 11:17:00
[🌐 360 Viewer](#)



2024-04-30 10:48:08 CDT
Door/Knob/Lock
 📅 2024-04-30 10:48:08
[🖼️ Image](#)



2024-04-30 10:48:14 CDT

Door/Knob/Lock

📅 2024-04-30 10:48:14

[🖼️ Image](#)



2024-04-30 10:48:19 CDT

Door/Knob/Lock

📅 2024-04-30 10:48:19

[🖼️ Image](#)



2024-04-30 10:48:24 CDT

Door/Knob/Lock

📅 2024-04-30 10:48:24

[🖼️ Image](#)



2024-04-30 10:48:29 CDT

Door/Knob/Lock

📅 2024-04-30 10:48:29

[🖼️ Image](#)



2024-04-30 10:48:42 CDT

Wall/Ceiling

📅 2024-04-30 10:48:42

[🖼️ Image](#)



2024-04-30 10:48:55 CDT

Wall/Ceiling

📅 2024-04-30 10:48:55

[🖼️ Image](#)



Wall/Ceiling
 📅 2024-04-30 10:49:05
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:49:10
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:49:18
[Image](#)



Wall/Ceiling
 📅 2024-04-30 10:49:23
[Image](#)

📖 Bedroom 4: In family room	📌 CONDITION	⚡ ACTION	💬 COMMENTS
Closet/Door/Track/Shelving	- - - !	Maintenance	Scratches on door
Door/Knob/Lock	- - - !	Maintenance	Scratches/marks on door and door frame
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Maintenance	Marks and scratches on wall, tacks
Window/Lock/Screen	- S - -	None	



📅 2024-04-30 11:14:57

[360 Viewer](#)



Closet/Door/Track/Shelving

📅 2024-04-30 10:51:26

[Image](#)



Closet/Door/Track/Shelving

📅 2024-04-30 10:51:32

[Image](#)



Door/Knob/Lock

📅 2024-04-30 10:52:00

[Image](#)



Door/Knob/Lock

📅 2024-04-30 10:52:05

[Image](#)




Door/Knob/Lock

📅 2024-04-30 10:52:12

[Image](#)



Door/Knob/Lock
📅 2024-04-30 10:52:17
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:09
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:16
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:24
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:28
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:32
[Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:36
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:40
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:44
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:49
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:53
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:50:59
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:51:03
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:51:07
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:51:12
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:51:42
[🖼️ Image](#)



Wall/Ceiling
📅 2024-04-30 10:51:50
[🖼️ Image](#)

📖 Systems	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Air Conditioning/Filter	- S - -	None	
Odor	- S - -	None	
Smoke Alarms	- - - !	Maintenance	Smoke detector hanging from ceiling.
Water Heater	- S - -	None	



Air Conditioning/Filter
📅 2024-04-30 10:47:20
[🖼️ Image](#)



Smoke Alarms
📅 2024-04-30 11:08:07
[🖼️ Image](#)



Water Heater
📅 2024-04-30 10:35:11
[🖼️ Image](#)

Additional Comments

Power was off at the time of inspection

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Inspector Signature

KJB

2024-05-01