

Move Out

Property	Tenant(s)	Date	Agent / Inspector
4326 Buckhorn Bayou		2023-12-05	Jesse Balderas

Move Out Condition Summary

 AREA	 DETAIL		 ACTION	 COMMENTS	 MEDIA
Front Yard/Exterior	Landscaping		Landscaping	Needs maintenance	 Image
Entry	Door/Knob/Lock	D	None	No doorbell	 Image
Entry	Flooring/Baseboard	D	None	Flooring damaged	 Image  Image  Image
Living Room	Flooring/Baseboard		Carpet Cleaning	Carpet cleaning	 Image  Image  Image
Living Room	Wall/Ceiling	D	None	Cleaning and repaint	 Image  Image
Dining Room	Dining Room		Cleaning	Cleaning/trash out needs	 Image  Image
Dining Room	Flooring/Baseboard		Cleaning	Trash out needed	 Image
Dining Room	Wall/Ceiling		Cleaning	Wall cleaning needed	 Image
Kitchen	Appliances	D	None	Deep clean needed	 Image  Image  Image  Image  Image
Kitchen	Cabinets/Drawers		Cleaning	Deep clean needed	 Image
Kitchen	Sink/Disposal		Cleaning	Cleaning needed	 Image  Image
Laundry Room	Flooring/Baseboard		Cleaning	Cleaning required, no door stop	 Image  Image  Image
Laundry Room	Wall/Ceiling	D	None	Repaint needed	 Image

 AREA	 DETAIL		 ACTION	 COMMENTS	 MEDIA
Garage/Parking	Driveway/Floor		Cleaning	Power wash needed, trash out	 Image  Image
Office	Wall/Ceiling	D	None	Will need repaint	 Image
Bathroom: Master	Sink/Faucet		Cleaning	Cleaning required	 Image  Image  Image
Bathroom: Master	Tub/Shower		Cleaning	Cleaning required	 Image
Bathroom: Master	Wall/Ceiling		Painting	Paint needed	 Image  Image  Image  Image  Image
Bathroom 2: Full bath upstairs	Other		Painting	Minor repaint	 Image
Bathroom 3: Half bath downstairs	Flooring/Baseboard		Cleaning	Cleaning required	 Image
Bathroom 3: Half bath downstairs	Toilet		Cleaning	Deep clean needed	 Image
Hallway/Stairs	Flooring/Baseboard		Carpet Cleaning	Stain remover needed	 Image  Image  Image
Hallway/Stairs	Wall/Ceiling	D	None	Repairs needed	 Image
Family Room	Flooring/Baseboard	D	None	Deep clean needed	 Image
Family Room	Wall/Ceiling	D	None	Repaint and minor repair	 Image  Image  Image
Bedroom: Master	Flooring/Baseboard		Carpet Cleaning	Carpet cleaning needed	 Image  Image  Image
Bedroom: Master	Wall/Ceiling		Painting	Will need matching paint	 Image  Image  Image  Image
Bedroom 3: End of hall	Wall/Ceiling	D	None	Will need repaint	 Image  Image
Systems	Odor		Carpet Cleaning	Will need deep clean	 Image  Image  Image

🔑 Move-Out Conditions

S=Satisfactory

D=Damaged

! - Action

📖 Front Yard/Exterior	🔑 CONDITION	✂ ACTION	💬 COMMENTS
Building Exterior	- S - -	None	
Landscaping	- - - !	Landscaping	Needs maintenance
Light Fixture	- S - -	None	
Walk/Driveway	- S - -	None	



Building Exterior
📅 2023-12-05 11:43:06
[🖼 Image](#)



Building Exterior
📅 2023-12-05 11:43:21
[🖼 Image](#)



Building Exterior
📅 2023-12-05 11:43:27
[🖼 Image](#)



Building Exterior
📅 2023-12-05 11:43:34
[🖼 Image](#)



Landscaping

📅 2023-12-05 11:43:45

[Image](#)

📖 Back Yard/Exterior	📍 CONDITION	🛠 ACTION	💬 COMMENTS
Building Exterior	- S - -	None	
Fence/Gate	- S - -	None	
Landscaping	- S - -	None	
Light Fixture	- S - -	None	
Patio/Deck/Balcony	- S - -	None	



Building Exterior

📅 2023-12-05 11:09:19

[Image](#)



Building Exterior

📅 2023-12-05 11:09:29

[Image](#)



Building Exterior
 📅 2023-12-05 11:10:22
[🖼️ Image](#)



Fence/Gate
 📅 2023-12-05 11:09:34
[🖼️ Image](#)



Fence/Gate
 📅 2023-12-05 11:09:43
[🖼️ Image](#)



Fence/Gate
 📅 2023-12-05 11:09:51
[🖼️ Image](#)



Fence/Gate
 📅 2023-12-05 11:10:00
[🖼️ Image](#)



Fence/Gate
 📅 2023-12-05 11:10:13
[🖼️ Image](#)

📖 Entry	📍 CONDITION	🛠️ ACTION	💬 COMMENTS
Door/Knob/Lock	- - D -	None	No doorbell
Doorbell	- S - -	None	
Flooring/Baseboard	- - D -	None	Flooring damaged
Front Porch	- S - -	None	

📖 Entry	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-12-05 10:51:07

[🌐 360 Viewer](#)



Door/Knob/Lock

📅 2023-12-05 10:49:01

[🖼️ Image](#)



Flooring/Baseboard

📅 2023-12-05 10:48:38

[🖼️ Image](#)



Flooring/Baseboard

📅 2023-12-05 10:48:41

[🖼️ Image](#)



Flooring/Baseboard

📅 2023-12-05 10:48:49

[🖼️ Image](#)

📖 Living Room	📍 CONDITION	🔧 ACTION	💬 COMMENTS
Fireplace	- S - -	None	

📖 Living Room	🔧 CONDITION	✂ ACTION	💬 COMMENTS
Flooring/Baseboard	- - - !	Carpet Cleaning	Carpet cleaning
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - D -	None	Cleaning and repaint
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



📅 2023-12-05 10:55:48

[🌐 360 Viewer](#)



📅 2023-12-05 10:56:25

[🌐 360 Viewer](#)



Flooring/Baseboard

📅 2023-12-05 10:55:32

[🖼 Image](#)



Flooring/Baseboard

📅 2023-12-05 10:55:34

[🖼 Image](#)



Flooring/Baseboard

📅 2023-12-05 10:55:35

[🖼 Image](#)



Wall/Ceiling

📅 2023-12-05 10:55:49

[🖼 Image](#)



Wall/Ceiling

2023-12-05 10:55:57

[Image](#)

Dining Room	CONDITION	ACTION	COMMENTS
Dining Room	- - - !	Cleaning	Cleaning/trash out needs
Flooring/Baseboard	- - - !	Cleaning	Trash out needed
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - - !	Cleaning	Wall cleaning needed
Window Covering	- S - -	None	
Window/Lock/Screen	- S - -	None	



2023-12-05 10:56:57

[360 Viewer](#)



Dining Room

2023-12-05 10:56:45

[Image](#)



Dining Room
 📅 2023-12-05 10:56:47
[🖼️ Image](#)




Flooring/Baseboard
 📅 2023-12-05 10:56:41
[🖼️ Image](#)



Wall/Ceiling
 📅 2023-12-05 10:57:05
[🖼️ Image](#)

📖 Kitchen	🔧 CONDITION	🛠️ ACTION	💬 COMMENTS
Appliances	- - D -	None	Deep clean needed
Cabinets/Drawers	- - - !	Cleaning	Deep clean needed
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Sink/Disposal	- - - !	Cleaning	Cleaning needed
Wall/Ceiling	- S - -	None	
Window/Lock/Screen	- S - -	None	



📅 2023-12-05 10:57:34
[🌐 360 Viewer](#)



📅 2023-12-05 10:58:13
[🌐 360 Viewer](#)



Appliances
📅 2023-12-05 10:57:22
[Image](#)



Appliances
📅 2023-12-05 10:57:24
[Image](#)



Appliances
📅 2023-12-05 10:57:28
[Image](#)



Appliances
📅 2023-12-05 10:57:29
[Image](#)




Appliances
📅 2023-12-05 10:57:36
[Image](#)



Cabinets/Drawers
📅 2023-12-05 10:58:02
[Image](#)



Sink/Disposal
 📅 2023-12-05 10:58:08
[🖼️ Image](#)



Sink/Disposal
 📅 2023-12-05 10:58:10
[🖼️ Image](#)


📖 Laundry Room	📍 CONDITION	✂️ ACTION	💬 COMMENTS
Flooring/Baseboard	- - - !	Cleaning	Cleaning required, no door stop
Light Fixture/Fan	- S - -	None	
Wall/Ceiling	- - D -	None	Repaint needed



📅 2023-12-05 10:52:28
[🌐 360 Viewer](#)



Flooring/Baseboard
 📅 2023-12-05 10:52:15
[🖼️ Image](#)



Flooring/Baseboard
 📅 2023-12-05 10:52:18
[🖼️ Image](#)



Flooring/Baseboard
 📅 2023-12-05 10:52:41
[🖼️ Image](#)



Wall/Ceiling

2023-12-05 10:52:29

[Image](#)

Garage/Parking	CONDITION	ACTION	COMMENTS
Driveway/Floor	- - - !	Cleaning	Power wash needed, trash out
Garage Door	- S - -	None	
Garage Door Opener	- S - -	None	
Light Fixture	- S - -	None	
Walls/Ceiling	- S - -	None	



2023-12-05 10:53:25

[360 Viewer](#)



2023-12-05 10:54:00

[360 Viewer](#)



Driveway/Floor

2023-12-05 10:53:06

[Image](#)



Driveway/Floor

2023-12-05 10:53:08

[Image](#)

Office	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Over View	- S - -	None	
Switch/Outlet	- S - -	None	
Wall/Ceiling	- - D -	None	Will need repaint
Window Covering	- S - -	None	



2023-12-05 10:51:48

[360 Viewer](#)



Wall/Ceiling

2023-12-05 10:51:14

[Image](#)

Bathroom: Master	CONDITION	ACTION	COMMENTS
Door/Knob/Lock	- S - -	None	
Exhaust Fan	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Sink/Faucet	- - - !	Cleaning	Cleaning required
Toilet	- S - -	None	
Tub/Shower	- - - !	Cleaning	Cleaning required
Wall/Ceiling	- - - !	Painting	Paint needed




📅 2023-12-05 11:04:45
[🌐 360 Viewer](#)



Sink/Faucet
 📅 2023-12-05 11:03:35
[🖼️ Image](#)



Sink/Faucet
 📅 2023-12-05 11:03:37
[🖼️ Image](#)



Sink/Faucet
 📅 2023-12-05 11:03:39
[🖼️ Image](#)



Tub/Shower
 📅 2023-12-05 11:03:52
[🖼️ Image](#)



Wall/Ceiling
 📅 2023-12-05 11:04:08
[🖼️ Image](#)



Wall/Ceiling
 📅 2023-12-05 11:04:09
[Image](#)



Wall/Ceiling
 📅 2023-12-05 11:04:12
[Image](#)



Wall/Ceiling
 📅 2023-12-05 11:04:17
[Image](#)



Wall/Ceiling
 📅 2023-12-05 11:04:18
[Image](#)

📖 Bathroom 2: Full bath upstairs

	🔧 CONDITION	🔧 ACTION	💬 COMMENTS
Door/Knob/Lock	- S - -	None	
Exhaust Fan	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture	- S - -	None	
Other	- - - !	Painting	Minor repaint
Sink/Faucet	- S - -	None	
Toilet	- S - -	None	
Tub/Shower	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2023-12-05 11:06:23

[360 Viewer](#)



Other

📅 2023-12-05 11:06:41

[Image](#)

📖 Bathroom 3: Half bath downstairs

🔗 CONDITION

✂ ACTION

💬 COMMENTS

Door/Knob/Lock	- S - -	None	
Exhaust Fan	- S - -	None	
Flooring/Baseboard	- - - !	Cleaning	Cleaning required
Light Fixture	- S - -	None	
Sink/Faucet	- S - -	None	
Toilet	- - - !	Cleaning	Deep clean needed
Tub/Shower	- S - -	None	



📅 2023-12-05 10:54:32

[360 Viewer](#)



Flooring/Baseboard

📅 2023-12-05 10:54:41

[Image](#)



Toilet

📅 2023-12-05 10:54:20

[🖼️ Image](#)

📖 Hallway/Stairs	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- - - !	Carpet Cleaning	Stain remover needed
Light Fixture	- S - -	None	
Wall/Ceiling	- - D -	None	Repairs needed




📅 2023-12-05 10:55:16

[🌐 360 Viewer](#)



📅 2023-12-05 10:58:54

[🌐 360 Viewer](#)



📅 2023-12-05 11:05:43

[🌐 360 Viewer](#)



📅 2023-12-05 11:06:02

[🌐 360 Viewer](#)



Flooring/Baseboard
 📅 2023-12-05 10:58:52
[Image](#)



Flooring/Baseboard
 📅 2023-12-05 10:58:53
[Image](#)



Flooring/Baseboard
 📅 2023-12-05 10:58:58
[Image](#)



Wall/Ceiling
 📅 2023-12-05 10:59:07
[Image](#)

📖 Family Room	📍 CONDITION	🛠 ACTION	💬 COMMENTS
Flooring/Baseboard	- - D -	None	Deep clean needed
Light fixture/ Fan	- S - -	None	
Wall/Ceiling	- - D -	None	Repaint and minor repair
Window/Lock/Screen	- S - -	None	




📅 2023-12-05 10:59:47
[360 Viewer](#)




📅 2023-12-05 11:00:14
[360 Viewer](#)



Flooring/Baseboard
 2023-12-05 10:59:34
[Image](#)



Wall/Ceiling
 2023-12-05 10:59:52
[Image](#)



Wall/Ceiling
 2023-12-05 11:00:08
[Image](#)



Wall/Ceiling
 2023-12-05 11:00:09
[Image](#)

Bedroom: Master	CONDITION	ACTION	COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- - - !	Carpet Cleaning	Carpet cleaning needed
Light Fixture/Fan	- S - -	None	
Smoke Detector	- S - -	None	
Wall/Ceiling	- - - !	Painting	Will need matching paint
Window/Lock/Screen	- S - -	None	



📅 2023-12-05 11:00:45

[360 Viewer](#)



📅 2023-12-05 11:01:08


[360 Viewer](#)



Flooring/Baseboard

📅 2023-12-05 11:01:13

[Image](#)



Flooring/Baseboard

📅 2023-12-05 11:01:17


[Image](#)



Flooring/Baseboard

📅 2023-12-05 11:01:18

[Image](#)



Wall/Ceiling

📅 2023-12-05 11:02:00

[Image](#)



Wall/Ceiling
 📅 2023-12-05 11:02:04
[🖼️ Image](#)



Wall/Ceiling
 📅 2023-12-05 11:02:07
[🖼️ Image](#)



Wall/Ceiling
 📅 2023-12-05 11:02:10
[🖼️ Image](#)

📖 Bedroom 2: Left hall	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Smoke Detector	- S - -	None	
Wall/Ceiling	- S - -	None	
Window/Lock/Screen	- S - -	None	



📅 2023-12-05 11:05:18

[360 Viewer](#)

📖 Bedroom 3: End of hall	📍 CONDITION	✂ ACTION	💬 COMMENTS
Closet/Door/Track/Shelving	- S - -	None	
Door/Knob/Lock	- S - -	None	
Flooring/Baseboard	- S - -	None	
Light Fixture/Fan	- S - -	None	
Smoke Detector	- S - -	None	
Wall/Ceiling	- - D -	None	Will need repaint
Window/Lock/Screen	- S - -	None	



📅 2023-12-05 11:08:03

[360 Viewer](#)



📅 2023-12-05 11:08:20

[360 Viewer](#)



Wall/Ceiling

📅 2023-12-05 11:07:35

[Image](#)



Wall/Ceiling

📅 2023-12-05 11:07:37

[Image](#)

 Systems	 CONDITION	 ACTION	 COMMENTS
Air Conditioning/Filter	- S - -	None	
Odor	- - - !	Carpet Cleaning	Will need deep clean
Smoke Alarms	- S - -	None	
Water Heater	- S - -	None	



Air Conditioning/Filter
 2023-12-05 11:06:54
 [Image](#)



Odor
 2023-12-05 11:08:44
 [Image](#)



Odor
 2023-12-05 11:08:46
 [Image](#)



Odor
 2023-12-05 11:08:51
 [Image](#)



Water Heater
 2023-12-05 10:53:23
 [Image](#)

Additional Comments

Entire home will need deep clean, repaint, minor repairs, refer to report for details

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Inspector SignatureA handwritten signature in black ink, consisting of a stylized 'M' followed by a horizontal line.

2023-12-05