



 <https://managerservices.pro/>
 Manager Services
 3002 Napier Park #101, Shavano Park, TX
78231
 210.888.0033

Move Out Inspection

Property	Date	Agent / Inspector
20313 Andalusite Way	2024-08-19	Josh Jordan

List!

General	- heavy maid service - item/trash removal - lawn service - touch up paint/patch holes as needed
Exterior	Na
Bedrooms	- replace missing blinds
Bathrooms	Na
Kitchen	- clean appliances
Laundry	Na
Living Areas	Na
Garage	Na
Notes	Na
Urgent Issues	***NO POWER AT PROPERTY***
LB Type, Code and Location	Permanent lb # 5 mounted on right side pillar of front porch Code: 9803

Front Yard/Exterior



Building Exterior
📅 2024-08-19 14:25:30
[🖼️ Image](#)



Building Exterior
📅 2024-08-19 14:25:37
[🖼️ Image](#)



Building Exterior
📅 2024-08-19 14:25:47
[🖼️ Image](#)

Back Yard/Exterior



Building Exterior
📅 2024-08-19 14:15:43
[🖼️ Image](#)



Fence/Gate
📅 2024-08-19 14:15:47
[🖼️ Image](#)



Fence/Gate
📅 2024-08-19 14:15:51
[Image](#)



Fence/Gate
📅 2024-08-19 14:15:54
[Image](#)




Fence/Gate
📅 2024-08-19 14:16:25
[Image](#)




Fence/Gate
📅 2024-08-19 14:16:37
[Image](#)



Fence/Gate
📅 2024-08-19 14:16:39
[Image](#)



Landscaping
📅 2024-08-19 14:15:11
[Image](#)



Landscaping
📅 2024-08-19 14:15:13
[🖼️ Image](#)



Landscaping
📅 2024-08-19 14:16:33
[🖼️ Image](#)

Entry



📅 2024-08-19 14:04:35
[🌐 360 Viewer](#)

Living Room



Other
📅 2024-08-19 14:11:03
[🖼️ Image](#)



Wall/Ceiling
📅 2024-08-19 14:11:09
[🖼️ Image](#)



Wall/Ceiling
📅 2024-08-19 14:11:20
[🖼️ Image](#)



Window Covering
📅 2024-08-19 14:11:27
[🖼️ Image](#)

Dining Room



📅 2024-08-19 14:05:02
[🌐 360 Viewer](#)

Kitchen



Appliances
📅 2024-08-19 14:11:39
[🖼️ Image](#)



Appliances
📅 2024-08-19 14:11:43
[🖼️ Image](#)



Appliances
📅 2024-08-19 14:11:47
[🖼️ Image](#)



Appliances
📅 2024-08-19 14:11:52
[🖼️ Image](#)



📅 2024-08-19 14:05:20
[🌐 360 Viewer](#)

Laundry Room



📅 2024-08-19 14:07:04
[🌐 360 Viewer](#)

Bathroom 1: Primary



📅 2024-08-19 14:10:05
[🌐 360 Viewer](#)

Bathroom 2:



📅 2024-08-19 14:08:02
[360 Viewer](#)

Hallway/Stairs



📅 2024-08-19 14:05:58
[360 Viewer](#)



Wall/Ceiling
📅 2024-08-19 14:12:35
[Image](#)

Bedroom 1: Primary




Flooring/Baseboard
📅 2024-08-19 14:14:50
[Image](#)



📅 2024-08-19 14:08:48
[360 Viewer](#)




📅 2024-08-19 14:09:30
[360 Viewer](#)




Wall/Ceiling
📅 2024-08-19 14:14:42
[Image](#)

Bedroom 2: Next to master



Flooring/Baseboard
📅 2024-08-19 14:13:45
[Image](#)



Flooring/Baseboard
📅 2024-08-19 14:13:54
[Image](#)



Flooring/Baseboard
📅 2024-08-19 14:13:57
[Image](#)




📅 2024-08-19 14:08:26
[360 Viewer](#)

Bedroom 3: Across from bathroom



📅 2024-08-19 14:07:31

[🌐 360 Viewer](#)



Wall/Ceiling

📅 2024-08-19 14:13:15

[🖼️ Image](#)

Systems



Water Heater

📅 2024-08-19 14:12:09

[🖼️ Image](#)