

Move Out Evaluation

Property: 124 Brookhaven Rd	Tenant(s):	Date: 2024-10-24	Evaluator: Jake Pye
--------------------------------	------------	---------------------	------------------------

Move-Out Conditions

S=Satisfactory

 Entry	 CONDITION	 ACTION	 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



 2024-10-24 09:30:03

 [Image](#)

 Front Yard/Exterior	 CONDITION	 ACTION	 COMMENTS
Building Exterior	- S - -	None	
Fence/Gate	- S - -	None	
Landscaping	- S - -	None	
Walk/Driveway	- S - -	None	



📅 2024-10-24 09:30:33

[Image](#)



📅 2024-10-24 09:30:36

[Image](#)

Bathroom: Master	🔧 CONDITION	🔧 ACTION	💬 COMMENTS
Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	



📅 2024-10-24 09:34:50

[Image](#)



📅 2024-10-24 09:34:58

[Image](#)



📅 2024-10-24 09:35:16

[Image](#)




📅 2024-10-24 09:35:19

[Image](#)



📅 2024-10-24 09:35:25

[🖼️ Image](#)



📅 2024-10-24 09:35:28

[🖼️ Image](#)

📖 Bathroom 2: Hall	📍 CONDITION	✂ ACTION	💬 COMMENTS
Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	



📅 2024-10-24 09:41:40

[🖼️ Image](#)



📅 2024-10-24 09:41:42

[🖼️ Image](#)



📅 2024-10-24 09:41:47

[🖼️ Image](#)



📅 2024-10-24 09:41:51

[🖼️ Image](#)

📖 Bathroom 3: Half	📍 CONDITION	✂ ACTION	💬 COMMENTS
Plumbing	- S - -	None	
Walls/Ceiling/Paint	- S - -	None	



📅 2024-10-24 09:29:01

[🖼️ Image](#)



📅 2024-10-24 09:29:03

[🖼️ Image](#)



📅 2024-10-24 09:29:06

[🖼️ Image](#)



📅 2024-10-24 09:29:09

[🖼️ Image](#)

📖 Bedroom: Master	📍 CONDITION	✂ ACTION	💬 COMMENTS
Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



📅 2024-10-24 09:34:18

[🖼️ Image](#)



📅 2024-10-24 09:34:31

[🖼️ Image](#)

📖 Bedroom 2: Left	📍 CONDITION	✂ ACTION	💬 COMMENTS
Flooring	- S - -	None	

📖 Bedroom 2: Left	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Walls / Ceiling / Paint	- S - -	None	



📅 2024-10-24 09:39:17
[🖼️ Image](#)



📅 2024-10-24 09:39:27
[🖼️ Image](#)

📖 Bedroom 3: Right	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring	- S - -	None	
Walls / Ceiling / Paint	- S - -	None	



📅 2024-10-24 09:37:17
[🖼️ Image](#)



📅 2024-10-24 09:37:29
[🖼️ Image](#)

📖 Dining Room	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2024-10-24 09:23:11

[🖼️ Image](#)



📅 2024-10-24 09:23:51

[🖼️ Image](#)

📖 Family Room	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2024-10-24 09:33:50


[🖼️ Image](#)



📅 2024-10-24 09:33:57

[🖼️ Image](#)

📖 Hallway/Stairs	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2024-10-24 09:33:05

[Image](#)

Kitchen	📌 CONDITION	🔧 ACTION	💬 COMMENTS
Appliances	- S - -	None	
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2024-10-24 09:18:59

[Image](#)



📅 2024-10-24 09:19:04

[Image](#)



📅 2024-10-24 09:19:07

[Image](#)



Appliances

📅 2024-10-24 09:20:56

[Image](#)



Appliances
📅 2024-10-24 09:21:05
[🖼️ Image](#)



Appliances
📅 2024-10-24 09:21:18
[🖼️ Image](#)




Appliances
📅 2024-10-24 09:21:38
[🖼️ Image](#)

📖 Laundry Room	🌡️ CONDITION	⚡ ACTION	💬 COMMENTS
Washer / Dryer / Hookups	- S - -	None	



📅 2024-10-24 09:36:50
[🖼️ Image](#)




📅 2024-10-24 09:36:52
[🖼️ Image](#)



📅 2024-10-24 09:37:00

 [Image](#)

📖 Living Room	📌 CONDITION	✂ ACTION	💬 COMMENTS
Flooring/Baseboard	- S - -	None	
Wall/Ceiling	- S - -	None	



📅 2024-10-24 09:22:56

 [Image](#)



📅 2024-10-24 09:22:58

 [Image](#)

📖 Back Yard/Exterior	📌 CONDITION	✂ ACTION	💬 COMMENTS
Landscaping	- S - -	None	
Other	- S - -	None	



📅 2024-10-24 09:25:10

[Image](#)



📅 2024-10-24 09:25:15

[Image](#)



📅 2024-10-24 09:25:17

[Image](#)



📅 2024-10-24 09:25:34

[Image](#)



📅 2024-10-24 09:25:47

[Image](#)



📅 2024-10-24 09:25:50

[Image](#)

Garage/Parking	CONDITION	ACTION	COMMENTS
Overall area	- S - -	None	



📅 2024-10-24 09:28:18


[🖼️ Image](#)



📅 2024-10-24 09:28:20

[🖼️ Image](#)

📖 Keys/Remotes/Devices	📌 CONDITION	✂ ACTION	💬 COMMENTS
Keys/fobs/devices	- S - -	None	



📅 2024-10-24 09:18:20

[🖼️ Image](#)

Additional Comments

Final Comments

Back yard has holes dug - need to be filled in as this is a trip hazard.
 Backyard needs items picked up and canopy cover reinstalled if it is not broken.
 Half bath has something splashed on the wall that need to be cleaned.
 Bedroom 2 has a rotted and torn window screen.
 Lite cleaning needed floors, countertops, sinks and toilets.

Tenant Signature	Evaluator Signature JCP#
------------------	-----------------------------