



# Employee Accident / Incident Report

Young & Sons Drywall, L.P.

08-13-2026

## 1. Project & Incident Information

JOB SITE

Cristo Rey Jesuit STEAM Building

JOB #

4066

GENERAL CONTRACTOR

Harvey Builders

DATE OF INCIDENT

08/13/2026

TIME OF INCIDENT

8:30 AM

INCIDENT LOCATION

Interior stairwell, job site

REPORT PREPARED BY

Jorge Vasquez – Safety Officer

FOREMAN

Antonio Rodriguez

REPORT DATE

August 13, 2026

## 2. Employee Information



### Elba Vasquez

Framer — Cristo Rey Jesuit STEAM Building crew

#### POSITION

Framer

#### REPORTS TO

Antonio Rodriguez,  
Foreman

## 3. Description of Incident

At approximately 8:30 AM, while descending the interior stairwell on the job site, Elba Vasquez's foot caught on a loose piece of banding/strap material left on the stairs, causing her to trip and fall, landing on her buttocks. The Safety Officer was notified and responded to the scene to assess the employee, document the incident, and photograph the tripping hazard.

## 4. Medical Response & Follow-Up

### Occucare Evaluation Offered

The employee was offered transport to Occucare for a medical evaluation following the fall.

### Employee Response

Elba Vasquez did not agree to go to Occucare today. She will go home to rest and will assess tomorrow whether she is able to return to work or needs to visit a clinic.

### Action Taken

The employee's request was granted; she left the job site to go home and rest for the remainder of the day. She will follow up regarding her ability to return to work tomorrow or the need for a clinic visit. No further medical treatment was administered on site.

## 5. Photo Documentation

### Incident Location

Stairwell where Elba Vasquez tripped while descending, and the immediate area of the fall.



Fig. 1 – Stairwell, incident location



Fig. 2 – Area where the employee fell

### Tripping Hazard

Banding/strap material identified as what the employee tripped on.





Fig. 3 – Banding material on the stairs

## 6. Signatures

### Injured Employee

Acknowledges the information above accurately reflects the incident.

PRINTED NAME

Elba Vasquez

DATE

MM/DD/YYYY

### Safety Officer

Prepared and verified this report.

PRINTED NAME

Jorge Vasquez

DATE

MM/DD/YYYY

## Foreman

Acknowledges this incident on the crew.

PRINTED NAME

Antonio Rodriguez

DATE

MM/DD/YYYY

**YOUNG & SONS DRYWALL, L.P. – JOB #4066 – CRISTO REY JESUIT STEAM BUILDING – 08-13-2026**

Prepared by Jorge Vasquez, Safety Officer