

INTERCHANGE DAMAGE REPORT

V.I.N.	1 2 P 3 4 0 9 5										
MODEL	FURGONATO					CAR MAKE	PEUGEOT				
CUSTOMER	GMV					GROUP CODE	A B				
DESTINATION	PALERMO										

STICKER BAR CODE
AREA

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16																17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36															

1				2				3				4			
DAMAGE	COMPONENT	SEVERITY	ALLOCATION	DAMAGE	COMPONENT	SEVERITY	ALLOCATION	DAMAGE	COMPONENT	SEVERITY	ALLOCATION	DAMAGE	COMPONENT	SEVERITY	ALLOCATION
M 121	/			KIT ASSISTENZA + KIT PORTA TARGHE											
M 045	/														
MODE OF ARRIVAL															
DELIVERING CARRIER (name)				CONSORZIO FREE SERVICE											
TRUCK /SHIP/WAGON				DR440 FE											
POSITION															
SIGNATURE															
NAME (PRINT)				ADRIANO MUZIO											
RECEIVING CARRIER NAME				GMV											
NAME OF SURVEYOR				STEFANO PIERANGELO											
SIGNATURE															
DATE				08/04/21											