QUALITY & SAFETY INSPECTION REPORT: INSP-9890

Site: Kattupalli Shipyard Drydock | **Date:** 2026-09-07
Certified Auditor: Vikram Sengupta (Safety Officer)

Checklist Inspection Item	Evaluation	Inspector Remarks
Visual inspection of casing for hairline casting cracks	PASS	Zero defects detected under UV dye
Dynamic shaft runout balance check (<0.02mm)	PASS	Measured at 0.012mm TIR
Hydrostatic pressure containment hold (350 bar / 30 min)	PASS	Pressure maintained without drop
Mechanical seal leak rate within tolerance (<5 ml/h)	PASS	No visible dripping observed
Foundation anchor bolt torque verification (450 Nm)	PASS	Torqued and calibrated
Emergency automatic shutdown circuit trip response	PASS	Tripped in 180ms
Bearing vibration velocity RMS (<2.8 mm/s)	PASS	Normal

Deficiencies Identified: None reported. Equipment within operational envelope.
Corrective Actions: Proceed with commissioning
Next Scheduled Inspection: 2026-10-26