QUALITY & SAFETY INSPECTION REPORT: INSP-4571

Site: Kattupalli Shipyard Drydock | **Date:** 2026-01-27
Certified Auditor: Priya Sundaram (NDT Level III)

Checklist Inspection Item	Evaluation	Inspector Remarks
Visual inspection of casing for hairline casting cracks	PASS	Zero defects detected under UV dye
Dynamic shaft runout balance check (<0.02mm)	PASS	Measured at 0.012mm TIR
Hydrostatic pressure containment hold (350 bar / 30 min)	PASS	Pressure maintained without drop
Mechanical seal leak rate within tolerance (<5 ml/h)	PASS	No visible dripping observed

Deficiencies Identified: None reported. Equipment within operational envelope.
Corrective Actions: Proceed with commissioning
Next Scheduled Inspection: 2026-10-26