SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Mold Assessment Report

Prepared for: Carol Vinelli

Property: 308 E 72nd St, Unit 4D, New York, NY 10021

Assessor: Sample Assessor (SAMPLE NYS Mold Assessor License #SAMPLE-0000)

Widespread mold growth was observed beneath the wood flooring in the bedroom.

Containment: full containment recommended.

Moisture source: plumbing leak from the unit above.