SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Mold Assessment Report

Prepared for: Jane Example

Property: 429 E 52nd St, Apt 5C, New York, NY 10022

Assessment date: 10/29/2026

Assessor: Sample Assessor (SAMPLE NYS Mold Assessor License #SAMPLE-0000)

Room: Bathroom

Room dimensions: 8 ft x 6 ft, ceiling height 8 ft

Visible growth on a portion of the bathroom ceiling and on the drywall behind the vanity.

Affected area: 14 SF

Containment: limited containment at the vanity wall.

Post-remediation verification: by an independent licensed mold assessor; visual inspection, moisture readings at or below dry standard, and air samples comparable to outdoor.

This sample report is for software testing only.