SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Mold Assessment Report

Prepared for: Carol Vinelli

Property: 308 E 72nd St, Unit 4D, New York, NY 10021

Assessor: Sample Assessor (SAMPLE NYS Mold Assessor License #SAMPLE-0000)

Room: Bedroom

Room dimensions: 12 ft x 8 ft, ceiling height 8 ft

Visible growth on a portion of the bedroom floor.

Moisture source: radiator valve leak, repaired.

Post-remediation verification: by an independent licensed mold assessor; visual inspection, moisture readings at or below dry standard, and air samples comparable to outdoor.