SAMPLE - TEST FIXTURE - FICTIONAL MOLD REPORT - NOT A REAL ASSESSMENT

Water Damage Assessment

Prepared for: Carol Vinelli

Property: 308 E 72nd St, Unit 4D, New York, NY 10021

Loss type: Category 1 water, Class 2 (S500)

Affected area: 120 SF of wet wood flooring in the bedroom

Moisture readings: 28% at the bedroom floor; drying with 3 air movers and 1 dehumidifier.

No visible mold growth observed.