Marine Surveyors and Logistics
Draft Surveys - Cargo Inspection - Bunker Surveys
On/Off Hire Surveys - Petroleum Q&Q
Container & Cargo Damage

CONTAINER INSPECTION REPORT

MSL-CR

Report No.	2149-0302-2026
Reference	2149-0302-2026
Vessel	Container SEGU94299733
To	-
On behalf of	Master Marine
Inspection place	Warehouse No. 15 - Industrias Delmor S.A. Plant, Corinto, Nicaragua
Inspection date	February 03, 2026
Status	Approved