Marine Surveyors and Logistics
Draft Surveys - Cargo Inspection - Bunker Surveys
On/Off Hire Surveys - Petroleum Q&Q
Container & Cargo Damage

CONTAINER INSPECTION REPORT

MSL-CR

Report No.	2149-0302-2026
Reference	2149-0302-2026
Vessel	Container SEGU94299733
To	-
On behalf of	Master Marine
Inspection place	Warehouse No. 15 - Industrias Delmor S.A. Plant, Corinto, Nicaragua
Inspection date	February 03, 2026
Status	Approved

Marine Surveyor and Logistics

Draft Surveys - Cargo Inspection - Bunquer Surveys
On/Off Hire Surveys - Petroleum Q&Q
Container & Cargo Damage

40' Reefer

CERT **2149-0302-2026**

	2149-0302-2026				
Nº		INSP. PLACE	**Warehouse No. 15 - Industrias Delmor S.A. Plant, Corinto, Nicaragua**	VSL	**Container SEGU94299733**
B / L		CONT. PERSON	**Juan Carlos Gutierrez - Surveyor**	CONTAC D/TIME	**February 03, 2026**
	14693		**February 03, 2026** **February 03, 2026**		**February 05, 2026** **February 05, 2026**
SEALS		Init INSP. D/TIME	TO	Final INSP. D/TIME	TO
APPOINT.	**Inspection conducted on February 03 and February 05, 2026.**	ON BEHALF OF	**Master Marine**		
SHIPPERS	**Boston Agrex LLC**	CONSIG/NOTIFY	**Industrias Delmor S.A.**		

CONTAINER DESCRIPTION					CAUSE OF INSPECTION					
	20 FOOT	DRY	ISO TANK	✔ FCL	SEALS	BL	CUSTOMS	LEAKING	✔	STUFF / D
✔	40 FOOT	✔ REEFER	FLAT RACK	LCL	CHANGE SEALS		TRANSFER ✔	DAMAGE	✔	CONDITION

Detail of Cause (If necessary) **Temperature deviations, frost presence, abnormal odours, partial thawing evidence and possible cold chain disruption affecting frozen pork legs.**

Goods	Type of Package			Qty Of Packages	
Frozen pork leg shipment. Total cargo: 683 cartons. Packing: 4 frozen pork legs per carton. Original set point: -20 C.	✔ Carton	Drums	Bdls	1st **683**	**cartons**
				68	**cartons inspected/opened**
	Bags	Pallets	Crates	2nd	
				2	**cartons controlled thaw evaluation**
	Boxes	Bulk	Other	3rd	

Package & Marking Description

Container SEGU94299733 / Seal 14693

Goods Condition (According Inspector Observations)

At inspection, internal air temperature and product core temperatures were above recommended frozen storage standards. Frost was present in inspected cartons. Several sampled units showed rancid and acidic odours, yellow fat discoloration, partial muscle paleness and loss of typical frozen rigidity.

Details of damage / Shortage (if any) or inspection cause.

Inspection on February 03, 2026: reefer set point -18.0 C, internal air temperature -9.6 C, 68 cartons opened, at least two units evaluated per carton, random core temperature readings from 7 cartons with average product temperature -4.4 C. Seventeen cartons exhibited abnormal odours described as rancid and acidic. Controlled thaw evaluation on February 05, 2026: two cartons assessed; prior container air temperature -17.1 C. Carton 1 had 3 of 4 units with rancid/acidic odours and yellowing of fat tissue. Carton 2 had rancid/acidic odours in all units, yellow fat discoloration and partial muscle paleness.

Remarks

The container arrived and was discharged on December 30, 2025 and was transferred to Warehouse No. 15 within Delmor facility. The container remained sealed under seal number 14693. Cargo was floor-loaded without pallets. No temperature data logger was found inside the container and no container temperature reading was available upon plant arrival or discharge. All inspected units were returned to the same container, placed inside two plastic crates and secured under safeguard pending further instructions.

Conclution

The inspection confirms apparent temperature deviations and organoleptic deterioration in part of the sampled cargo. The evidence supports an apparent potential cold chain disruption affecting product integrity. The exact timing and location of the temperature deviation cannot be determined with the available evidence.

Link Picture

https://photos.app.goo.gl/rwJSRCBHAiJRYLyXA

COLLECTED DOCUMENTS		QUALITY		INSPECTED CONTAINER			TRANSFER TO CONTAINER	
B/L		✔	PACKING EXAMINATION	Manuf. Nº			Number	**SEGU94299733**
PACKING LIST			UN / STUFFED WITNESS	CSC Saf.Apr.			Manuf. Nº	
SHIPPING INVOICE		✔	VISUAL EXAMINATION	Max.gross weight		Kgs	CSC Saf.Apr.	
CARGO MANIFEST		✔	PRODUCT EXAMINATION	Tare		Kgs	Seal Nº	**14693**
COMMERCIAL INVOICE		✔	QUALITY DOCUMENTS	**GENERAL DETAILS**			Max.gross weight	Kgs
DELIVERY /RECEIVED RECORD			SANITARY CERTIFICATE	NEW COMMODITY			Tare	Kgs
NOTICE OF LOSS / DAMAGE			PHYTOSANITARY CERT.	USED COMMODITY			**SCOPE OF INSPECTION**	
INSURANCE POLICY			FACTORY CERTIFICATE	NET W.	**21,791.07 kg**	Kgs	100%	
OTHER			CERTIFICATE OF ORIGIN	GROSS W.		Kgs	✔ RANDOM	
								68 cartons selected and fully opened; at least 2 units evaluated per carton; random core temperature readings from 7 cartons.
				VOLUME		m3	Nº ITEMS	

Name and designation of all persons present at the Survey

Claudia Silva	**Assistant, Integrated Management System - Industrias Delmor S.A.**
Karla Miranda	**Internal Control Assistant - Industrias Delmor S.A.**
Juan Carlos Gutierrez	**Surveyor**

PABEL PEÑA

SURVEYOR NAME



MSL SURVEYOR SIGNATURE