

Scanned Incident Report

The following page is an embedded image intended for OCR/document AI testing.

WORKPLACE INCIDENT REPORT

Incident ID: INC-2026-045
Date: 22 August 2026
Location: Production Line 3
Reported By: Michael Joseph

Incident Summary:

A maintenance technician slipped on an oil spill while inspecting a conveyor belt. The employee suffered a minor wrist injury. No warning signs were present.

Immediate Actions:

- First aid provided
- Area isolated
- Oil spill cleaned
- Supervisor notified

Root Cause:

Oil leak from conveyor gearbox and delayed house keeping.

Corrective Actions:

- Repair gearbox
- Daily house keeping inspections
- Install spill warning signs
- Conduct safety refresher training

Risk Assessment:

Likelihood: Likely
Severity: Moderate
Risk Level: High