



# Battery Health Live Dashboard

State of Health (SoH)

79.35 %

↓ -20.65%

Internal Resistance (Average)

1.53  $\Omega$

 Maintenance Required


--- Predictive Maintenance Prognose ---

Remaining cycles until 80% SoH: approx. 0 Cycles

Estimated End Cycle: approx. 374


Remaining battery life:

## Capacity Loss (SoH Trend)




Shows how the State of Health (SoH) has evolved over discharge cycles. A downward trend indicates degradation.

## Internal Resistance Rise



Shows the average internal resistance over cycles. An increasing trend can indicate worsening battery health.

 CRITICAL ALERT: State of Health has dropped to 79.35%. Battery inspection required.