

SAMPLE DOCUMENT — Generated from fictitious data for demonstration only. Not a real incident, claim, or filing.**Initial Crash Brief****Incident:** INC-2026-04-17-0042**Status:** evidence_capturing**Severity:** moderate**Reported (UTC):** 2026-04-17T14:32:18Z**Maintenance window:** last 90 days**Driver**

Name	Dorothy Gale
Phone	+15555550118
Driver ID	DRV-CABC-00318
Active	True

Driver Safety History

Incident	Created (UTC)	Status	Severity
INC-2025-09-02-0019	2025-09-02T18:11:00Z	closed	minor

Dispatch Instructions

Dispatch ID	DSP-2026-04-17-7781
Load #	L-778124
Dispatched By	Glinda Northman
Dispatched (UTC)	2026-04-17T05:42:00Z
Pickup Appt (UTC)	2026-04-17T08:00:00Z
Delivery Appt (UTC)	2026-04-17T17:30:00Z
ETA (UTC)	2026-04-17T17:05:00Z
Origin	Munchkinland Distribution Center, 4400 Yellow Brick Rd., Munchkinland, CA
Destination	Emerald City Logistics Hub, 9 Emerald Plaza, Emerald City, CA
HOS Drive Remaining (min)	410
HOS Duty Remaining (min)	530
Source	tms_sync
Notes	Standard dry-van run. No hazmat.

Tractor

Unit Number	4471
VIN	1FUJGLDR8CSBM4471
Provider	Samsara

SAMPLE DOCUMENT — Generated from fictitious data for demonstration only. Not a real incident, claim, or filing.

Trailer ID	TRL-CABC-22107
VIN	1JJV532D9NL022107
Make / Model	Wabash DuraPlate
Year	2022
Plate	CA 4Z 81293
Last Inspection	2026-03-28T09:14:00Z
Source	tms_sync

Loading Dock Reports

Loaded (UTC)	2026-04-17T07:48:00Z
Facility	Munchkinland DC
Facility Address	4400 Yellow Brick Rd., Munchkinland, CA
Commodity	Packaged consumer goods (palletized)
Pieces	22
Gross Weight (lb)	41280
Net Weight (lb)	28140
Seal #	S-447188
Securement	Load bars (3) + corner protectors
Weight Distribution	Heavier pallets staged over drive axles.
Loaded By	Boq Underhill
Dock Supervisor	Nessa Thropp
Source	tms_sync

Loading dock photos (2):

- dock_photo — captured (ART-DCK-7781-01)
- dock_photo — captured (ART-DCK-7781-02)

Weigh Station Reports

Weighed (UTC)	2026-04-17T11:14:00Z
Station	Cowardly Lion Scale House
Location	I-5 NB, mile marker 178, CA
Ticket #	WS-2026-1144789
Gross (lb)	71860
Steer Axle (lb)	11240
Drive Axle (lb)	33420

SAMPLE DOCUMENT — Generated from fictitious data for demonstration only. Not a real incident, claim, or filing.

Legal Limit (lb)	80000
Result	passed
Inspector	Insp. T. Mann
Source	manual_entry

Scanned ticket artifact: ART-WS-7781-01

Maintenance (last 90 days)

Performed (UTC)	Asset	Vendor	Summary	Mileage
2026-04-09T13:30:00Z	tractor: Unit 4471	Tin Man Diesel Service	B-service: oil & filter, brake adjustment, DOT inspection.	184220
2026-03-28T09:14:00Z	trailer: TRL-CABC-22107	Tin Man Diesel Service	Annual DOT trailer inspection, all brakes within spec.	—

ELD Logs (last 8 captured artifacts)

- eld_log_csv — captured (ART-ELD-7781-01)
- eld_log_pdf — captured (ART-ELD-7781-02)

Dashcam (Samsara)

- dashcam_forward_clip — [Open in Samsara](#)
- dashcam_inward_clip — [Open in Samsara](#)

Related events on this incident: 14