



Trip hazard on walkway

AI-assisted photographic hazard assessment · Bay 3

RISK LEVEL
MEDIUM

INCIDENT DETAILS

PLANT / UNIT Bokaro Steel Plant	DEPARTMENT Maintenance	LOCATION Bay 3	DATE & TIME 26 Sep 2026, 10:15
REPORTED BY ACME Safety Officer	PERSONNEL NO. -	OBSERVATION TYPE N/A	STATUS OPEN
REPORT TYPE AI Image Scan	WSA CATEGORY -	REFERENCE NO. INC-2026	PEOPLE INVOLVED 0

INCIDENT SUMMARY

Loose hoses across the walkway.

HAZARDS IDENTIFIED - 1 TOTAL

#	HAZARD	SEVERITY	DESCRIPTION	REGULATION	CORRECTIVE ACTION
1	Trip hazard	MEDIUM	Hoses on path.		

REPORTED BY ACME Safety Officer Reporting officer Signature & date	REVIEWED BY Safety Officer / HOD Name: Signature & date	APPROVED BY Plant Head / GM (Safety) Name: Signature & date
---	--	--

Generated by ACME Safety Lens. AI observations are advisory and subject to verification by the Safety Department before any finding is recorded.