



Loose item on bench


AI-assisted photographic hazard assessment · Conveyor C3

RISK LEVEL
LOW

INCIDENT DETAILS

PLANT / UNIT Rourkela Steel Plant	DEPARTMENT Safety	LOCATION Conveyor C3	DATE & TIME 03 Oct 2026, 11:48
REPORTED BY Audit	PERSONNEL NO. 1	OBSERVATION TYPE N/A	STATUS OPEN
REPORT TYPE AI Image Scan	WSA CATEGORY -	REFERENCE NO. AUDIT_TE	PEOPLE INVOLVED 0

EVIDENCE PHOTOGRAPH & INCIDENT SUMMARY



1 hazard(s) - 1 marked on photo

OVERALL RISK
LOW
AI confidence 80%

6 / 25
L3 × S2 (L est.)

SUMMARY
Worker near running conveyor without eye protection; a small exposed item on the left.

CLOSE-UP OF MARKED AREAS


Exposed sharp item

1
HAZARD

1
MARKED ON PHOTO

0
TO VERIFY

HAZARDS IDENTIFIED - 1 TOTAL

#	HAZARD	SEVERITY	DESCRIPTION	REGULATION	CORRECTIVE ACTION
1	Exposed sharp item	LOW	Small exposed item on the bench.	IS 14489	Remove.

REPORTED BY Audit P.No. 1 Signature & date	REVIEWED BY Safety Officer / HOD Name: Signature & date	APPROVED BY Plant Head / GM (Safety) Name: Signature & date
--	---	---

Generated by SAIL Safety Lens. AI observations are advisory and subject to verification by the Safety Department before any finding is recorded.