

Scaffold Hand Over

Company Address -	471 Kororoit Creek Road

Scaffold Hand Over Date	08-Jul-2025 10:26 AM
Scaffold Hand Over Certificate #	000040
Scaffold Owner (Client Name)	Qenos
Site	Olefins Plant
Building No.	OFFSITES
Location	AREA1
Floor Level	Ground Floor
Scaffold Tag #	000516
Scaffold/Section being Handed Over. Description	
Photo of Scaffold/Section to be handed over	
Scaffold Duty Rating	
Number of Working Decks	N/A
Max Number of Decks Loaded at one time	
Has this Scaffold been designed to be Encapsulated?	YES
Does this scaffold have an Engineered Design?	NO
Design Drawing No:	
Reason for Access	SV checks
Length (m)	
Width (m)	
Height TWP (m)	

Hand Over & Sign Off

Comments	dhzedb
Acknowledgement	The structure as described above, has now been completed and complies with Standards AS/NZS 1576 ALL PARTS, Scaffold Guidelines AS/NZS 4576 and any other applicable standards, guidelines or regulations. It is structurally sound and ready for use. The detailed requirements of the regulations with regard to guard-rails, working platforms, toe-boards, bracing and ties have been complied with. This structure has been inspected and tagged on completion of build. It must be inspected at minimum intervals of 30 days or at site interval requirements, whichever is the least number of days, since last inspection. It must also be inspected after any event likely to jeopardise the structures integrity , after part dismantle or any modification. Particulars of future inspections to be recorded in the inspection report. NO UNAUTHORIZED MODIFICATIONS OR ALTERATIONS ARE TO BE MADE TO THE STRUCTURE. ☑ I Agree
Scaffold Contractor Representative	Mick Dwyer
Licence to Perform High Risk Work #	123456
Scaffold Contractor Representative Position	Manager All Branches
Scaffold Contractor Representative Signature	
Scaffold Owner (Client) Representative	
Scaffold Owner (Client) Representative	ContractManager
Scaffold Owner (Client) Rep To Sign Here	