
Scaffold Hand Over

Company Address -	Hanson Rd

Scaffold Hand Over Date	17-May-2022 11:10 AM
Scaffold Hand Over Certificate #	000010
Scaffold Owner (Client Name)	owner DLF
Site	DLF Floor Site
Building No.	DLF Floor B-1
Floor Level	HeliDeck
Scaffold Tag #	000005
Scaffold/Section being Handed Over Description	
Photo of Scaffold/Section to be handed over	
Scaffold Duty Rating	Light
Number of Working Decks	N/A
Max Number of Decks Loaded at one time	
Has this Scaffold been designed to be Encapsulated?	YES
Does this scaffold have an Engineered Design?	
Design Drawing No:	
Reason for Access	
Length (m)	23.00
Width (m)	2.00
Height TWP (m)	23.00

Hand Over & Sign Off

Comments	comment
Acknowledgement	The structure as described above, has now been completed and complies with Standards AS/NZS 1576 ALL PARTS, Scaffold Guidelines AS/NZS 4576 and any other applicable standards, guidelines or regulations. It is structurally sound and ready for use. The detailed requirements of the regulations with regard to guard-rails, working platforms, toe-boards, bracing and ties have been complied with. This structure has been inspected and tagged on completion of build. It must be inspected at minimum intervals of 30 days or at site interval requirements, whichever is the least number of days, since last inspection. It must also be inspected after any event likely to jeopardise the structures integrity , after part dismantle or any modification. Particulars of future inspections to be recorded in the inspection report. NO UNAUTHORIZED MODIFICATIONS OR ALTERATIONS ARE TO BE MADE TO THE STRUCTURE. ☑ I Agree
Scaffold Contractor Representative	363
Licence to Perform High Risk Work #	25
Scaffold Contractor Representative Position	User
Scaffold Contractor Representative Signature	
Scaffold Owner (Client) Representative	Name
Scaffold Owner (Client) Representative Position	ContractManager
Scaffold Owner (Client) Rep To Sign Here	