

Drone Inspection

Wind turbine blade & solar panel defect analysis

Generated September 6, 2026 at 7:10 PM · 2 of 3 images analysed · models: gate gate.onnx, turbine turbine.onnx, solar solar.onnx

Moderate damage detected

0

Severe

2

Moderate

0

Minor

0


Clear

1

Rejected

0

Errors




turbine_red.png

Moderate damage · score 4.20

Wind turbine blade · 2 detections · gate 100%

- corrosion — 90.0%
- crack — 80.0%

No 'healthy' class by design: an image with no detections is the healthy result.




solar_blue.png

Moderate damage · score 3.85

Solar panel · 2 detections · gate 100%

- soiling — 85.0%
- missing_module — 75.0%

RGB only. Cannot detect hotspots, cell defects, bypass-diode failure or offline modules - those are electrical faults visible only in thermal infrared.



invalid_green.png

Please upload a valid turbine blade or solar panel image.

turbine 0% · solar 0% · invalid 100%

Inference runs locally with ONNX Runtime Web. Images are processed on your device and are never transmitted. Results are a screening aid, not a certified structural assessment — confirm findings before acting on them.