

WIND TURBINE INSPECTION REPORT

Autonomous Drone Inspection System

Inspection Date	24 June 2026
Turbine ID	TRB-001
Site	Wind Farm — Location TBC
Operator	DRONE EDUTRAIN LLC
Model Used	YOLOv8m — Defect Detection v1
Total Images	312

Overall Status: Moderate damage detected

5

Severe

66

Moderate

29

Minor wear

212

Healthy

Inspection Summary

#	Image	Defects Detected	Score	Status
1	Areial_Healthy358_jpg.rf.90cf7bf869...	None	0.0	No defects detected
2	259_jpg.rf.081ad309b23492e8a32df81c...	surface_peeling	1.29	Minor wear
3	838_jpg.rf.37ce3355ff5e427c21579c31...	crack	2.83	Moderate damage
4	Areial_Healthy411_jpg.rf.1ccce9475f...	None	0.0	No defects detected
5	89_jpg.rf.d79f8dd8d756a6eb057d208d4...	crack	4.64	Moderate damage
6	Healthy_Train7_jpg.rf.6d8dc5a6abf36...	None	0.0	No defects detected
7	Healthy_Train702_jpg.rf.a9772436414...	None	0.0	No defects detected
8	Healthy_Train42_jpg.rf.e5eafdaf5ff0...	None	0.0	No defects detected
9	Areial_Healthy844_jpg.rf.1c9a280683...	None	0.0	No defects detected
10	615_jpg.rf.c190fbf68271cc43b47e2df2...	crack	4.54	Moderate damage
11	252_jpg.rf.ff4834a1fbc83bc2d8bc36ca...	surface_peeling, crack	3.51	Moderate damage
12	Areial_Healthy402_jpg.rf.af28c6e5bd...	None	0.0	No defects detected
13	Healthy_Train1309_jpg.rf.7fff09999b...	None	0.0	No defects detected
14	Healthy_Train5_jpg.rf.fc429bb9e95af...	None	0.0	No defects detected
15	882_jpg.rf.02d2d3ded834a47178972505...	corrosion	2.27	Moderate damage
16	Healthy_Train518_jpg.rf.e45b7a5cd0a...	None	0.0	No defects detected
17	Areial_Healthy438_jpg.rf.9d003262ea...	None	0.0	No defects detected
18	582_jpg.rf.461894dea6de79ed41c33e8d...	crack	3.25	Moderate damage
19	Healthy_Train323_jpg.rf.1ec84ed8d74...	None	0.0	No defects detected
20	Healthy_Train939_jpg.rf.827de74e08f...	None	0.0	No defects detected
21	Areial_Healthy124_jpg.rf.975c03efa5...	None	0.0	No defects detected
22	Healthy_Train970_jpg.rf.f130dc48aa3...	None	0.0	No defects detected
23	Healthy_Train1248_jpg.rf.2578421d9b...	None	0.0	No defects detected
24	Healthy_Train653_jpg.rf.cc72ce2d7b7...	None	0.0	No defects detected
25	Areial_Healthy643_jpg.rf.14b79df49e...	None	0.0	No defects detected
26	Healthy_Train819_jpg.rf.f6ce07c3a7e...	None	0.0	No defects detected
27	Healthy_Train1394_jpg.rf.27e0dadef0...	None	0.0	No defects detected
28	Healthy_Train456_jpg.rf.72931c2c214...	None	0.0	No defects detected
29	Healthy_Train1244_jpg.rf.bea0d37c93...	None	0.0	No defects detected
30	873_jpg.rf.38c7240e4ab98b9b3b6d4972...	surface_peeling	1.08	Minor wear
31	1006_jpg.rf.6bf0d7ea8e3205f8cba24a8...	crack	2.06	Moderate damage

#	Image	Defects Detected	Score	Status
32	Healthy_Train1391_jpg.rf.3b143b5344...	None	0.0	No defects detected
33	1043_jpg.rf.629ecc948fc391175b036f8...	corrosion	1.39	Minor wear
34	Healthy_Train15_jpg.rf.fdb65ec0f95c...	None	0.0	No defects detected
35	Healthy_Train630_jpg.rf.7e6b38ce37e...	None	0.0	No defects detected
36	Healthy_Train954_jpg.rf.f81730fa435...	None	0.0	No defects detected
37	Healthy_Train23_jpg.rf.25aa4951fd53...	None	0.0	No defects detected
38	Healthy_Train725_jpg.rf.ae06c130f9b...	None	0.0	No defects detected
39	Areial_Healthy258_jpg.rf.96f237ae86...	None	0.0	No defects detected
40	Healthy_Train490_jpg.rf.2343c7ee4c0...	None	0.0	No defects detected
41	Healthy_Train191_jpg.rf.9dc7ed4d65e...	None	0.0	No defects detected
42	166_jpg.rf.6ac17179a30cefd5db529c...	crack	2.52	Moderate damage
43	117_jpg.rf.c4402f1a3fc75181b3b51026...	crack, corrosion	3.25	Moderate damage
44	Healthy_Train166_jpg.rf.4b266b7f05f...	None	0.0	No defects detected
45	139_jpg.rf.ca04b2d9950a452113d51716...	crack	7.73	Severe damage
46	908_jpg.rf.1627da4d4f716cbea7ff5aad...	crack	3.16	Moderate damage
47	Healthy_Train724_jpg.rf.43f01113a77...	None	0.0	No defects detected
48	648_jpg.rf.2d86b6e4728e1f2e6770c5cd...	surface_peeling, crack	3.11	Moderate damage
49	854_jpg.rf.d86cb7d756bd088f4441cf30...	crack	2.17	Moderate damage
50	Healthy_Train443_jpg.rf.4ed628ad872...	None	0.0	No defects detected
51	Healthy_Train561_jpg.rf.6f933517ca5...	None	0.0	No defects detected
52	209_jpg.rf.e4d5f11a36a6178c09861e84...	crack	3.42	Moderate damage
53	Healthy_Train305_jpg.rf.6a2154ddb91...	None	0.0	No defects detected
54	Healthy_Train816_jpg.rf.250bbf0a89d...	None	0.0	No defects detected
55	Areial_Healthy896_jpg.rf.a3c073be84...	None	0.0	No defects detected
56	745_jpg.rf.f9531ab214709dc89589142f...	surface_peeling	1.3	Minor wear
57	Healthy_Train412_jpg.rf.daae2374e0c...	None	0.0	No defects detected
58	Areial_Healthy758_jpg.rf.a344b3a553...	None	0.0	No defects detected
59	70_jpg.rf.84deaf062fe4f46868c974881...	crack	4.08	Moderate damage
60	Healthy_Train294_jpg.rf.4451e5b3cb8...	None	0.0	No defects detected
61	709_jpg.rf.866a0aa0b8bcf7675565fe68...	crack	3.06	Moderate damage
62	245_jpg.rf.2909bb8b2c99dcc263eba137...	surface_peeling	2.17	Moderate damage
63	199_jpg.rf.2bddb49bb4ed0b5ccd8cb154...	crack	2.33	Moderate damage

#	Image	Defects Detected	Score	Status
64	1031_jpg.rf.5ab049420bf9f1695386d45...	corrosion	0.74	Minor wear
65	Healthy_Train965_jpg.rf.f36a5a0090b...	None	0.0	No defects detected
66	312_jpg.rf.fe21e85e4d6f9be9f6a472f8...	crack	2.23	Moderate damage
67	Healthy_Train748_jpg.rf.4df173fe741...	None	0.0	No defects detected
68	Healthy_Train251_jpg.rf.577821906ea...	None	0.0	No defects detected
69	991_jpg.rf.dbe83641c895ae5a99552b6a...	crack	3.4	Moderate damage
70	Areial_Healthy314_jpg.rf.0fc9358117...	None	0.0	No defects detected
71	739_jpg.rf.6f75fa7eebce8c687facaf93...	crack	4.42	Moderate damage
72	894_jpg.rf.0ec6384c7f55b24238065357...	crack	2.07	Moderate damage
73	534_jpg.rf.b7b1bef6a1b566f4b073b27a...	crack	3.1	Moderate damage
74	Healthy_Train1331_jpg.rf.6c3967a318...	None	0.0	No defects detected
75	827_jpg.rf.ff91c808f2c0f901c1134226...	surface_peeling, crack	6.38	Severe damage
76	Areial_Healthy55_jpg.rf.3fb6a133c88...	None	0.0	No defects detected
77	Areial_Healthy75_jpg.rf.67a5b6cebc4...	None	0.0	No defects detected
78	Healthy_Train292_jpg.rf.6061eff26f3...	None	0.0	No defects detected
79	1013_jpg.rf.a9b058a46bc2d461925dbeb...	surface_peeling	1.13	Minor wear
80	98_jpg.rf.b236752272400f1e5f3d2dfba...	crack	2.57	Moderate damage
81	Healthy_Train206_jpg.rf.0d2fe1c7666...	None	0.0	No defects detected
82	Healthy_Train740_jpg.rf.4236bfbcb608...	None	0.0	No defects detected
83	642_jpg.rf.f7ec90245a222252376707b...	surface_peeling, crack	2.97	Moderate damage
84	679_jpg.rf.e7265cbd8b3bb23756887525...	crack	2.11	Moderate damage
85	Areial_Healthy230_jpg.rf.10b30d26fb...	None	0.0	No defects detected
86	Areial_Healthy815_jpg.rf.583134c00f...	None	0.0	No defects detected
87	Areial_Healthy110_jpg.rf.be6f5c72d3...	None	0.0	No defects detected
88	Healthy_Train238_jpg.rf.e1700d36a8c...	None	0.0	No defects detected
89	628_jpg.rf.a48c2d867c1875b076739701...	crack	3.77	Moderate damage
90	Areial_Healthy160_jpg.rf.36fad503f8...	None	0.0	No defects detected
91	Healthy_Train397_jpg.rf.5abbf4c5578...	None	0.0	No defects detected
92	Areial_Healthy34_jpg.rf.ce3f5833cb7...	None	0.0	No defects detected
93	865_jpg.rf.3407e64552aff8d89b28534e...	crack, corrosion	5.92	Severe damage
94	Healthy_Train1232_jpg.rf.718edd0f15...	None	0.0	No defects detected
95	Healthy_Train137_jpg.rf.2ba5c3c15ab...	None	0.0	No defects detected

#	Image	Defects Detected	Score	Status
96	Healthy_Train658_jpg.rf.7e4b12fae29...	None	0.0	No defects detected
97	Areial_Healthy908_jpg.rf.1d5f69f001...	None	0.0	No defects detected
98	289_jpg.rf.b87219b931b514f594d5f834...	crack, corrosion	2.72	Moderate damage
99	Healthy_Train1067_jpg.rf.1bc287ced4...	None	0.0	No defects detected
100	910_jpg.rf.bff73ed0e670ce758e6aaa14...	crack	2.32	Moderate damage
101	720_jpg.rf.10218bd55758b62fd855aa6b...	crack	1.84	Minor wear
102	404_jpg.rf.fb5382b62215eeb77f473474...	None	0.0	No defects detected
103	176_jpg.rf.84f24d19764b23660c459c98...	crack	3.22	Moderate damage
104	Healthy_Train786_jpg.rf.d82aac42cab...	None	0.0	No defects detected
105	Areial_Healthy663_jpg.rf.55522dd7b5...	None	0.0	No defects detected
106	Areial_Healthy819_jpg.rf.dab8f8f9f1...	None	0.0	No defects detected
107	Areial_Healthy404_jpg.rf.71e2728f20...	None	0.0	No defects detected
108	Healthy_Train1284_jpg.rf.0392ba9e0f...	None	0.0	No defects detected
109	Healthy_Train642_jpg.rf.6637417b142...	None	0.0	No defects detected
110	Areial_Healthy782_jpg.rf.a5c34fec69...	None	0.0	No defects detected
111	Healthy_Train562_jpg.rf.865e5ac1b2b...	None	0.0	No defects detected
112	234_jpg.rf.c2c27b72a5a3c7cc57472a0e...	surface_peeling, crack	5.47	Severe damage
113	Healthy_Train2_jpg.rf.c55d82954c480...	None	0.0	No defects detected
114	Healthy_Train529_jpg.rf.13c12a5419d...	None	0.0	No defects detected
115	1056_jpg.rf.b414b7c949a7dd1df56631b...	crack	2.11	Moderate damage
116	251_jpg.rf.9c9a8b8b2e5e118cb227f475...	crack	7.44	Severe damage
117	Healthy_Train503_jpg.rf.8028bf1b13b...	None	0.0	No defects detected
118	Healthy_Train491_jpg.rf.14c0255a88f...	None	0.0	No defects detected
119	Healthy_Train1396_jpg.rf.7a09368c2d...	None	0.0	No defects detected
120	Healthy_Train1102_jpg.rf.6707b17a09...	None	0.0	No defects detected
121	280_jpg.rf.7035274199fd750499c1dfc1...	None	0.0	No defects detected
122	27_jpg.rf.400cf30590ded4a832543145...	surface_peeling	1.85	Minor wear
123	Areial_Healthy914_jpg.rf.1a17d31a3e...	None	0.0	No defects detected
124	Healthy_Train1241_jpg.rf.ac802d6de0...	None	0.0	No defects detected
125	Healthy_Train628_jpg.rf.e7246ee14b9...	None	0.0	No defects detected
126	Healthy_Train1091_jpg.rf.3f635ffd60...	None	0.0	No defects detected
127	Healthy_Train1017_jpg.rf.2ef269907a...	None	0.0	No defects detected

#	Image	Defects Detected	Score	Status
128	Healthy_Train691_jpg.rf.0226c824a3f...	None	0.0	No defects detected
129	Healthy_Train224_jpg.rf.f17cf10c127...	None	0.0	No defects detected
130	750_jpg.rf.88a52df507c26ae968215c77...	surface_peeling	1.13	Minor wear
131	Healthy_Train525_jpg.rf.92f66684a27...	None	0.0	No defects detected
132	165_jpg.rf.57febbc56db351bd5b04e01c...	corrosion	2.42	Moderate damage
133	Healthy_Train547_jpg.rf.0c7dac39212...	None	0.0	No defects detected
134	Healthy_Train523_jpg.rf.fc1589d4d88...	None	0.0	No defects detected
135	Healthy_Train390_jpg.rf.7a69541405f...	None	0.0	No defects detected
136	Healthy_Train1037_jpg.rf.01e7cda2cd...	None	0.0	No defects detected
137	566_jpg.rf.fe37290058c2340ac76f18dd...	corrosion	1.43	Minor wear
138	Areial_Healthy301_jpg.rf.5706925b04...	None	0.0	No defects detected
139	248_jpg.rf.5ed7cecc9d6b7da72cb3c661...	corrosion	1.05	Minor wear
140	105_jpg.rf.dcaa68a4e5919b81d91c0a44...	surface_peeling	0.96	Minor wear
141	Areial_Healthy126_jpg.rf.ccf444bd15...	None	0.0	No defects detected
142	Healthy_Train245_jpg.rf.e7429491ee5...	None	0.0	No defects detected
143	517_jpg.rf.5982adcca64e086897c5b432...	None	0.0	No defects detected
144	Areial_Healthy845_jpg.rf.0d2256bad0...	None	0.0	No defects detected
145	Healthy_Train1137_jpg.rf.31e1d14aaa...	None	0.0	No defects detected
146	Areial_Healthy418_jpg.rf.62ffa1329e...	None	0.0	No defects detected
147	Areial_Healthy302_jpg.rf.c04dddee94...	None	0.0	No defects detected
148	Areial_Healthy468_jpg.rf.791eef30e6...	None	0.0	No defects detected
149	Areial_Healthy587_jpg.rf.6bedf65207...	None	0.0	No defects detected
150	1057_jpg.rf.30c3727d592b693867065b2...	crack	2.2	Moderate damage
151	848_jpg.rf.0a6d4a79caf30fb7853239c8...	crack	0.77	Minor wear
152	Areial_Healthy861_jpg.rf.98f22ff4e9...	None	0.0	No defects detected
153	Healthy_Train638_jpg.rf.e2163f6bffd...	None	0.0	No defects detected
154	970_jpg.rf.e0a5c24ca1528e1baaba787d...	crack	2.46	Moderate damage
155	Healthy_Train1237_jpg.rf.29d5d9cd8a...	None	0.0	No defects detected
156	803_jpg.rf.a532b2e16db4d55886a323ca...	crack	1.98	Minor wear
157	Healthy_Train614_jpg.rf.a6aa77ff674...	None	0.0	No defects detected
158	Healthy_Train1058_jpg.rf.5e73e68980...	None	0.0	No defects detected
159	Areial_Healthy712_jpg.rf.de36e2179e...	None	0.0	No defects detected

#	Image	Defects Detected	Score	Status
160	Areial_Healthy850_jpg.rf.2f584301e5...	None	0.0	No defects detected
161	Areial_Healthy642_jpg.rf.5b045946e7...	None	0.0	No defects detected
162	Healthy_Train255_jpg.rf.b32b5014676...	None	0.0	No defects detected
163	779_jpg.rf.25f7f25c4ec9ca548cf7867b...	crack	2.58	Moderate damage
164	Areial_Healthy497_jpg.rf.a5b4e238d8...	None	0.0	No defects detected
165	Areial_Healthy958_jpg.rf.ae79b5426c...	None	0.0	No defects detected
166	1018_jpg.rf.2a50b989ad94cb0b09df1c6...	surface_peeling	3.25	Moderate damage
167	Areial_Healthy96_jpg.rf.758fccccd289...	None	0.0	No defects detected
168	478_jpg.rf.0aea1336c6e6eaf2d6f42567...	None	0.0	No defects detected
169	Healthy_Train451_jpg.rf.5ca8183c5f5...	None	0.0	No defects detected
170	Areial_Healthy910_jpg.rf.edbf97e307...	None	0.0	No defects detected
171	753_jpg.rf.7551ed184731565da538da39...	crack	2.29	Moderate damage
172	Healthy_Train1141_jpg.rf.6cc04778a8...	None	0.0	No defects detected
173	Healthy_Train4_jpg.rf.b2d5384543660...	None	0.0	No defects detected
174	537_jpg.rf.6bdf7972c37208b6c35d2d8b...	crack	4.63	Moderate damage
175	Areial_Healthy557_jpg.rf.37cb85a919...	None	0.0	No defects detected
176	Healthy_Train135_jpg.rf.0c7f601bc4a...	None	0.0	No defects detected
177	522_jpg.rf.5b1403f9db04292a0bc32ed2...	surface_peeling	2.45	Moderate damage
178	Healthy_Train905_jpg.rf.885d4265c9d...	None	0.0	No defects detected
179	Areial_Healthy101_jpg.rf.b8d24f304c...	None	0.0	No defects detected
180	634_jpg.rf.79a2e02cb797bdb35c008bf8...	crack	1.83	Minor wear
181	55_jpg.rf.84c8deea5c9dc47eca9355b7b...	crack	2.34	Moderate damage
182	Areial_Healthy407_jpg.rf.d3352b2c8a...	None	0.0	No defects detected
183	391_jpg.rf.0b0ccee6b3c86d34ee8651ce...	crack	3.09	Moderate damage
184	Areial_Healthy412_jpg.rf.5bc4c3b05e...	None	0.0	No defects detected
185	Healthy_Train703_jpg.rf.d891d1b0895...	None	0.0	No defects detected
186	1021_jpg.rf.9062592d4958f20ad94b7f6...	crack	2.37	Moderate damage
187	Healthy_Train463_jpg.rf.165e4a35778...	None	0.0	No defects detected
188	Areial_Healthy851_jpg.rf.85d414e190...	None	0.0	No defects detected
189	Areial_Healthy488_jpg.rf.7a0ffc1df3...	None	0.0	No defects detected
190	730_jpg.rf.6079d6f0afbd0c904bb9d7e6...	crack	1.72	Minor wear
191	Healthy_Train1319_jpg.rf.84ef542c8a...	None	0.0	No defects detected

#	Image	Defects Detected	Score	Status
192	Areial_Healthy532_jpg.rf.5d17b90d19...	None	0.0	No defects detected
193	Healthy_Train468_jpg.rf.e75eafc39a1...	None	0.0	No defects detected
194	861_jpg.rf.097ad4aa0e32a31507752358...	crack	4.41	Moderate damage
195	Healthy_Train526_jpg.rf.901e5a2c345...	None	0.0	No defects detected
196	159_jpg.rf.8b21f1fddba3a967ed41ecf0...	crack	3.28	Moderate damage
197	456_jpg.rf.bcbcef2e238dad7c11af4c45...	crack	2.37	Moderate damage
198	345_jpg.rf.c61b3ebc44251ed4c9723938...	surface_peeling, crack	4.49	Moderate damage
199	Healthy_Train362_jpg.rf.7ffa7a281e8...	None	0.0	No defects detected
200	438_jpg.rf.70492997bd05caa85cb3e67c...	crack	1.44	Minor wear
201	Healthy_Train796_jpg.rf.95da49a4a2e...	None	0.0	No defects detected
202	Areial_Healthy97_jpg.rf.560fc841ce8...	None	0.0	No defects detected
203	Areial_Healthy691_jpg.rf.bb56321a7e...	None	0.0	No defects detected
204	Healthy_Train765_jpg.rf.50713e9f171...	None	0.0	No defects detected
205	786_jpg.rf.756ca6402cb541a04177eafb...	crack	2.03	Moderate damage
206	Healthy_Train549_jpg.rf.89d16c7c107...	None	0.0	No defects detected
207	Healthy_Train1369_jpg.rf.11826c744a...	None	0.0	No defects detected
208	565_jpg.rf.505dcbbebaee00387f203223...	crack	2.35	Moderate damage
209	Healthy_Train964_jpg.rf.ae6ddde94e6...	None	0.0	No defects detected
210	612_jpg.rf.4a9575dfb38a0c641cdf7878...	crack	2.12	Moderate damage
211	Areial_Healthy774_jpg.rf.5b41278714...	None	0.0	No defects detected
212	104_jpg.rf.2e3077bca01881ba7d4ba17d...	crack	2.6	Moderate damage
213	819_jpg.rf.842842ba6e497ade35dad543...	crack	2.17	Moderate damage
214	Areial_Healthy800_jpg.rf.e47814bd88...	None	0.0	No defects detected
215	572_jpg.rf.ad294dccc0c153a6ddfa3fd4...	crack	2.45	Moderate damage
216	440_jpg.rf.6de3ffab484fbe56e9e76cdb...	crack	2.72	Moderate damage
217	Healthy_Train598_jpg.rf.f6ff774582b...	None	0.0	No defects detected
218	Healthy_Train1317_jpg.rf.f5a1990428...	None	0.0	No defects detected
219	287_jpg.rf.3e7c936d3e52ee836638b2c4...	surface_peeling	1.39	Minor wear
220	Healthy_Train1247_jpg.rf.bfb8688a31...	None	0.0	No defects detected
221	Areial_Healthy515_jpg.rf.ad56216e79...	None	0.0	No defects detected
222	Areial_Healthy959_jpg.rf.f002852d84...	None	0.0	No defects detected
223	613_jpg.rf.f8f4fa4273fde851a8774384...	crack	3.05	Moderate damage

#	Image	Defects Detected	Score	Status
224	Areial_Healthy867_jpg.rf.fd330afae0...	None	0.0	No defects detected
225	Healthy_Train896_jpg.rf.607e61b5aa4...	None	0.0	No defects detected
226	Areial_Healthy12_jpg.rf.cb323dfc851...	None	0.0	No defects detected
227	Healthy_Train146_jpg.rf.b9ea4d0b10f...	None	0.0	No defects detected
228	Areial_Healthy698_jpg.rf.e97973f01f...	None	0.0	No defects detected
229	Healthy_Train1357_jpg.rf.f124a7242e...	None	0.0	No defects detected
230	531_jpg.rf.8bd202df6e16c08297c7a189...	crack	2.48	Moderate damage
231	60_jpg.rf.f8f556828b3bd1cdd627c5a69...	crack	4.16	Moderate damage
232	Healthy_Train198_jpg.rf.9d533c88d39...	None	0.0	No defects detected
233	427_jpg.rf.f2a1bce918b0c8cd4b78ccd7...	surface_peeling	0.48	Minor wear
234	304_jpg.rf.be788f16a8f1c530a4acedff...	crack	1.43	Minor wear
235	Areial_Healthy517_jpg.rf.f42b20dda6...	None	0.0	No defects detected
236	120_jpg.rf.a7f078c9ec36c8bcf2e78aed...	corrosion	1.03	Minor wear
237	Areial_Healthy1000_jpg.rf.861658095...	None	0.0	No defects detected
238	Healthy_Train427_jpg.rf.a1d7e7c1681...	None	0.0	No defects detected
239	Areial_Healthy505_jpg.rf.60efa3c5fb...	None	0.0	No defects detected
240	Areial_Healthy90_jpg.rf.8d08db6a50e...	None	0.0	No defects detected
241	121_jpg.rf.5e6feeed4099d6f689b25661...	crack	2.22	Moderate damage
242	Healthy_Train222_jpg.rf.1d061a8e7e3...	None	0.0	No defects detected
243	Healthy_Train158_jpg.rf.e84a1b2909f...	None	0.0	No defects detected
244	Healthy_Train776_jpg.rf.ef1ad5b11f0...	None	0.0	No defects detected
245	Areial_Healthy98_jpg.rf.ae16ae970dc...	None	0.0	No defects detected
246	Healthy_Train960_jpg.rf.9e0a6d93c29...	None	0.0	No defects detected
247	Healthy_Train590_jpg.rf.38921d5d283...	None	0.0	No defects detected
248	595_jpg.rf.17f5d3601e70a4ca29c21110...	surface_peeling, crack	3.27	Moderate damage
249	Healthy_Train584_jpg.rf.8d5bc1e30c5...	None	0.0	No defects detected
250	Healthy_Train1304_jpg.rf.7b97dd14e5...	None	0.0	No defects detected
251	Areial_Healthy87_jpg.rf.9a49f68808e...	None	0.0	No defects detected
252	Areial_Healthy604_jpg.rf.af620ae7a1...	None	0.0	No defects detected
253	Areial_Healthy388_jpg.rf.f4fd9c6e18...	None	0.0	No defects detected
254	618_jpg.rf.1878d31e066ba366e295a213...	crack	2.4	Moderate damage
255	Areial_Healthy65_jpg.rf.4d13bf4da30...	None	0.0	No defects detected

#	Image	Defects Detected	Score	Status
256	Healthy_Train235_jpg.rf.e86a28f6e74...	None	0.0	No defects detected
257	Healthy_Train270_jpg.rf.5cb4e069a17...	None	0.0	No defects detected
258	Healthy_Train667_jpg.rf.3a6577fdea1...	None	0.0	No defects detected
259	390_jpg.rf.373ad02a3ab116042c178ed2...	surface_peeling	0.79	Minor wear
260	Areial_Healthy538_jpg.rf.887a74f53f...	None	0.0	No defects detected
261	Healthy_Train309_jpg.rf.1c20552c6d3...	None	0.0	No defects detected
262	Healthy_Train499_jpg.rf.475b25ca03c...	crack	1.09	Minor wear
263	Healthy_Train230_jpg.rf.89befa117ba...	None	0.0	No defects detected
264	Healthy_Train1197_jpg.rf.a4e2fd5e2b...	None	0.0	No defects detected
265	Healthy_Train1216_jpg.rf.bccaa61c5d...	None	0.0	No defects detected
266	463_jpg.rf.cc217e5a7c912cd87820ee31...	crack	2.23	Moderate damage
267	588_jpg.rf.c7832364f0ff379b575b4210...	corrosion	0.92	Minor wear
268	718_jpg.rf.1268d71b307a54c2f9ef7384...	crack	2.56	Moderate damage
269	389_jpg.rf.777832f069d5da0b5299a55b...	crack	2.37	Moderate damage
270	162_jpg.rf.a9468bda2367593d8f1c546f...	surface_peeling, crack	1.62	Minor wear
271	Healthy_Train1079_jpg.rf.5554c7c8b4...	None	0.0	No defects detected
272	329_jpg.rf.45c807749a947a7eaa5db97c...	crack	3.12	Moderate damage
273	Healthy_Train1287_jpg.rf.6446ccc7f6...	None	0.0	No defects detected
274	316_jpg.rf.4a55d51cd22d82601aaea699...	crack	2.12	Moderate damage
275	Areial_Healthy375_jpg.rf.66e36f2a72...	None	0.0	No defects detected
276	Healthy_Train178_jpg.rf.eb559ba8380...	None	0.0	No defects detected
277	Healthy_Train751_jpg.rf.58a886159b8...	None	0.0	No defects detected
278	Healthy_Train328_jpg.rf.df2719e4731...	None	0.0	No defects detected
279	958_jpg.rf.b18561dc040b52b5db34408a...	crack	2.07	Moderate damage
280	Healthy_Train16_jpg.rf.aca2c7b0e894...	None	0.0	No defects detected
281	432_jpg.rf.9d73e841fcc724468ce465d0...	surface_peeling	0.94	Minor wear
282	Healthy_Train582_jpg.rf.e9b0caedbad...	None	0.0	No defects detected
283	Healthy_Train44_jpg.rf.42d69633f583...	crack	0.83	Minor wear
284	Healthy_Train1353_jpg.rf.3b2e6ef2c3...	None	0.0	No defects detected
285	Healthy_Train519_jpg.rf.086d782d942...	None	0.0	No defects detected
286	886_jpg.rf.309a886db30299969625ce69...	crack	2.37	Moderate damage
287	Healthy_Train532_jpg.rf.ddda27e52f5...	None	0.0	No defects detected

#	Image	Defects Detected	Score	Status
288	Healthy_Train1339_jpg.rf.35cf523003...	None	0.0	No defects detected
289	Healthy_Train708_jpg.rf.e2c697ecd32...	None	0.0	No defects detected
290	Healthy_Train145_jpg.rf.657c765eb25...	None	0.0	No defects detected
291	946_jpg.rf.d8ea32f2ccd70a95ae0b1d72...	crack	2.5	Moderate damage
292	Areial_Healthy309_jpg.rf.c2b99d8fcb...	None	0.0	No defects detected
293	Healthy_Train528_jpg.rf.540ed71d3bf...	None	0.0	No defects detected
294	Healthy_Train739_jpg.rf.8f24018b331...	None	0.0	No defects detected
295	Healthy_Train1329_jpg.rf.bbc93f91ea...	None	0.0	No defects detected
296	Areial_Healthy244_jpg.rf.2369238490...	None	0.0	No defects detected
297	Healthy_Train883_jpg.rf.d49111879b6...	None	0.0	No defects detected
298	Areial_Healthy702_jpg.rf.b0f53889dd...	None	0.0	No defects detected
299	Healthy_Train30_jpg.rf.df0e55a007a6...	None	0.0	No defects detected
300	Healthy_Train861_jpg.rf.a326cdf548...	None	0.0	No defects detected
301	Healthy_Train254_jpg.rf.070913eeb65...	None	0.0	No defects detected
302	Healthy_Train301_jpg.rf.527f86ad689...	None	0.0	No defects detected
303	2_jpg.rf.852b98d4d1e25f2add492c0eb5...	surface_peeling	0.98	Minor wear
304	Healthy_Train991_jpg.rf.5d3ff40c10a...	None	0.0	No defects detected
305	Areial_Healthy687_jpg.rf.041063eccd...	None	0.0	No defects detected
306	Healthy_Train304_jpg.rf.91134847866...	None	0.0	No defects detected
307	51_jpg.rf.05cd3db8515498bfc374db3ef...	crack	0.77	Minor wear
308	Healthy_Train148_jpg.rf.e82f8ec6026...	None	0.0	No defects detected
309	Areial_Healthy786_jpg.rf.8cea60dca2...	None	0.0	No defects detected
310	Areial_Healthy401_jpg.rf.46d24b3a74...	None	0.0	No defects detected
311	Healthy_Train605_jpg.rf.dcb8f6cfbc5...	None	0.0	No defects detected
312	Healthy_Train887_jpg.rf.75dc7c16dfd...	None	0.0	No defects detected




259_jpg.rf.081ad309b23492e8a32df81c073f0b58.j
pg

Score: 1.29 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	85.7%	(438, 152) -> (609, 227)



838_jpg.rf.37ce3355ff5e427c21579c31b61f2ace.jp
g

Score: 2.83 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	50.5%	(419, 207) -> (472, 483)
crack	44.0%	(408, 210) -> (496, 484)




89_jpg.rf.d79f8dd8d756a6eb057d208d43434fa1.jpg

Score: 4.64 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	86.2%	(230, 57) -> (378, 352)
crack	68.5%	(68, 194) -> (120, 409)




615_jpg.rf.c190fbf68271cc43b47e2df2355fc061.jpg

Score: 4.54 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	65.6%	(224, 156) -> (431, 587)
crack	56.5%	(227, 156) -> (357, 590)
crack	29.4%	(242, 24) -> (429, 621)




252_jpg.rf.ff4834a1fbc83bc2d8bc36cac58db224.jpg

Score: 3.51 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	85.7%	(288, 63) -> (350, 116)
surface_peeling	62.4%	(0, 478) -> (330, 640)



882_jpg.rf.02d2d3ded834a4717897250516e9b66d.
jpg

Score: 2.27 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
corrosion	64.4%	(1, 256) -> (435, 322)
corrosion	49.2%	(0, 256) -> (599, 325)



582_jpg.rf.461894dea6de79ed41c33e8d344e1325.jpg

Score: 3.25 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	75.0%	(320, 0) -> (428, 309)
crack	33.4%	(53, 142) -> (237, 379)




873_jpg.rf.38c7240e4ab98b9b3b6d4972f645fb8a.jpg

Score: 1.08 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	72.3%	(311, 320) -> (532, 470)



1006_jpg.rf.6bf0d7ea8e3205f8cba24a8738a711d5.jpg

Score: 2.06 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	68.5%	(22, 435) -> (147, 482)




1043_jpg.rf.629ecc948fc391175b036f808c48a6ce.
jpg

Score: 1.39 / 10

Minor wear

Defect Type	Confidence	Bounding Box
corrosion	69.4%	(32, 0) -> (375, 639)



166_jpg.rf.6ac17179a30cefdf25db529c5c09d98b.jpg

Score: 2.52 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	83.9%	(182, 188) -> (358, 256)



Defect Type	Confidence	Bounding Box
crack	79.0%	(231, 210) -> (639, 640)
corrosion	44.0%	(0, 140) -> (200, 639)




139_jpg.rf.ca04b2d9950a452113d51716dc5ca21a.jpg

Score: 7.73 / 10

Severe damage

Defect Type	Confidence	Bounding Box
crack	69.8%	(200, 203) -> (285, 286)
crack	62.8%	(265, 249) -> (376, 378)
crack	54.5%	(430, 450) -> (593, 640)
crack	41.5%	(310, 313) -> (431, 454)
crack	29.2%	(365, 380) -> (510, 575)



908_jpg.rf.1627da4d4f716cbea7ff5aadaa72da39.jpg

Score: 3.16 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	63.3%	(391, 407) -> (640, 590)
crack	42.1%	(391, 331) -> (640, 598)



648_jpg.rf.2d86b6e4728e1f2e6770c5cd25c3dd78.jpg

Score: 3.11 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	81.8%	(126, 252) -> (381, 424)
surface_peeling	43.6%	(345, 450) -> (392, 639)



854_jpg.rf.d86cb7d756bd088f4441cf30ad747ca3.jpg

Score: 2.17 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	72.3%	(354, 175) -> (443, 333)



209_jpg.rf.e4d5f11a36a6178c09861e843db34c56.jpg

Score: 3.42 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	76.8%	(0, 231) -> (306, 274)
crack	37.3%	(1, 218) -> (299, 282)



745_jpg.rf.f9531ab214709dc89589142f0683c28b.jpg

Score: 1.3 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	86.9%	(197, 70) -> (414, 350)



70_jpg.rf.84deaf062fe4f46868c97488147f2e0f.jpg

Score: 4.08 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	72.6%	(113, 138) -> (248, 360)
crack	63.5%	(322, 0) -> (424, 297)




709_jpg.rf.866a0aa0b8bcf7675565fe680db519e3.jpg

Score: 3.06 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	57.2%	(195, 189) -> (273, 487)
crack	44.8%	(214, 186) -> (270, 476)




245_jpg.rf.2909bb8b2c99dcc263eba1379a9f0e54.jpg

Score: 2.17 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
surface_peeling	73.3%	(130, 204) -> (387, 343)
surface_peeling	71.1%	(0, 255) -> (152, 478)




199_jpg.rf.2bddb49bb4ed0b5ccd8cb154536d5f22.jpg

Score: 2.33 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	77.5%	(321, 158) -> (404, 619)




1031_jpg.rf.5ab049420bf9f1695386d45975ca7a57.jpg

Score: 0.74 / 10

Minor wear

Defect Type	Confidence	Bounding Box
corrosion	37.2%	(294, 0) -> (456, 640)



Defect Type	Confidence	Bounding Box
crack	74.4%	(214, 0) -> (466, 351)



991_jpg.rf.dbe83641c895ae5a99552b6a366638b9.jpg

Score: 3.4 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	67.8%	(97, 81) -> (227, 199)
crack	45.6%	(124, 503) -> (388, 545)




739_jpg.rf.6f75fa7eebce8c687facaf93b43cb628.jpg

Score: 4.42 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	74.9%	(364, 45) -> (470, 148)
crack	72.3%	(72, 139) -> (187, 219)




894_jpg.rf.0ec6384c7f55b242380653570b3acc0c.jpg


Score: 2.07 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	68.9%	(167, 66) -> (354, 156)



Defect Type	Confidence	Bounding Box
crack	58.4%	(287, 472) -> (332, 626)
crack	45.1%	(287, 63) -> (406, 637)



827_jpg.rf.ff91c808f2c0f901c1134226070c3338.jpg

Score: 6.38 / 10

Severe damage

Defect Type	Confidence	Bounding Box
surface_peeling	82.0%	(207, 256) -> (346, 404)
crack	59.2%	(147, 49) -> (335, 194)
crack	56.0%	(318, 400) -> (427, 518)
crack	29.6%	(195, 211) -> (497, 326)
crack	27.0%	(134, 38) -> (335, 266)




1013_jpg.rf.a9b058a46bc2d461925dbebf3c1ee23
8.jpg

Score: 1.13 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	75.6%	(406, 330) -> (479, 374)



98_jpg.rf.b236752272400f1e5f3d2dfba9cdfa67.jpg

Score: 2.57 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	85.8%	(283, 381) -> (456, 446)



Defect Type	Confidence	Bounding Box
crack	74.5%	(288, 429) -> (544, 553)
surface_peeling	48.8%	(481, 1) -> (527, 87)



679_jpg.rf.e7265cbd8b3bb23756887525ff9ebb88.jpg

Score: 2.11 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	70.5%	(80, 142) -> (520, 405)



Defect Type	Confidence	Bounding Box
crack	54.2%	(119, 493) -> (393, 546)
crack	39.2%	(102, 171) -> (196, 199)
crack	32.4%	(92, 65) -> (224, 200)




865_jpg.rf.3407e64552aff8d89b28534ef875151c.jpg

Score: 5.92 / 10

Severe damage

Defect Type	Confidence	Bounding Box
corrosion	63.5%	(0, 285) -> (440, 364)
corrosion	63.3%	(1, 287) -> (290, 355)
corrosion	47.2%	(184, 287) -> (583, 370)
corrosion	34.4%	(0, 285) -> (581, 371)
crack	32.4%	(0, 204) -> (40, 286)
crack	26.1%	(0, 195) -> (43, 303)




289_jpg.rf.b87219b931b514f594d5f8345206c53f.jpg

Score: 2.72 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
corrosion	82.9%	(1, 336) -> (640, 640)
crack	35.3%	(28, 0) -> (640, 431)




910_jpg.rf.bff73ed0e670ce758e6aaa14b0e5ca2c.jpg

Score: 2.32 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	77.3%	(135, 282) -> (346, 540)



Defect Type	Confidence	Bounding Box
crack	31.5%	(282, 15) -> (358, 640)
crack	30.0%	(284, 28) -> (333, 640)




176_jpg.rf.84f24d19764b23660c459c98beb3b0c2.jpg

Score: 3.22 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	56.6%	(294, 73) -> (322, 222)
crack	50.6%	(220, 57) -> (254, 180)



234_jpg.rf.c2c27b72a5a3c7cc57472a0e5c855d2c.
jpg

Score: 5.47 / 10

Severe damage

Defect Type	Confidence	Bounding Box
crack	80.3%	(140, 27) -> (415, 269)
surface_peeling	74.4%	(201, 258) -> (349, 403)
crack	64.7%	(323, 420) -> (422, 514)




1056_jpg.rf.b414b7c949a7dd1df56631bec06c547
c.jpg


Score: 2.11 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	70.5%	(392, 378) -> (476, 551)



Defect Type	Confidence	Bounding Box
crack	85.1%	(277, 113) -> (488, 349)
crack	83.9%	(4, 301) -> (270, 552)
crack	79.0%	(478, 0) -> (640, 121)



27_jpg.rf.400fcf30590ded4a8325431458ece618.jpg

Score: 1.85 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	70.2%	(7, 105) -> (267, 299)
surface_peeling	53.1%	(253, 260) -> (478, 486)

surface_peeling 0.40;




750_jpg.rf.88a52df507c26ae968215c77cb76daca.jpg

Score: 1.13 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	39.7%	(18, 21) -> (384, 246)
surface_peeling	35.6%	(24, 26) -> (377, 132)



165_jpg.rf.57febbc56db351bd5b04e01c3b83cb60.
jpg

Score: 2.42 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
corrosion	67.4%	(133, 294) -> (516, 640)
corrosion	53.4%	(40, 1) -> (449, 631)



566_jpg.rf.fe37290058c2340ac76f18dd58628cdf.jpg

Score: 1.43 / 10

Minor wear

Defect Type	Confidence	Bounding Box
corrosion	71.5%	(223, 0) -> (406, 601)




248_jpg.rf.5ed7cecc9d6b7da72cb3c661f634d915.
jpg

Score: 1.05 / 10

Minor wear

Defect Type	Confidence	Bounding Box
corrosion	52.6%	(195, 0) -> (439, 630)



105_jpg.rf.dcaa68a4e5919b81d91c0a44a7a6546b.jpg

Score: 0.96 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	63.8%	(221, 287) -> (357, 521)




1057_jpg.rf.30c3727d592b693867065b27b6920417.jpg

Score: 2.2 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	73.2%	(291, 95) -> (352, 150)



Defect Type	Confidence	Bounding Box
crack	25.8%	(206, 19) -> (488, 563)




970_jpg.rf.e0a5c24ca1528e1baaba787d7d17f342.jpg


Score: 2.46 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	81.9%	(132, 372) -> (419, 574)



Defect Type	Confidence	Bounding Box
crack	66.0%	(336, 258) -> (411, 478)



779_jpg.rf.25f7f25c4ec9ca548cf7867b4150afc5.jpg

Score: 2.58 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	86.1%	(183, 188) -> (360, 256)



Defect Type	Confidence	Bounding Box
surface_peeling	82.1%	(338, 40) -> (442, 126)
surface_peeling	80.9%	(278, 290) -> (408, 401)
surface_peeling	53.9%	(275, 535) -> (349, 606)




753_jpg.rf.7551ed184731565da538da39c43c42ed.jpg

Score: 2.29 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	40.9%	(269, 51) -> (304, 321)
crack	35.4%	(252, 0) -> (639, 640)




537_jpg.rf.6bdf7972c37208b6c35d2d8bd5e8f815.jpg

Score: 4.63 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	86.2%	(339, 121) -> (480, 310)
crack	68.0%	(172, 212) -> (220, 351)




522_jpg.rf.5b1403f9db04292a0bc32ed234023919.jpg

Score: 2.45 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
surface_peeling	87.2%	(153, 0) -> (397, 229)
surface_peeling	76.4%	(14, 13) -> (123, 332)




634_jpg.rf.79a2e02cb797bdb35c008bf836be7013.jpg

Score: 1.83 / 10

Minor wear

Defect Type	Confidence	Bounding Box
crack	61.0%	(377, 5) -> (471, 640)




55_jpg.rf.84c8deea5c9dc47eca9355b7b4496c8c.jpg

Score: 2.34 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	78.0%	(305, 435) -> (576, 585)



Defect Type	Confidence	Bounding Box
crack	59.6%	(267, 0) -> (428, 583)
crack	43.5%	(250, 1) -> (427, 374)




1021_jpg.rf.9062592d4958f20ad94b7f69fb08a10e.jpg


Score: 2.37 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	79.1%	(65, 322) -> (412, 448)



Defect Type	Confidence	Bounding Box
crack	32.3%	(331, 33) -> (366, 189)
crack	25.1%	(324, 256) -> (383, 365)



861_jpg.rf.097ad4aa0e32a31507752358a15f2098.jpg

Score: 4.41 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	64.0%	(161, 23) -> (366, 290)
crack	46.0%	(388, 93) -> (494, 145)
crack	37.1%	(390, 113) -> (494, 144)



159_jpg.rf.8b21f1fddba3a967ed41ecf07e735b73.jpg

Score: 3.28 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	72.9%	(322, 89) -> (375, 271)
crack	36.3%	(53, 456) -> (111, 639)



456_jpg.rf.bcbcef2e238dad7c11af4c45951f03d2.jpg

Score: 2.37 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	45.6%	(239, 425) -> (264, 638)
crack	33.3%	(244, 46) -> (270, 375)



345_jpg.rf.c61b3ebc44251ed4c972393800083d95.jpg

Score: 4.49 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
surface_peeling	66.0%	(306, 540) -> (336, 566)
crack	55.7%	(287, 413) -> (301, 448)
crack	32.4%	(266, 190) -> (303, 397)
crack	28.7%	(276, 197) -> (303, 399)



438_jpg.rf.70492997bd05caa85cb3e67c61309061.
jpg

Score: 1.44 / 10

Minor wear

Defect Type	Confidence	Bounding Box
crack	48.1%	(134, 74) -> (622, 192)



Defect Type	Confidence	Bounding Box
crack	67.5%	(16, 238) -> (263, 322)



565_jpg.rf.505dcbbebaee00387f2032231dee66e9.jpg

Score: 2.35 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	78.5%	(228, 301) -> (472, 597)



612_jpg.rf.4a9575dfb38a0c641cdf7878f04125c7.jpg

Score: 2.12 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	70.7%	(7, 100) -> (513, 525)




104_jpg.rf.2e3077bca01881ba7d4ba17d84d3f3df.jpg


Score: 2.6 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	86.8%	(228, 232) -> (456, 447)



Defect Type	Confidence	Bounding Box
crack	72.2%	(103, 104) -> (388, 291)




572_jpg.rf.ad294dccd0c153a6ddfa3fd4b0720120.jpg

Score: 2.45 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	81.8%	(91, 10) -> (626, 370)



Defect Type	Confidence	Bounding Box
crack	34.2%	(1, 2) -> (262, 293)
crack	29.0%	(211, 232) -> (414, 526)
crack	27.5%	(165, 161) -> (414, 531)




287_jpg.rf.3e7c936d3e52ee836638b2c48c760b5f.jpg

Score: 1.39 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	92.4%	(0, 61) -> (210, 389)



Defect Type	Confidence	Bounding Box
crack	72.5%	(71, 66) -> (566, 626)
crack	29.3%	(110, 68) -> (565, 490)




531_jpg.rf.8bd202df6e16c08297c7a1899b9d561f.jpg

Score: 2.48 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	82.8%	(410, 97) -> (614, 514)



Defect Type	Confidence	Bounding Box
crack	72.8%	(42, 389) -> (243, 452)
crack	65.8%	(40, 361) -> (244, 454)



427_jpg.rf.f2a1bce918b0c8cd4b78ccd798c50f1f.jpg

Score: 0.48 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	32.3%	(221, 274) -> (335, 347)



Defect Type	Confidence	Bounding Box
crack	47.8%	(247, 254) -> (407, 560)



120_jpg.rf.a7f078c9ec36c8bcf2e78aedba739533.jpg

Score: 1.03 / 10

Minor wear

Defect Type	Confidence	Bounding Box
corrosion	51.7%	(303, 2) -> (428, 633)




121_jpg.rf.5e6feeed4099d6f689b25661f532b5cf.jpg

Score: 2.22 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	73.9%	(446, 0) -> (640, 152)



595_jpg.rf.17f5d3601e70a4ca29c21110fc76eb3c.jpg

Score: 3.27 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
surface_peeling	89.7%	(0, 255) -> (241, 484)
crack	64.2%	(210, 206) -> (561, 348)



618_jpg.rf.1878d31e066ba366e295a21342e088c0.
jpg

Score: 2.4 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	79.9%	(224, 244) -> (542, 540)




390_jpg.rf.373ad02a3ab116042c178ed21fe5cb31.jpg

Score: 0.79 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	52.6%	(78, 346) -> (218, 450)



Defect Type	Confidence	Bounding Box
crack	36.4%	(0, 172) -> (148, 640)



463_jpg.rf.cc217e5a7c912cd87820ee3153790208.jpg


Score: 2.23 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	74.5%	(116, 84) -> (216, 162)



Defect Type	Confidence	Bounding Box
corrosion	45.8%	(0, 42) -> (640, 365)



718_jpg.rf.1268d71b307a54c2f9ef73849ef84421.jpg

Score: 2.56 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	85.2%	(89, 189) -> (436, 391)



Defect Type	Confidence	Bounding Box
crack	78.9%	(487, 298) -> (547, 342)




162_jpg.rf.a9468bda2367593d8f1c546f027db3de.jpg

Score: 1.62 / 10

Minor wear

Defect Type	Confidence	Bounding Box
crack	36.4%	(122, 444) -> (200, 622)
surface_peeling	35.2%	(190, 0) -> (322, 640)



329_jpg.rf.45c807749a947a7eaa5db97c252c84a4.
jpg

Score: 3.12 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	44.8%	(366, 1) -> (439, 640)
crack	34.1%	(376, 3) -> (460, 640)
crack	25.1%	(366, 0) -> (429, 495)




316_jpg.rf.4a55d51cd22d82601aaea6994a81a876.
jpg

Score: 2.12 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	70.6%	(351, 176) -> (443, 334)



Defect Type	Confidence	Bounding Box
crack	69.0%	(180, 61) -> (437, 112)



432_jpg.rf.9d73e841fcc724468ce465d050fd5812.jpg


Score: 0.94 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	62.8%	(171, 315) -> (322, 526)



Defect Type	Confidence	Bounding Box
crack	27.7%	(483, 256) -> (640, 352)



886_jpg.rf.309a886db30299969625ce69d7dff3ae.jpg

Score: 2.37 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	79.1%	(198, 358) -> (622, 598)



946_jpg.rf.d8ea32f2ccd70a95ae0b1d72254ab58d.jpg

Score: 2.5 / 10

Moderate damage

Defect Type	Confidence	Bounding Box
crack	55.9%	(305, 275) -> (554, 312)
crack	27.6%	(303, 274) -> (556, 330)




2_jpg.rf.852b98d4d1e25f2add492c0eb5d35857.jpg

Score: 0.98 / 10

Minor wear

Defect Type	Confidence	Bounding Box
surface_peeling	65.0%	(311, 90) -> (372, 139)



Defect Type	Confidence	Bounding Box
crack	25.5%	(250, 0) -> (417, 600)