

carlytics

SUV · Diesel · 1.5L 1461cc

VIN: UU1HSDAWE54209393

Report fdbbf464 · 2026-08-10 · Lifetime access — this report never expires · carlytics.eu

Vehicle Specifications

MAKE DACIA	MODEL Duster	BODY TYPE SUV
FUEL Diesel	ENGINE 1.5L 1461cc	POWER 67 kW / 91 HP
TRANSMISSION Manual	DOORS 5	SEATS 5
WEIGHT 1264 kg	COUNTRY OF ORIGIN Romania	CYLINDERS 4
ASPIRATION Turbocharged		

Vehicle Identity

MARKET TRADE NAME DUSTER

Cross-Country Registration Trail

Registry records found in a single country only. —

Emissions & Fuel Economy

EMISSION STANDARD —	CO ₂ (WLTP) —	CO ₂ (NEDC) —
CO ₂ RATING BAND —	EST. ANNUAL CO ₂ —	NOX —
FUEL CONSUMPTION (COMBINED) 4 L/100km	FUEL CONSUMPTION (URBAN) —	FUEL CONSUMPTION (EXTRA-URBAN) —
FUEL TANK —	NOISE LEVEL —	

Real-World vs Official Emissions

OFFICIAL CO ₂ 135.2 g/km	REAL-WORLD CO ₂ (FLEET AVG.) 157.6 g/km	CO ₂ GAP +16.6%
OFFICIAL CONSUMPTION 5.02 L/100km	REAL-WORLD CONSUMPTION 5.97 L/100km	CONSUMPTION GAP +18.9%

Real-world figures are fleet averages measured on comparable vehicles under actual driving conditions.

Safety & History Checks

VIN Authenticity Verification		Check digit mismatch
Safety Recalls		25 recalls on record
DATE	RECALL	
2026-07-03	The rear suspension springs may not have been manufactured with the required dimensions, w	
2025-11-14	Vorschriftenabweichung RDKS	
2025-10-10	The position sensor of the parking brake actuator is at the wrong angle, causing the stopp	
2025-09-05	The position sensor of the parking brake actuator is at the wrong angle, causing the stopp	
2025-06-05	Verkabelung des ABS-Systems	
2025-04-18	Due to an inappropriate manufacturing process, the gasket seal between the solenoid valve	
2024-11-22	A decoupling of the R107 connector, which may not have been secured properly at the factor	
2024-11-15	Fehlerhafte Verkabelung	
2024-05-10	The left curtain airbags may be faulty. In the event of an accident, they may cause excess	
2024-02-08	Nicht konformer linker Windowbag kann sich im Falle eines Unfalls nicht wie vorgesehen ent	

Crash Test Safety Rating

Euro NCAP			★★★★★ — Average safety (2024)
ADULT OCCUPANT 69%	CHILD OCCUPANT 57%	PEDESTRIAN 57%	
SAFETY ASSIST 59%			

Wheels & Brakes

No wheel or brake specification on record for this variant. —

Standard Equipment

Engine	Cylinders: 4-cylinder · Aspiration: Turbocharged
Interior	Seats: 5 seats

Market Value

LOWER RANGE €3,800	ESTIMATED VALUE €4,800	UPPER RANGE €5,800
-----------------------	---------------------------	-----------------------

Similar Sale Listings

COMPARABLE LISTINGS 100	PRICE RANGE €0 – €5,650	MEDIAN ASKING €4,799			
VEHICLE	YEAR	FUEL	MILEAGE	PRICE	COUNTRY
Dacia Duster	2023	Diesel	66,765 km	€0	EE
Dacia Duster	2015	Diesel	52,000 km	€3,400	RO
Dacia Duster 1.5 dCi Laureate	2012	Diesel	175,000 km	€3,961	PL
Dacia Duster	2011	Diesel	160,023 km	€4,290	RO
Dacia Duster	2011	Diesel	199,000 km	€4,500	RO
Dacia Duster	2016	Diesel	290,000 km	€4,900	RO
Dacia Duster	2010	Diesel	299,999 km	€5,000	RO
Dacia Duster 1.5dci,ČR	2015	Diesel	136,156 km	€5,200	CZ
Dacia Duster	2012	Diesel	221,735 km	€5,490	RO
Dacia Duster	2012	Diesel	247,000 km	€5,650	RO

Listing Intelligence

No historic market-listing claims on record for this exact VIN. —

Fair Price Check

FAIR VALUE (LOW) €3,800	FAIR VALUE (MEDIAN) €4,800	FAIR VALUE (HIGH) €5,800
----------------------------	-------------------------------	-----------------------------

Compare the seller's asking price against this band: within ±5% of the median is a fair price; more than 15% above is above market value.

Depreciation Forecast

CURRENT ESTIMATE €18,100	IN 1 YEAR €16,300	IN 3 YEARS €13,300
IN 5 YEARS €10,900	ANNUAL DEPRECIATION 9.7%/year	CONFIDENCE high

Pre-Purchase Inspection Checklist

Exterior □ Walk around the car in daylight — look for dents, scratches, and rust spots □ Check that paint colour and finish match on every panel □ Inspect panel gaps — uneven gaps indicate poor bodywork or frame damage □ Open and close every door, the bonnet, and the boot — they should latch smoothly □ Look for chips or cracks in all glass □ Check all lights: headlights, tail lights, indicators, fog lights, and brake lights	Interior □ Sniff for musty or mouldy smell (signs of flood damage or water leaks) □ Check upholstery for tears, stains, and wear inconsistent with stated mileage □ Test all seat adjustments, mirrors, and window switches □ Verify A/C blows cold and heater blows hot — test every fan speed □ Check dashboard: no warning lights illuminated, all gauges functional □ Inspect under floor mats and in the boot for water stains, silt, or rust	Under the Hood □ Check engine oil level and colour — milky oil may indicate head-gasket failure □ Inspect coolant level and condition (no discolouration or oily residue) □ Look for visible fluid leaks under the car and around the engine bay □ Examine belts for cracks, fraying, or glazing □ Check hoses for brittleness, swelling, or soft spots □ Inspect battery terminals for corrosion
Test Drive □ Cold start: engine should fire up smoothly without excessive smoke or noise □ Accelerate onto a fast road — check for hesitation, misfires, or loss of power □ Brake firmly — pedal should feel solid, no pulsing, pulling, or grinding □ Drive at highway speed — no vibration in the steering wheel or seats □ Listen for unusual noises from suspension and drivetrain □ Transmission shifts smoothly through all gears; clutch engages cleanly	Documents □ Confirm the VIN on the dashboard and door jamb matches the registration document □ Verify the title is clean — not salvage, rebuilt, or flood-branded □ Check that the seller's name matches the registration certificate □ Review the full service booklet — regular stamps and consistent mileage entries	History Verification □ Run a VIN history check — compare mileage records against the odometer reading □ Check for open safety recalls that have not yet been remedied □ Verify accident and damage history against the seller's disclosure □ Confirm the car is not listed in any stolen-vehicle database □ Cross-check import history — know which countries the vehicle has been registered in

Print this checklist and bring it to your inspection.

Vehicle Timeline

DATE	EVENT	DETAIL
2026-07-03	Recall	The rear suspension springs may not have been manufactured with the required dim
2025-11-14	Recall	Vorschriftenabweichung RDKS
2025-10-10	Recall	The position sensor of the parking brake actuator is at the wrong angle, causing
2025-09-05	Recall	The position sensor of the parking brake actuator is at the wrong angle, causing
2025-06-05	Recall	Verkabelung des ABS-Systems
2025-04-18	Recall	Due to an inappropriate manufacturing process, the gasket seal between the solen
2024-11-22	Recall	A decoupling of the R107 connector, which may not have been secured properly at
2024-11-15	Recall	Fehlerhafte Verkabelung
2024-05-10	Recall	The left curtain airbags may be faulty. In the event of an accident, they may ca
2024-02-08	Recall	Nicht konformer linker Windowbag kann sich im Falle eines Unfalls nicht wie vorg
2023-11-10	Recall	Incorrect welding of the liquefied petroleum gas (LPG) tank may lead to the rele
2021-03-24	Recall	Überhitzung des Anlassers kann zum Fahrzeugbrand führen.
2021-01-29	Recall	The key may become blocked in the starting position, which could damage the vehi
2020-07-20	Recall	Fehlende Angabe des Zuggesamtgewichtes im Fahrzeugschein kann zu einer Überladun
2020-03-27	Recall	The frame of the rear seat may not be sufficiently strong. As a result, it wil
2020-02-04	Recall	Die Rückhaltekraft der Rücksitzbank hinsichtlich im Kofferraum befindlicher Gepä
2019-01-18	Recall	The positive terminal of the 12-volt battery, of the car is uncorrectly welded.
2019-01-11	Recall	Fehlerhafte Batterie kann zu Startschwierigkeiten führen.
2018-04-20	Recall	Incorrect contact may occur between the towing harness and the trailer coupling.
2018-04-06	Recall	A software problem could affect the stop-start system.
2018-03-23	Recall	Möglicher Ausfall der Anhängersignalanlage durch fehlerhaften Kabelstrang.
2018-02-16	Recall	Fehlerhafte Software des Motorsteuergeräts führt dazu, dass die Stop/Start Funkt
2017-10-04	Recall	Die Betätigung der Zweisignal-Hupe kann zur Auslösung des Airbags führen.
2017-09-21	Recall	Die Betätigung der Einsignal-Hupe kann zur Auslösung des Airbags führen.
2012-03-26	Recall	Bei Fahrten in tiefem Schnee oder Matsch können die hinteren Bremsschläuche besc

Mileage & Odometer History

Odometer Rollback Check	No anomaly detected
Typical Annual Mileage (this model)	11,726 km/year

No independent odometer readings on record for this vehicle. —

Stolen Vehicle Check

Result	Not reported stolen
--------	---------------------

VIN UU1HSDAWE54209393 was not found in any stolen-vehicle databases.

Cross-checked against 51,314 publicly disclosed stolen vehicles from European registries.

Aggregated from publicly available sources including press releases, EU open-data portals, and user-submitted reports. For legal verification, contact local law enforcement or your national vehicle registration authority.

Reliability & Breakdown Risk

Inspection Pass Rate	84%
Typical Mileage at Age 5	50,101 km

Known Issues

No recurring known-issue patterns on record for this model. —

Owner Complaints

No owner complaints on record for this model. —

Estimated Annual Running Cost

COST COMPONENT	PER YEAR (EST.)
Fuel	€1,050
Vehicle Tax (DE)	€143
Insurance (est.)	€500
Depreciation	€720
Total	€2,413

Technical Service Bulletins

No technical service bulletins found for this model. —

Diagnostic Trouble Codes

If you get an OBD-II scan during a pre-purchase inspection, these are the diagnostic trouble codes most commonly associated with DACIA. Cross-reference any codes the mechanic finds.

CODE	CATEGORY	DESCRIPTION
005	inspection-defect	Goedkeuringsdocument ontbreekt bij taxi of OV-voertuig
005	inspection-defect	Goedkeuringsdocument ontbreekt bij taxi of OV-voertuig
005	inspection-defect	Goedkeuringsdocument ontbreekt bij taxi of OV-voertuig
005	inspection-defect	Goedkeuringsdocument ontbreekt bij taxi of OV-voertuig
005	inspection-defect	Goedkeuringsdocument ontbreekt bij taxi of OV-voertuig
005	inspection-defect	Goedkeuringsdocument ontbreekt bij taxi of OV-voertuig
008	inspection-defect	VIN in kentekenregister wijkt af t.o.v. VIN in voertuig
008	inspection-defect	VIN in kentekenregister wijkt af t.o.v. VIN in voertuig
008	inspection-defect	VIN in kentekenregister wijkt af t.o.v. VIN in voertuig
008	inspection-defect	VIN in kentekenregister wijkt af t.o.v. VIN in voertuig
008	inspection-defect	VIN in kentekenregister wijkt af t.o.v. VIN in voertuig
008	inspection-defect	VIN in kentekenregister wijkt af t.o.v. VIN in voertuig
009	inspection-defect	VIN in voertuig is (gedeeltelijk) niet leesbaar/ontbreekt
009	inspection-defect	VIN in voertuig is (gedeeltelijk) niet leesbaar/ontbreekt
009	inspection-defect	VIN in voertuig is (gedeeltelijk) niet leesbaar/ontbreekt
009	inspection-defect	VIN in voertuig is (gedeeltelijk) niet leesbaar/ontbreekt
009	inspection-defect	VIN in voertuig is (gedeeltelijk) niet leesbaar/ontbreekt
009	inspection-defect	VIN in voertuig is (gedeeltelijk) niet leesbaar/ontbreekt
010	inspection-defect	Beoordelen keuringsaspect niet mogelijk
010	inspection-defect	Beoordelen keuringsaspect niet mogelijk

Inspection & Registration History

No registration or inspection history on record for this vehicle. —

Inspection history is sourced from national vehicle registries. Coverage varies by country and may not include all recorded inspections.

Maintenance Schedule (estimated)

ITEM	INTERVAL	STATUS
Air filter	30,000 km	OK Within interval
Brake fluid	50,000 km / 24 months	OK Within interval
Cabin filter	20,000 km / 24 months	OK Within interval
Coolant	120,000 km / 48 months	OK Within interval
Front brake pads	50,000 km	OK Within interval
Gearbox fluid	80,000 km	OK Within interval
Oil & filter change	15,000 km / 12 months	OK Within interval
Rear brake pads	70,000 km	OK Within interval
Timing belt (if fitted)	120,000 km / 72 months	OK Within interval

Estimated from standard manufacturer intervals and an assumed 15,000 km/year average. Refer to the vehicle's owner's manual for exact service intervals.

Parts Availability

Availability Index

Excellent parts availability — wide aftermarket, short delivery times.

- DACIA is a high-volume brand — large aftermarket with widely available parts.
- Vehicle is 15 years old — most parts still readily available through standard channels.

Standard maintenance should be straightforward and affordable.

German Annual Vehicle Tax (KFZ-Steuer)

Not enough engine / emissions data to compute the German annual vehicle tax. —

Low-Emission Zone Eligibility

Zone Access

Unknown — check the registration document for the Euro class

Manufacturer Warranty Status

Factory Warranty

Unknown

Make or year not available — cannot estimate warranty status.

Theft Risk Index

Theft Risk

Average / low

No significant theft-related insurance premium impact.

Accident & Damage History

We check whether the vehicle has been involved in any reported traffic accidents. When buying a damaged vehicle, extra caution is warranted — or consider walking away from the deal.

European Database Coverage

85%+

Reported Accident / Total-Loss Records

No reported accident or total-loss record found

Countries checked

DE	✓ Checked
LT	✓ Checked
FI	✓ Checked
HR	✓ Checked
SE	✓ Checked
FR	✓ Checked
SK	✓ Checked
PL	✓ Checked
IT	✓ Checked
EU	✓ Checked

*Coverage varies by country. Not all national insurance or police databases are publicly accessible. Absence of a record does not guarantee the vehicle has never been in an accident — always request a service history from the seller before purchase.

Absence of a record is not a guarantee the vehicle was never damaged. A physical pre-purchase inspection remains recommended.

Natural Disaster Exposure

Result

No records found

This section flags vehicles that have been in regions affected by floods, hail storms, wildfires, or hurricanes during their lifetime.

3 data sources checked. —

About the Manufacturer

FOUNDED 1966	HEADQUARTERS Mioveni	COUNTRY Romania
PARENT COMPANY Renault		

Complete Vehicle Data (11 fields)

FIELD	VALUE
Emissions Gap (%)	16.6
Fuel (Primary)	Diesel
Fuel Consumption (L/100km)	4
Fuel Gap (%)	18.9
Official CO ₂ (g/km)	135.2
Official Fuel (L/100km)	5.02
Real-World CO ₂ (g/km)	157.6
Real-World Fuel (L/100km)	5.97
Region	Europe
Transmission Style	Manual
Vehicle Type	passenger