

Silverstate Wire Rope and Rigging

Customer Information

24-Hour Emergency Service
Sales - Service - Repair
Electrical - Mechanical - Pneumatic
Cal-OSHA Accredited

Customer Name: LVVWD
Customer Contact: DAVID BOURN
Job Number: 6567
Email Address: DAVID.BOURN@LVVWD.COM
Customer Address: 1001 S VALLEY VIEW BLVD, LAS VEGAS, NV 89107

Crane Description: BRIDGE

Overall Condition Rating: TEMP
Crane Mfg: HUH
Hoist Mfg: FFD
Hoist Model: 3-110101-25B

Cap: 2 TON
Crane Srl: PP00657
Hoist Srl: 60-56120
Equip #: TTH-013

Operational Check: Hoist Main

Work Performed and Discrepancies Noted:

Just a test 2

Rope Length: Chain Length: Mfg and Mdl or Remote or Pendant:

Material Used:

Material Ordered:

Crane Condition Rating:

1=Great
2=Good Minor Problems (scheduled repair)
3=Maintenance Problems(Immediate Repair)
4=Safety Concern(Immediate Repair)

Technician:

Date: 07/05/2012

Customer:LVVWD

Date: 07/05/2012

