Silverstate Wire Rope and Rigging

**Customer Information** 

24-Hour Emergency Service Sales - Service - Repair

Electrical - Mechanical - Pneumatic

Cal-OSHA Accredited

**Customer Name: JOHNNY Customer Contact: LVWWD** Job Number: 1234

Email Address: ADEIJI@YAHOO.COM

Customer Address: 8605 BLOWING PINES DR, LAS VEGAS, NV, 89143

Crane Description: BRIDGE

Overall Condition Rating: TEMP Crane Mfg: HUNJ Hoist Mfg: **FETY** Hoist Model: **TTTG** 

**JHHB** Cap: Crane Srl: **KNNJ** Hoist Srl: HOME-4 Equip #: TH-001

Operational Check: Hoist Main

Work Performed and Discrepancies Noted:

Test

Mfg and Mdl or Remote or Pendant: Rope Length: Chain Length:

Material Used:

Material Ordered:

Crane Condition Rating:

1=Great

2=Good Minor Problems (scheduled repair)

3=Maintenance Problems(Immediate Repair)

4=Safety Concern(Immediate Repair)

Technician:JOHNNY Date: 07/11/2012

**Customer:JOHNNY** Date: 07/11/2012