

## Silverstate Wire Rope and Rigging

## Customer Information

24-Hour Emergency Service  
Sales - Service - Repair  
Electrical - Mechanical - Pneumatic  
Cal-OSHA Accredited

Customer Name: LVVWD  
Customer Contact: DAVID BOURN  
Job Number: 25654  
Email Address: DAVID.BOURN@LVVWD.COM  
Customer Address: 1001 S VALLEY VIEW BLVD, LAS VEGAS, NV 89107

Crane Description: BRIDGE

Overall Condition Rating: TEMP  
Crane Mfg: JIJ  
Hoist Mfg: HUHG  
Hoist Model: F2A

Cap: 3 TON  
Crane Srl: FRONTIER 3708  
Hoist Srl: 14043WX1  
Equip #: 232

Operational Check: Trolley

Work Performed and Discrepancies Noted:

Hrhfjjcjf

Rope Length: MDJFJF Chain Length: FDJFHFH Mfg and Mdl or Remote or Pendant: DNDJDJF

Material Used: Ncndhcjd

Material Ordered: Cndndnnc

Crane Condition Rating:  
1=Great  
2=Good Minor Problems (scheduled repair)  
3=Maintenance Problems(Immediate Repair)  
4=Safety Concern(Immediate Repair)

Technician:JOHNNY  
Date: 06/11/2012

Customer:LVVWD  
Date: 06/11/2012

