Silverstate Wire Rope and Rigging

24-Hour Emergency Service Sales - Service - Repair

Electrical - Mechanical - Pneumatic

Cal-OSHA Accredited

Job Number:

Customer Name:

Customer Contact:

Customer Information

JOHNNY LVWWD

12345

Email Address:

ADEIJI@YAHOO.COM

Customer Address: 8605 BLOWING PINES DR, LAS VEGAS, NV, 89143

Crane Description: BRIDGE

Overall Condition Rating: TEMP Crane Mfg: HUNJ Hoist Mfg: **FETY**

JHHB Cap: Crane Srl: **KNNJ** Hoist Srl: TEST-4 Equip #: TH-001

Operational Check: Runway

Work Performed and Discrepancies Noted:

TTTG

Test 4

Hoist Model:

Mfg and Mdl or Remote or Pendant: Rope Length: Chain Length:

Material Used:

Material Ordered:

Crane Condition Rating:

1=Great

2=Good Minor Problems (scheduled repair)

3=Maintenance Problems(Immediate Repair)

4=Safety Concern(Immediate Repair)

Technician:JOHNNY

Date: 07/10/2012

Customer:JOHNNY Date: 07/10/2012