

SONAR-X

Physics-Aware Explainable Marine Debris Intelligence System

SURVEY INTELLIGENCE REPORT

Survey Information

Survey ID	SX-SRV-20260924-003
Survey Name	SONAR Survey — sonar test image
Survey Date	2026-09-24
Area	Not specified
Operator	Not specified
Data Source	SURVEY
Status	COMPLETED
Generated	2026-09-24 17:04 UTC
Software	SONAR-X 0.1.0-prototype

Sonar Metadata

Altitude above seabed	Not available
Range scale	Not available
Channel layout	BOTH
Already gain corrected	No
Already slant-range corrected	No

Detection Summary

Total detections	0
Marine Debris	0
Natural Formation	0
Sonar Artifact	0
Unknown Anomaly	0
Hazard — High Caution	0
Hazard — Caution	0

Detection List

No detections found for this survey.

Limitations and Disclaimers

- This is a prototype system. All detections require human verification before any action.
- Confidence and evidence scores are prototype heuristic values, NOT validated probabilities.
- Side-scan sonar does not directly provide water temperature or depth.
- Conventional side-scan sonar is not a direct bathymetric sensor.
- Slant-range correction geometry is approximate where metadata was unavailable.
- Geolocation is approximate. GPS coordinates require field calibration.
- A missing detection does NOT prove debris was removed or moved.
- Absence of a hazard flag does NOT mean an object is safe.

AI-generated observations require verification by qualified human experts.