

Railway Inspection Summary

Session ID: 20260314_071909
Generated: 2026-03-14 07:19:20

Key Session Metrics

Metric	Value
Total Defects Detected	0
Minimum Clearance Found	0.191 m
Maximum Peak Acceleration	N/A
UML (Urgent) Clearances	0
PML (Planned) Clearances	153
CBML (Safe) Clearances	0

Top 10 Defect Detections

No defects detected or log file missing.

Structure Clearance Profile

Not enough chainage variation to plot clearance.

Vehicle Acceleration Profile

No acceleration data available for chart.