



Job Name: Test - Home  
Task: **Flex Uploader**  
Job Address: 15226 Liberty Ridge Ln, Huntersville, NC 28078, USA

Report Date: 08/15/2025

IMAGING

# INSPECTION REPORT

15226 LIBERTY RIDGE LANE  
HUNTERSVILLE, NC 28078

08/15/2025





# Inspection Report



## Property Information

Job Name  
**Test - Home**

Job Type  
**Residential**

Phone Number  
**N/A**

Email Address  
**N/A**

## About This Report

Report Created  
**08/15/2025**

Assets  
**20**

Added Photos  
**0**

Annotations  
**0**

Images With Confirmed Damage  
**20**

## General Information

Completed by  
**Aaron Dworsky**



Completed on  
**08/14/2025**

Inspect List Type  
**N/A**



AT013

CLOSE UP EXAMPLES




NOTE



CONFIRMED DAMAGE

Hail Hit

3




AT023

CLOSE UP EXAMPLES



NOTE



CONFIRMED DAMAGE

Hail Hit

6





Job Name: Test - Home  
Task: **Flex Uploader**  
Job Address: 15226 Liberty Ridge Ln, Huntersville, NC 28078, USA

Report Date: 08/15/2025



AT017

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit




3

NOTE



AT005

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit


9

NOTE




Job Name: Test - Home  
Task: **Flex Uploader**  
Job Address: 15226 Liberty Ridge Ln, Huntersville, NC 28078, USA

Report Date: 08/15/2025



AT001

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit


3

NOTE



AT015

CLOSE UP EXAMPLES




CONFIRMED DAMAGE

Hail Hit

7


NOTE



AT021


CLOSE UP EXAMPLES

1 - Hail Hit



An example has not been added.

B




An example has not been added.

D



An example has not been added.

NOTE



CONFIRMED DAMAGE

Hail Hit

1



AT020

CLOSE UP EXAMPLES

1 - Hail Hit



2 - Hail Hit

B




An example has not been added.

An example has not been added.

C

D

NOTE



CONFIRMED DAMAGE

Hail Hit

2



Job Name: Test - Home  
Task: **Flex Uploader**  
Job Address: 15226 Liberty Ridge Ln, Huntersville, NC 28078, USA

Report Date: 08/15/2025



AT006


CLOSE UP EXAMPLES

1 - Hail Hit



An example has not been added.

B




An example has not been added.

D

An example has not been added.

NOTE



CONFIRMED DAMAGE

Hail Hit

1



AT016

CLOSE UP EXAMPLES


1 - Hail Hit




2 - Hail Hit



3 - Hail Hit



4 - Hail Hit



NOTE



CONFIRMED DAMAGE

Hail Hit


8



## AT008

Edited by Aaron Dworsky on  
08/15/2025 12:10 PM EDT

### CLOSE UP EXAMPLES




### NOTE



### CONFIRMED DAMAGE


Hail Hit

4



## AT019

### CLOSE UP EXAMPLES



### NOTE



### CONFIRMED DAMAGE

Hail Hit

3





Job Name: Test - Home  
Task: **Flex Uploader**  
Job Address: 15226 Liberty Ridge Ln, Huntersville, NC 28078, USA

Report Date: 08/15/2025



AT014

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit



6

NOTE



AT004

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit


13

NOTE





Job Name: Test - Home  
Task: **Flex Uploader**  
Job Address: 15226 Liberty Ridge Ln, Huntersville, NC 28078, USA

Report Date: 08/15/2025



AT009

CLOSE UP EXAMPLES




CONFIRMED DAMAGE

Hail Hit

13

NOTE



AT002

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit


5

NOTE



Job Name: Test - Home  
Task: **Flex Uploader**  
Job Address: 15226 Liberty Ridge Ln, Huntersville, NC 28078, USA

Report Date: 08/15/2025




AT011

CLOSE UP EXAMPLES

1 - Hail Hit



An example has not been added.



An example has not been added.



An example has not been added.




NOTE



CONFIRMED DAMAGE

Hail Hit

1




AT007

CLOSE UP EXAMPLES

1 - Hail Hit



2 - Hail Hit



3 - Hail Hit



4 - Hail Hit




NOTE



CONFIRMED DAMAGE



Hail Hit

13



AT012

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit


4

NOTE



AT018

CLOSE UP EXAMPLES



CONFIRMED DAMAGE

Hail Hit

2

NOTE